

MEMORANDUM

Date: January 07, 2013
To: Water Right File 81-11981
From: csaxton 
Re: POU - Delivery System

Field examiner confirmed that despite that the aerial photography does not look irrigated, there is a buried underground system with risers that can supply water to the entire 5.4 acres recommended as irrigated POU. The limited capacity of 0.04 cfs for the system is probably partially to blame for it not looking irrigated. Water has to be spread thin or rotated to irrigate all the property but the pipe delivery system is in place to do that.