

65-23504 FIELD EXAM REPORT

This permit was split from 65-13050 with new split system : original # with reduced use & new # for split portion.

See 65-13050 exam report.

Everything is the same for 65-23504 except:

- Permit owner/address
- POU overlap: 65-23496, same uses & same home (same well as 65-23497 in 65-13050 overlap)
- Condition X60, POU located at #2 Snow Springs Drive.

ADD DATABASE COMMENT

See 65-13050 for field exam report, same system, different home.

SL 9/14/12