

IDAHO DEPARTMENT OF WATER RESOURCES

Water Right Report 29-14049

WATER RIGHT NUMBER: 29-14049

<u>Owner Type</u>	<u>Name and Address</u>
Current Owner	MAYNARD LAND & LIVESTOCK LLC C/O TAM MAYNARD 18255 S MARSH VALLEY RD DOWNEY, ID 83234

Priority Date: 06/15/1973

Basis: Decreed

Status: Active

<u>Source</u>	<u>Tributary</u>
GROUND WATER	

<u>Beneficial Use</u>	<u>From</u> <u>To</u>	<u>Diversion Rate</u>	<u>Annual Volume</u>
IRRIGATION	03/15 to 11/15	0.050 CFS	19.30 AF
	<u>Total Diversion:</u>	0.050 CFS	19.30 AF

Location of Point(s) of Diversion

GROUND WATER	SE1/4SE1/4	Sec. 35, Twp 10S, Rge 36E, B.M.
BANNOCK County		
GROUND WATER	SE1/4SE1/4	Sec. 35, Twp 10S, Rge 36E, B.M.
BANNOCK County		

Place of Use

IRRIGATION

Twp	Rge	Sec	NE				NW				SW				SE				Totals
			NE	NW	SW	SE	NE	NW	SW	SE	NE	NW	SW	SE	NE	NW	SW	SE	
10S	36E	35													6.6	1.4			8.0
11S	36E	2														13.4			13.4

Total Acres: 21.4

Conditions of Approval:

1. T19 Pursuant to Section 42-1412(6), Idaho Code, this water right is subject to such general provisions necessary for the definition of the rights or for the efficient administration of water rights as may be determined by the Snake River Basin Adjudication court at a point in time no later than the entry of the final unified decree.
2. E55 Right Nos. 29-14045 and 29-14049 are limited to the irrigation of a combined total of 15.8 acres in a single irrigation season.
3. X35 Rights 29-14045, 29-14047, and 29-14049 when combined shall not exceed the irrigation of 21.4 acres.
4. K06 This right is limited to the irrigation of 6.9 acres within the place of use described above in a single irrigation season.
5. C05 Right includes accomplished change in place of use pursuant to Section 42-1425, Idaho Code.
6. C03 Right includes accomplished change in point of diversion pursuant to Section 42-1425, Idaho Code.

IDAHO DEPARTMENT OF WATER RESOURCES
Water Right Report 29-14049

Remarks:

Comments:

1. mholliday 11/21/2012 split right
Comment: Parent right 29-13883 split by ownership change into 29-14049 and 29-14050. Since the POU shape for 29-13883 did not appear to accurately reflect the tabular data, probably due to recent drift in the GCDB, the POU shapes for the split portions located in the NWSE of section 2 were moved slightly northward to better correspond to the aerial photography.
2. mholliday 11/21/2012 4:46:19 PM POD
Comment: Updated Shape
3. mholliday 11/21/2012 4:46:49 PM POD
Comment: Updated Shape
4. mholliday 11/21/2012 4:49:07 PM POU
Comment: Updated Shape