

Saxton, Craig

From: Raymond, Kade
Sent: Thursday, September 27, 2012 2:56 PM
To: Saxton, Craig
Subject: Banks Measuring Device
Attachments: pics 041.jpg; pics 042.jpg

Craig,

Me and Blake went out today and checked to make sure that Banks have their measuring device in. I have attached a few pictures that show the measuring device that was recently installed. It appears that the channel could supply 2.9 cfs when it is cleaned out; however we did not observe 2.9cfs moving through there today. David said that in the spring it flows quite a bit more and when cleaned out there would definitely be more water there. I hope this is what you needed. Please let me know if you have any further questions.

Kade Raymond, EIT
IDWR Dam Safety Program
900 North Skyline Drive, Suite A
Idaho Falls, ID 83402-1718
(208) 525-7161 (Office)
(208) 525-7177 (Fax)

648-7856
David Banks
cell
208-7447

29-7391: Verification of Installed Measuring Device



Collected by Kade Raymond and Blake Jordan, Eastern Region on 9-27-12