

MEMO

TO: Files 95-9395 and 95-9484

ATTENTION: Field Examiner

FROM: Cherie Palmer

DATE: April 17, 2012

RE: Measurement Required for 95-9395 when 95-9484 is Conducted

In 2010 I was tasked with reinstating permit 95-9395. In the process of reinstating the permit, it was thought that enough information was available to license 95-9395. I was able to compile all the information important for a field examination but I was not able to make sense of a diversion rate given the system.

I have partially completed a field examination report and have made it part of file 95-9395 but, I could not get Shelley Keen to buy off on the contemplated diversion rate. Thus, no license can be issued without more information. I have solicited KMC on a few occasions and have been unsuccessful.

In 2010, proof was filed for 95-9484 and will need a field examination. Craig Saxton, my supervisor, thought it would be appropriate to complete a measurement on the system for 95-9395 when the field examination for 95-9484 is being conducted and forward the information to the file for final licensure. Thank you to the field examiner and let me or Craig Saxton know if you have any questions.