

Memorandum

Date: December 13, 2011

To: File 36-8761

From: Craig L. Saxton

Re: POU correction for range description in license 36-8761

After reviewing the file, I agree with the permit holder and Benny Walker. The POU description identifying the POU as being in Range 11 East, is in error. The application, permit and field examination all report the POU as being in Range 15 East. It seems clear that the developed POU for 36-8761 falls in Range 15 East rather than Range 11 East.

This appears to be a clerical error that can be fixed with an order.