

Hemenway, Sandy

From: Craig Collins [craigcollins@jugmountainranch.com]
Sent: Tuesday, September 20, 2011 9:31 AM
To: Hemenway, Sandy
Subject: weir pictures

Sandy - I am forwarding pictures taken of the weirs. The upstream weir is in the concrete culvert. The downstream weir is in the galvanized culvert. Hope these are helpful. If you have any questions please contact me. (208)-634-6982

Thank You,

Craig Collins



15-22912 Timber Arch Culvert abutment. Near Millersburg, Ohio



1.5-22912 Twa Mtn Ranch

4/20/2011

11 streams Lixir (1)

Annie Collins

