

Van Bussum, Monica

From: Yenter, Cindy
Sent: Wednesday, May 04, 2011 3:24 PM
To: Van Bussum, Monica
Subject: Stevenson

Stevenson Bros does not appear to have acres under CREP. Some pivot corners under 36-2727 and 36-7495 were included in the 2005-2007 mitigation plan. Other acres were not eligible. The acres were entered under the name of Kerbs; they were probably the operator. See the spreadsheet below.

Scott Stevenson had no acres under 36-7651 accepted to mitigation, but currently has some acres in CREP. I think he intended to enter some acres in mitigation, but (and this is a classic screw up which I did not go out of my way to fix) acres in the incorrect QQ were identified, in this case, acres under 36-7652 which belongs to Delis Farms just to the east.

Regarding Scott Stevenson, you will see that he had some acres excluded from CREP, primarily rocky outcroppings and this was because NRCS did not have them classified as irrigable, even though he had a valid water right on them. So we had recommended that these acres be placed in the water bank to protect them, as they would technically forfeit during the term of CREP. They are NOT rentable acres. Jeff P. has signed off on this, and I can't recall if you were around for these discussions. please see him if you have questions.

You can find the CREP shape at X:\spatial\irrigation\CREP.



Stevenson.xlsx

Magic Valley Water-Bank / GW Curtailment Acres for 2006

Magic Valley Water-Bank/ GW Curtailment Acres for 2005																			
Idle Acres																			
Waterbank History										IDWR	SUBMITTED	APPROVED	ENROLLED	IRR 05	ELIGIBLE 06	IDWR	2005	Eligibility	Comments
Owner	Township	Rtng	Sec	QQ	Q	Assoc	WRN	U		2004	2005	2006	05 PLAN	05 PLAN	04 PLAN		Code		
100030 Kerbs and f 06S	22E	36 SE	NE			36-2727, 36	36-2727, 36	7	7	7	7	9.2	yes	yes	yes		4		listed under stevenson and sons on MVG 05 Redmacres-dwr reww FINAL
100030 Kerbs and f 06S	22E	36 SW	NE			36-2727, 36	36-2727, 36	7	7	7	7	6.4	yes	yes	yes	no	5		listed under stevenson and sons on MVG 05 Redmacres-dwr reww FINAL
100031 Kerbs and f 06S	22E	36 NW	NW			36-2727, 36	36-2727, 36	7	7	7	7	6.9	yes	yes	yes	no	4		listed under stevenson and sons on MVG 05 Redmacres-dwr reww FINAL
100031 Kerbs and f 06S	22E	36 SE	NW			36-2727, 36	36-2727, 36	7	7	7	7	7.3	yes	yes	yes	no	4		listed under stevenson and sons on MVG 05 Redmacres-dwr reww FINAL
100030 Kerbs and f 06S	22E	36 NE	SE			36-2727, 36	36-2727, 36	7	7	7	7	9.8	yes	yes	yes	no	4		listed under stevenson and sons on MVG 05 Redmacres-dwr reww FINAL
100030 Kerbs and f 06S	22E	36 NW	SE			36-2727, 36	36-2727, 36	7	7	7	7	8	yes	yes	yes	no	4		listed under stevenson and sons on MVG 05 Redmacres-dwr reww FINAL
100030 Kerbs and f 06S	22E	36 SW	SE			36-2727, 36	36-2727, 36	7	7	7	7	9.1	yes	yes	yes	no	4		listed under stevenson and sons on MVG 05 Redmacres-dwr reww FINAL
100031 Kerbs and f 06S	22E	36 NE	SW			36-2727, 36	36-2727, 36	7	7	7	7	6.1	yes	yes	yes	no	4		listed under stevenson and sons on MVG 05 Redmacres-dwr reww FINAL
100031 Kerbs and f 06S	22E	36 SE	SW			36-2727, 36	36-2727, 36	6	6	6	7	8	yes	yes	yes	no	4		listed under stevenson and sons on MVG 05 Redmacres-dwr reww FINAL
100030 Kerbs and f 06S	22E	36 NW	NE			36-2727, 36	36-2727, 36						no	na	yes	no		Not reviewe	not submitted in 05 plan, not irrigated in 05, ineligible
100030 Kerbs and f 06S	22E	36 NE	NE			36-2727, 36	36-2727, 36	7	7	7	7		no	na	yes	no		Not reviewe	not submitted in 05 plan, not irrigated in 05, ineligible
100031 Kerbs and f 06S	22E	36 NW	NW			36-2727, 36	36-2727, 36	7	7	7	7		no	na	yes	no		Not reviewe	not submitted in 05 plan, not irrigated in 05, ineligible
100031 Kerbs and f 06S	22E	36 SW	NW			36-2727, 36	36-2727, 36	7	7	7	7		no	na	yes	no		Not reviewe	not submitted in 05 plan, not irrigated in 05, ineligible
100031 Kerbs and f 06S	22E	36 NW	SW			36-2727, 36	36-2727, 36	7	7	7	7		no	na	yes	no		Not reviewe	not submitted in 05 plan, not irrigated in 05, ineligible
100031 Kerbs and f 06S	22E	36 SW	SW			36-2727, 36	36-2727, 36	7	7	7	7		no	na	yes	no		Not reviewe	not submitted in 05 plan, not irrigated in 05, ineligible
100695, 11 Delis Farm: 08S	22E	11 NW	NE			36-7311, 36	36-7311, 36				7.3	5.8	N	N	N	Y	5.8		2006 is first
100695, 11 Delis Farm: 08S	22E	11 NE	NE			36-7311, 36	36-7311, 36				7.8	5.4	N	N	N	Y	5.4		2006 is first
100695, 11 Delis Farm: 08S	22E	11 SE	NE			36-7311, 36	36-7311, 36				7.4	7.4	N	N	N	Y	7.4		2008 is first
100695, 11 Delis Farm: 08S	22E	11 SW	NE			36-7311, 36	36-7311, 36				7.5	6.4	N	N	N	Y	6.4		2008 is first
100695, 11 Delis Farm: 08S	22E	11 NE	SE			36-7311, 36	36-7311, 36				7.3	5	N	N	N	Y	5		2006 is first
100695, 11 Delis Farm: 08S	22E	11 NW	SE			36-7311, 36	36-7311, 36				7.4	5.4	N	N	N	Y	5.4		2006 is first
100695, 11 Delis Farm: 08S	22E	11 SE	SE			36-7311, 36	36-7311, 36				5.4	8.4	N	N	N	Y	8.4		2006 is first
100695, 11 Delis Farm: 08S	22E	11 SW	SE			36-7311, 36	36-7311, 36				6.8	7	N	N	N	Y	7		2006 is first
100691, Stevenson, 08S	22E	11 NE	NE			36-7651, 36	36-7651, 36	7	7	7	7	6	N	N	Y	Y	0		Not reviewe
100691, Stevenson, 08S	22E	11 SE	NE			36-7651, 36	36-7651, 36	7	7	7	7	8	N	N	Y	Y	0		Not reviewe
100691, Stevenson, 08S	22E	11 SW	NE			36-7651, 36	36-7651, 36	7	7	7	7	5	N	N	Y	Y	0		Not reviewe
100691, Stevenson, 08S	22E	11 NE	SE			36-7651, 36	36-7651, 36	7	7	7	7	4	N	N	Y	Y	0		Not reviewe
100691, Stevenson, 08S	22E	11 SW	SE			36-7651, 36	36-7651, 36	7.5	7.5	7.5	7	7	N	N	Y	Y	0		Not reviewe
100691, Stevenson, 08S	22E	11 NW	SE			36-7651, 36	36-7651, 36	8	8	8	5	N	N	N	Y	Y	0		Not reviewe
100691, Stevenson, 08S	22E	11 SE	SE			36-7651, 36	36-7651, 36	10	10	10	8	N	N	N	Y	Y	0		Not reviewe