

Mills, William

From: Darin Harper [dharper@atcnet.net]
Sent: Thursday, February 17, 2011 7:31 AM
To: Mills, William
Subject: Re: Change of Point of Diversion

2/17/2011

Bill,

I'm a little surprised that the point of diversion is not correct, the well is east of the pivot centers. So I would assume it would be in the NWSESE 1/4 section. I could see the POD being in the other section if the pivot centers are not centered in the field, which is the case. So if you have the actual coordinates and it truly is in the NESWSE 1/4 section, then I acknowledge and agree to the correction on the location of the POD. Thanks for your help.

Darin G. Harper

From: Mills, William
Sent: Wednesday, February 16, 2011 1:42 PM
To: dharper@atcnet.net
Subject: FW: Change of Point of Diversion

From: Mills, William
Sent: Wednesday, February 16, 2011 11:58 AM
To: 'garyb@atc.net'
Subject: FW: Change of Point of Diversion

From: Mills, William
Sent: Monday, February 14, 2011 10:47 AM
To: 'garyb@atc.net'
Subject: Change of Point of Diversion

02/14/2011

Mr. Harper,

As per our telephone conversation this morning, our analysis using our most current data in our Geographic Coordinate Data Base (GCDB) indicates the actual point of diversion for the water rights involved in this transfer is actually located in the NESWSE ¼ of Sec. 31 Twp 11S Rge 27E and not in the NWSESE ¼ of the same section. By responding to this email with your approval we will make the correction in our database and continue processing transfer #77029.

Thank you for your time,

Bill Mills

Water Resource Agent