

Robertson, Jean

From: Robertson, Jean
Sent: Monday, September 27, 2010 2:54 PM
To: 'Ann Pool'
Subject: RE: RJ LLC
Attachments: img-927143811.pdf

That point right in the middle is where our computer system puts something when it doesn't really know where the well is. If you notice in right 36-2449, the first condition states that right no. 36-7835 is also diverted through the point of diversion in T06S, R23 E, Sec. 31 NWSENW, but it doesn't mention the well in the SWSW. To me, that means that other well must be the domestic well. Also, looking at the claim file, the map in there showed the irrigation well up in the NWSENW and pointed to domestic use in the other location. (see the attached map.) We need an actual location of the well in the SWSW on a map and clarification from Mr. Young as to whether that well is tied into the irrigation system or is a separate system. Jeanie

From: Ann Pool [mailto:ann.pool@brockwayeng.com]
Sent: Monday, September 27, 2010 2:13 PM
To: Robertson, Jean
Subject: RJ LLC

On the map, if you look closely at the #52 in the section missing the well icon, you can just see it in there! It's a brighter red!

Amy is going to move the #52 so the well shows clearer but it will take several days as she's on a huge project right now.

Thank you for the time and personal visit...

ann

Ann Pool
Hydrologic Technician
Brockway Engineering PLLC
2016 North Washington Street, Suite 4
Twin Falls, ID 83301
Off 208-736-8543
Fax 208-736-8506
ann.pool@brockwayeng.com