

Keen, Shelley

TO FILE 37-8613A

From: Zach Latham [zach.latham@brockwayeng.com]
Sent: Tuesday, June 29, 2010 2:01 PM
To: Keen, Shelley; Charles E. Brockway
Subject: RE: Locations of Valley Club wells

Shelley-

Chuck Sr. had me take a look at the location of the Valley Club's wells with regards to the permits listed in your email below. We concur that the locations for the two wells that you have listed below are correct. One well is in the NESENW, Sec. 20, T3N, R18E, and the other well is in the NWSWNE, Sec. 20, T3N, R18E. Please let me know if you have any additional questions regarding the locations of these two wells, thanks for your time Shelley.

Zach Latham

Hydrologist
Brockway Engineering, P.L.L.C.
2016 Washington Street North, Suite 4
Twin Falls, ID 83301
t. 208-736-8543
c. 208-308-0739
f. 208-736-8506
zach.latham@brockwayeng.com

All information, calculations, maps, drawings, or other documents transmitted via e-mail are preliminary unless explicitly stated in the e-mail text or in the documents themselves.

From: Charles E. Brockway
Sent: Tuesday, June 22, 2010 3:03 PM
To: Zach Latham
Subject: FW: Locations of Valley Club wells

Zach: can you check these two well locations?

From: Keen, Shelley [mailto:Shelley.Keen@idwr.idaho.gov]
Sent: Tuesday, June 22, 2010 3:01 PM
To: Charles E. Brockway
Subject: Locations of Valley Club wells

Dr. Brockway,

As we discussed this afternoon, I've attached a map showing where IDWR's field examiner reported the Valley Club wells to be. The map is from the field report for Permit 37-8810. A duplicate appears in the field report for Permit 37-8613A. The field examiner used GPS to locate the wells. He reported one to be in the NESENW, S20, T3N, R18E, and the other to be in the NWSWNE, S20, T3N, R18E.

I would like to know if the legal descriptions for the points of diversion appear accurate to you based on your work preparing Application for Permit No. 37-22252, which proposes diverting water for irrigation purposes from the same two wells. If they seem accurate to you, IDWR will try to get licenses issued soon for the two permits. If the descriptions appear to be incorrect, IDWR will double-check our information before issuing licenses. If I haven't heard back from you by June 30, 2010, we'll assume you concur with the examiner's initial findings.

Thanks for your help.

Sincerely,

Shelley Keen

Idaho Department of Water Resources

P.O. Box 83720

Boise, ID 83720-0098

(208) 287-4947

shelley.keen@idwr.idaho.gov

<<Locations of Valley Club wells .pdf>>

Keen, Shelley

From: Keen, Shelley
Sent: Tuesday, June 22, 2010 2:45 PM
To: Charles E. Brockway (charles.e.brockway@brockwayeng.com)
Subject: Locations of Valley Club wells

Dr. Brockway,

As we discussed this afternoon, I've attached a map showing where IDWR's field examiner reported the Valley Club wells to be. The map is from the field report for Permit 37-8810. A duplicate appears in the field report for Permit 37-8613A. The field examiner used GPS to locate the wells. He reported one to be in the NESENW, S20, T3N, R18E, and the other to be in the NWSWNE, S20, T3N, R18E.

I would like to know if the legal descriptions for the points of diversion appear accurate to you based on your work preparing Application for Permit No. 37-22252, which proposes diverting water for irrigation purposes from the same two wells. If they seem accurate to you, IDWR will try to get licenses issued soon for the two permits. If the descriptions appear to be incorrect, IDWR will double-check our information before issuing licenses. If I haven't heard back from you by June 30, 2010, we'll assume you concur with the examiner's initial findings.

Thanks for your help.

Sincerely,

Shelley Keen
Idaho Department of Water Resources
P.O. Box 83720
Boise, ID 83720-0098
(208) 287-4947
shelley.keen@idwr.idaho.gov



Locations of Valley
Club wells...