

Merritt, Allen

From: Swank, Lyle
Sent: Friday, March 12, 2010 11:49 AM
To: Merritt, Allen
Cc: Olenichak, Tony
Subject: Transfer76277

Allen,

We talked this morning about Transfer 76277. Tony Olenichak is familiar with the pump also. The previous totalizing flow meter has not been maintained in working order for the past few years.

I would propose the following watermaster comments:

- 1) The pump and pivots should contain a lockable controlling works.
- 2) There should be a totalizing measuring device requirement.

Possibly a 3rd comment is needed to make sure sufficient storage water is owned or rented to cover any excess storage water used. In prior years, Osborn did own storage water to cover the possibility for excess uses. Isaak might not have ownership of storage water in Palisades Reservoir at this time.

I see the proposed transfer does include a statement that delivery is contingent on sufficient water being available at the confluence of Fall Creek.

In past years, we did allow Osborn to turn in pump cards, but data was inconsistent, and not always collected on a timely basis.

PCC data has been collected in the past, and has substituted for flow meter records, but would not be as accurate as a totalizing flow meter.

Lyle Swank,
Watermaster WD1