

Keen, Shelley

From: Ciscell, Michael
Sent: Thursday, August 13, 2009 4:55 PM
To: Keen, Shelley
Cc: Falk, John
Subject: Permit 98-7846, Dam ID00689

Attachments: 98-7846_POD.jpg

Shelly, John,

I am doing some random checking of Dam locations and water rights to see how our correlation went, and ran across the dam and permit above. We have two different locations for what should be the same structure, the dam being the POD for the permit. The permit indicates the legal as 64N01W6SWNW, which is where it is on the quad map submitted by the applicant, and where we digitized it. The GPSed location for the dam in the dam layer, done by DS staff, is located in 64N01W6NESW. Neither location shows a dam or reservoir.

The actual location for both is in 64N01W6SWNE. I found the original GPS data taken by DS staff, and it lands right on the dam. And there's water behind it.

So, our permit needs to have the shape and PLS updated prior to licensing, and the dam needs to have its shape and PLS updated.

The correct shape is on P:\mciscell\98-7846\Dam shapefile. I have already loaded the location into SpatialData.

I have attached a jpg of the Permit POD and actual Dam location.

Michael



98-7846_POD.jpg
(987 KB)

Attachment to Michael Ciscell's 8/13/09 email.

