

Weaver, Mathew

From: Horsmon, Merritt [mhorsmon@idfg.idaho.gov]
Sent: Tuesday, October 21, 2008 12:13 PM
To: Weaver, Mathew
Cc: Crawford, Eric; Lukens, Jim
Subject: RE: Redfish Cabin Water Right Field Exam

Mat,
Sorry this took so long.....I had some trouble finding any information.
The pump is a 1/2 HP Grundfos. The model number is 10s 05 09. I couldn't find and serial number.
You can amend the permit to our regional supervisor Jim Lukens. His contact information is:
99 Highway 93 North
P.O. Box 1336
Salmon, Id 83467
208-756-2271

Thanks

Merritt Horsmon
SCO - Stanley
Home: 208-774-2735
Cell: 208-940-2735

From: Weaver, Mathew [mailto:Mathew.Weaver@idwr.idaho.gov]
Sent: Wed 10/15/2008 12:09 PM
To: Horsmon, Merritt
Subject: Redfish Cabin Water Right Field Exam

Merritt,

Just a reminder, before I can finish issuing the water right for Redfish Cabin I will need information on the pump (make, model, serial number and horse power), horse power is the biggie from that list. Also, b/c the cabin and well are in a different quarter-quarter than was described on the permit I will need to amend the permit to issue the license. This will require a \$25 filing fee and a signature from the applicant. Do you know who at IDFG I should send the amendment documents to? If it is not you I'll need a contact address and phone number.

Thanks, and good luck with the hunting season. Next time I'm in Stanley I might just look you up to do some fishing.

Mat Weaver, PE
Staff Engineer
Idaho Department of Water Resource
(208) 287-4914