

MEMO

TO: 34-2406D and 34-2406H

FROM: CPADILLA

DATE: August 5, 2008

RE: Place of Use Discrepancy

A discrepancy in the place of use was identified during an ownership change for right 34-13908, which is a child of 34-2406D. The following is a brief description of the error and the steps made in correcting the error.

After a thorough review, it was found that transfer #70891 corrected the place of use for 34-2406D because it was recommended in the NWSE of Section 9 when it really belongs in the SWSE of Section 9 and the place of use for 34-2406H was also corrected through this transfer because it was recommended in the SWSE of Section 9 when it really belongs in the NWSE of Section 9. It is possible the two records got transposed during an ownership split that took place prior to the AJ recommendation, ~~was made~~.

cf