

10/17/07

Idaho Department of Water Resources
7600 Mineral Dr., Suite 100
Coeur d'Alene, ID 83815

Re: Well Log Correction

Dear Sir or Madam:

During the compilation of this Application for Permit, it was brought to our attention that the Section, Township, and Range noted on our well drillers report is incorrect. The report indicates that our well location is in T55N, R5W, S33, when in actuality it should read T56N, R5W, S33. We will be in contact with our well driller to inform him of this discrepancy.

Best Regards,

Randy Johnson

Randy Johnson