

Scott Carlisle
(Star Valley Trout Farm)
6/20/2006
Prepared by: C. Bird
Field exam done on 6/13/2006

RECEIVED
JUN 23 2006

Department of Water Resources
Eastern Region



Photo 1376
10:56 am

Photo 1. Looking in a southwesterly direction at the head of Spring Crk where the 4" and 1½" pipe is buried. 4" pipe goes to the hatchery and the 1½-inch pipe goes to the home and lodge. Pipes were installed in 1996. This is also the proposed site to install covered structure for permit 24-10673. GPS
FILENAME: DOMHCH



Photo 1377
11:03 am

Photo 2. Looking south at 10-inch pipe in Spring Crk. This pipe supplies water to 6 concrete ponds. Pipe was installed in 1996 after getting approval from the Forest Service under Special Use Permit FS 2700-4 (7/93) GPS
FILENAME: 10INPL



Photo 1378
11:23 am

Photo 3. Looking east at 3 of the 6 concrete fishponds. Water supplied to the ponds by the 10-inch pipe in Spring Creek. These structures were built about 5 years ago according to Scott Carlisle. The diameter of each structure is about 30 ft X 30 inches deep and all 6 ponds were operating at the time of my visit. Inlet pipe is a 4-inch PVC pipe going into each pond. GPS FILENAME: POU4IN



Photo 1379
11:32 am

Photo 4. Looking in a southwesterly direction at 2-10" pipes that dumps water from the concrete ponds into a sediment pool before going back into Spring Creek. GPS FILENAME: PTOFIJ



Photo 1380
11:33 am

Photo 5. Looking in a northeasterly direction at Spring Creek and the water from the settling pond as it flows back into Spring Creek.



Photo 1381
11:51 am

Photo 6. Looking in a westerly direction into the hatchery at the large raceways. GPS FILENAME: HATCHY



Photo 1382
11:52 am

Photo 7. Looking into one of the large raceways at the hatchery.



Photo 1383
11:58 am

Photo 8. Looking in a southerly direction at the water coming into the small raceways. The supply line is 1-inch PVC pipe that dumps water into the trough then it flows into the small raceways. A 4-inch pipe from Spring Creek supplies the hatchery water.



Photo 1384
11:58 am

Photo 9. Looking at the 2-inch PVC pipe coming into the large raceways in the hatchery.



Photo 1385
12:14 pm

Photo 10. Looking west at the lodge/restaurant. Scott Carlisle is talking with Steve Spencer from the Forest Service. GPS FILENAME: LODGE



Photo 1386
12:22 pm

Photo 11. Looking north at Scott Carlisle's home. GPS FILENAME: HOUSE



Photo 1387
12:23 pm

Photo 12. Looking in a northeasterly direction from Scott's house at earth ponds described under 24-2038.



Photo 1388
12:24 pm

Photo 13. Looking in a northwesterly direction from Scott's house at earth ponds under 24-2038.



Photo 1389
12:24 pm

Photo 14. Looking in a northwesterly direction from the house at the 4 cabins on the hill that overlooks the earth ponds. According to Scott Carlisle there is no water used in the cabins.