

Peppersack, Jeff

From: Wilson, Keith
Sent: Thursday, October 06, 2005 9:56 AM
To: Peppersack, Jeff
Subject: RE: Valley Pork Producers 35-8659

To File
35-8659

Jeff,

Yes, the well appeared to be the same one in the field exam. Using the field exam photos, the relative position of the well to buildings seen in the photo and my on site inspection confirmed that this well was the field exam well. I did not feel that additional photos were needed. The only difference was the vegetation around the well site, and time of year (exam in June, re-exam in October).

Sorry that I did not include this information in my e-mail.

Keith

-----Original Message-----

From: Peppersack, Jeff
Sent: Wednesday, October 05, 2005 4:54 PM
To: Wilson, Keith
Subject: RE: Valley Pork Producers 35-8659

Keith,

Were you able to verify the same well based on the pictures from the field exam?

Jeff

-----Original Message-----

From: Wilson, Keith
Sent: Wednesday, October 05, 2005 3:57 PM
To: Peppersack, Jeff
Subject: Valley Pork Producers 35-8659

Jeff,

I went on site to determine the location of the point of diversion of 35-8659.

Point of Diversion Located in:

SW1/4SE1/4SE1/4 Sec 15, T04N, R37E

DATA Collected:

Trimble- GeoExplorer (SN 00100033FM)(State of ID #196823)

The Point of diversion:

N 43d 40m 11.54s

W 112d 05m 13.57s

See attached ArcView map:

<< File: 3508659_pod.jpg >>

Trimble - GeoExplorer Roving files:

<< File: cor1005a.txt >> << File: R100520A.cor >> << File: DTL1005a.TXT >> << File:

R100520A.ssf >>

Hopefully this will assist you.

Keith C. Wilson
Senior Resource Agent



Sections

GCDB04N37E GCDB

Re-Exam Date 10/05/2005

N 43d 40m 11.5s

W 112d 05m 13.4s

Keith C. Wilson

Senior Resource Agent

35-8659