



BROCKWAY
ENGINEERING
P.L.L.C.

Hydraulics

Hydrology

Water Resources

July 31, 2001

Mr. Jim Stanton
Idaho Department of Water Resources
1341 Fillmore Street, Suite 200
Twin Falls, ID 83301

RECEIVED

AUG 02 2001

**Department of Water Resources
Southern Region**

Re: Picabo Livestock transfer application
Project No. 160-04-2000

Dear Jim:

In our last meeting, you raised several questions about areas of irrigation and/or irrigable areas that were unclear on the 2000 FSA aerial photo. I met with Nick Purdy to discuss each of these, and I am enclosing a revised GIS map showing some minor changes. Also, the enclosed diskette contains the relevant ArcView shape files. If there is any problem pulling this in, please give Mitchell a call.

1. The square area in NESE Section 19 is a pond. It receives some overflow water from the Gillihan Ditch.
2. The small area in NWNW Section 30 is not irrigated – it has been removed from the map.
3. The PPU line in the NWNW Section 29 has been modified slightly to correspond to the field line.
4. The acreage in SWNW Section 35 has been re-calculated to reflect 25.9 acres irrigated.
5. The area in SESW Section 26 is the east end of the future Picabo Hills subdivision. The PPU line was modified to show a row of landscaping and trees along the highway and west of the storage cellars, in addition to some land between the highway and the "O" Drain that is irrigable. This brings the PPU area in this 40 to 8.6 acres.
6. The PPU line in SESW Section 27 has been modified to show only land owned by Picabo Livestock.

CHARLES E.
BROCKWAY,
PH.D., P.E.

CHARLES G.
BROCKWAY,
PH.D., P.E.

2016 NORTH
WASHINGTON
STREET • SUITE 4

TWIN FALLS,
IDAHO 83301

208•736•8543

FAX: 736•8506

7. The area in SESW Section 20 between the railroad grade and Silver Creek has been removed from the PPU.
8. The area next to the creek in SWSE Section 20 is not irrigated.
9. Depressed areas in SESE Section 20 are not irrigated – the PPU line has been changed to reflect this.
10. The PPU line in the north portion of Section 28 and in other areas with depressions and old oxbows around the creek and drains was checked by Mr. Purdy and found to be accurate.
11. The PPU line in the NE Section 27, the SENW Section 27, and the NWSW Section 26 has been changed slightly to better reflect the irrigable areas, according to Mr. Purdy.
12. All wells serving this land are shown on the GIS map.

Regards,



Charles G. Brockway, I.E.

Enc: Revised GIS map
PPU acreage list
Diskette with ArcView shape files

cc: Nick Purdy (w/o diskette)