

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES
BENEFICIAL USE FIELD REPORT

A. GENERAL INFORMATION

Permit No: 97-7397
Exam Date: 07/26/2001

1. Current Owner:
PRIEST LAKE GOLF CLUB INC 4777 W LAKESHORE RD PRIEST LAKE ID 83856
2. Accompanied by: Craig Hill
Phone No: 208-443-2551
Address: Same as above
Relationship to permit Holder: President, Priest Lake Golf Club Inc.

3. SOURCE:
GROUND WATER

Method of Determination: Arcmap and DRG

B. OVERLAP REVIEW

1. Other water rights with the same place of use: YES Overlap

Water Right No.	Source	Purpose of Use	Basis
97-2052	LAMB CREEK	IRRIGATION	LICENSE
97-7142	GROUNDWATER	DOMESTIC	LICENSE
97-7342	LAMB CREEK	IRRIGATION	PERMIT IN PROCESS FOR LICENSING
97-7343	GROUNDWATER	DOMESTIC	PERMIT IN PROCESS FOR LICENSING

Comments: Right 97-2052 is a surface water source irrigation license that irrigates the front nine of the Priest Lake Golf Course, and not a concern for overlap. Right 97-7342 is a surface water source irrigation permit being licensed in conjunction with this right, which irrigates the front nine of the Priest Lake Golf Course, and does not overlap the irrigation area covered under this right. Right 97-9342 is not a concern for overlap.

Right 97-7142 is a groundwater source license that uses water for domestic purposes that overlaps this right. Upon conclusion of a meeting with Mr. Hill, President of the Priest Lake Golf Club Inc., it was determined that the 5 homes covered for domestic purposes under right 97-7142 has not been used by the applicant's system for decades. The homes are being serviced by the well(s) associated with 97-7343 and 97-7397. As such right 97-7142 will be considered forfeiture and not a concern for overlap, but will be added to condition X35 for licensing purposes.

Right 97-7343 is being licensed in conjunction with this right, and uses groundwater for domestic purposes; the overlapping POU covers the parcels with homes and/or stub-ins identified in the service area for the Priest Lake Golf Course. The annual volume for 97-7343 accounts for domestic volume for 137 parcels not including irrigation, the volume associated with the clubhouse, and up to ½ acre irrigation volume associated with 9 homes constructed prior to 3/1/1999. Condition X35 is incorporated in licensing this right, to mitigate overlap concerns between 97-7142, 97-7343, and 97-7397.

2. Other water rights with the same point-of-diversion: NO Overlap

Water Right No.	Source	Purpose of Use	Basis

Comments: _____

C. DIVERSION AND DELIVERY SYSTEM**1. LOCATION OF POINT(S) OF DIVERSION:**

GROUND WATER SW¼ SE¼, Sec. 25, Twp 60N, Rge 05W, B.M. BONNER County

Method of Determination: GPS. POD is a well (D0013090, A0015422) located at -116°55.605, 48°30.997.

PLACE OF USE: MUNICIPAL

Twp	Rng	Sec	NE				NW				SW				SE				Totals
			NE	NW	SW	SE	NE	NW	SW	SE	NE	NW	SW	SE	NE	NW	SW	SE	
60N	05W	24												X					
60N	05W	25		X	X		X			X	X			X	X	X	X	X	
60N	05W	36	X	X															

Method of Determination: Field exam and Arcmap aerial imagery.

3.

Delivery System Diagram Attached (required). Indicate all major components and distances between components.

☒ Indicate weir size/pipe as applicable.

Map Attached Showing Location(s) of point(s) of diversion and place(s) of use (required). Scale must be

☒ 1:24,000 or greater.☒ Aerial Photo Attached (required for irrigation of 10+ acres).☒ Photo of Diversion and System Attached**4.**

Well or Diversion ID No.*	Motor Make	Hp	Motor Serial No.	Pump Make	Pump Serial No. or Discharge Size
D0013090	GRUNDFOS	30			

D. FLOW MEASUREMENTS**1.**

Measurement Equipment	Type	Make	Model No.	Serial No.	Size	Calib. Date
NONE						

2. Measurements: Due to inadequate piping requirements, a flow measurement was not able to be completed.

E. FLOW CALCULATIONS☒ Additional Computation Sheets Attached

Measured Method: Applicants used RC Worst & Co to install the pump in this well; Mr. Scott Jesicks, RC Worst & Co representative, provided pump curve data for the 30 hp pump installed in well D0013090. The flow rate derived = 319 gpm = **0.71 cfs**.

F. VOLUME CALCULATIONS

1. Volume Calculations for irrigation: N/A

$$V_{I.R.} = (\text{Acres Irrigated}) \times (\text{Irrigation Requirement}) = 23.8 \times 3.0 \text{ afa} = 71.4 \text{ af}$$

$$V_{D.R.} = [\text{Diversion Rate (cfs)}] \times (\text{Days in Irrigation season}) \times 1.9835 = 0.71 \text{ cfs} \times 214 \text{ days} \times 1.9835 = 301 \text{ af}$$

$$V = \text{Smaller of } V_{I.R.} \text{ and } V_{D.R.} = 71.4 \text{ af}$$

2. Volume Calculations for Other Uses:

$$\text{Municipal associated irrigation} = 23.8 \text{ acres} \times 3.0 \text{ afa} = 71.4 \text{ af}$$

$$\text{Annual volume for 1 home built in development period} = 0.6 \text{ af}$$

$$\text{Municipal Maximum Diversion Volume} = \mathbf{72.0 \text{ af}}$$

G. NARRATIVE/REMARKS/COMMENTS

Admin note: an initial field exam was performed by department staff on 7/26/2001; due to inadequate information provided in field exam notes, multiple overlapping rights, number of wells in the immediate area, how they interact with this right, and a substantial time gap between the initial exam and licensing, a second field exam was performed on 7/29/2017 in order to finalize this right.

Field exam performed on 6/29/2017 with Craig Hill, President of the Priest Lake Golf Club Inc., showed water being diverted from a groundwater well for domestic purposes. Due to the lapse in time between initial field exam in 2001 and this exam, the well pump had been replaced in year 2014, changing from the original 30hp Grundfos pump originally installed to a 10hp Grundfos pump. Due to the 30hp pump being installed during the permit development period, the flow measurements and diversion rate will be calculated using the 30hp pump that was installed at that time. The applicant's water system includes a second well associated with right 97-7343; the two wells are interconnected in a looped water main line that routes throughout the domestic POU. In the SENE ¼ ¼ of section 25, a single branch water line from the main line runs upgrade to a 125,000 gallon storage tank. The storage tank uses gravity flow to direct water down grade during peak use times to provide added system flow reducing the well pump cycling time. Due to inadequate piping requirements, a flow measurement was not able to be completed. The applicants used RC Worst & Co to install the pump in this well; Mr. Scott Jesicks, RC Worst & Co representative, provided pump curve data for the 30 hp pump that was installed in well D0013090. The flow rate derived = 319 gpm = **0.71 cfs**, which will be carried forward to licensing.

The field exam conducted on 6/29/2017 provided GPS coordinates for the POD, which did not match the previous field exam data collected. The current GPS coordinates are being used to license this right. Initial field exam notes inadequately described the domestic POU and how the wells interacted; follow on field exam and meetings were conducted to capture accurate data for both POD, system interaction, and POU.

During the field exam performed on 6/29/2017, constructed homes and stub-in service connections were validated for the homes not constructed, equaling 137 lots. Additionally, one clubhouse is serviced by the water system. Mr. Hill provided an accurate 2020 Golf Club Estates Water Assn Census Count Excel Doc, which validated the 137 service connections. During a meeting with Mr. Hill on 10/1/2020, the POU was sketched out on field exam maps. The municipal POU was traced out using Arcmap aerial imagery, and includes the 18 hole golf course, 137 parcels, and 1 clubhouse. Multiple water rights are associated with the POU, and accounts for an added well to the system, irrigation occurring under the municipal beneficial use for the back nine of the golf course, and irrigation up to ½ acre for one home constructed within this right's

F. VOLUME CALCULATIONS**1. Volume Calculations for irrigation: N/A**

$$V_{IR} = (\text{Acres Irrigated}) \times (\text{Irrigation Requirement}) = 23.8 \times 3.0 \text{ afa} = 71.4 \text{ af}$$

$$V_{DR} = [\text{Diversion Rate (cfs)}] \times (\text{Days in Irrigation season}) \times 1.9835 = 0.71 \text{ cfs} \times 214 \text{ days} \times 1.9835 = 301 \text{ af}$$

$$V = \text{Smaller of } V_{IR} \text{ and } V_{DR} = 71.4 \text{ af}$$

2. Volume Calculations for Other Uses:

$$\text{Municipal associated irrigation} = 23.8 \text{ acres} \times 3.0 \text{ afa} = 71.4 \text{ af}$$

$$\text{Annual volume for 1 home built in development period} = 0.6 \text{ af}$$

$$\text{Municipal Maximum Diversion Volume} = \mathbf{72.0 \text{ af}}$$

G. NARRATIVE/REMARKS/COMMENTS

Admin note: an initial field exam was performed by department staff on 7/26/2001; due to inadequate information provided in field exam notes, multiple overlapping rights, number of wells in the immediate area, how they interact with this right, and a substantial time gap between the initial exam and licensing, a second field exam was performed on 7/29/2017 in order to finalize this right.

Field exam performed on 6/29/2017 with Craig Hill, President of the Priest Lake Golf Club Inc., showed water being diverted from a groundwater well for domestic purposes. Due to the lapse in time between initial field exam in 2001 and this exam, the well pump had been replaced in year 2014, changing from the original 30hp Grundfos pump originally installed to a 10hp Grundfos pump. Due to the 30hp pump being installed during the permit development period, the flow measurements and diversion rate will be calculated using the 30hp pump that was installed at that time. The applicant's water system includes a second well associated with right 97-7343; the two wells are interconnected in a looped water main line that routes throughout the domestic POU. In the SENE ¼ ¼ of section 25, a single branch water line from the main line runs upgrade to a 125,000 gallon storage tank. The storage tank uses gravity flow to direct water down grade during peak use times to provide added system flow reducing the well pump cycling time. Due to inadequate piping requirements, a flow measurement was not able to be completed. The applicants used RC Worst & Co to install the pump in this well; Mr. Scott Jesicks, RC Worst & Co representative, provided pump curve data for the 30 hp pump that was installed in well D0013090. The flow rate derived = 319 gpm = **0.71 cfs**, which will be carried forward to licensing.

The field exam conducted on 6/29/2017 provided GPS coordinates for the POD, which did not match the previous field exam data collected. The current GPS coordinates are being used to license this right. Initial field exam notes inadequately described the domestic POU and how the wells interacted; follow on field exam and meetings were conducted to capture accurate data for both POD, system interaction, and POU.

During the field exam performed on 6/29/2017, constructed homes and stub-in service connections were validated for the homes not constructed, equaling 137 lots. Additionally, one clubhouse is serviced by the water system. Mr. Hill provided an accurate 2020 Golf Club Estates Water Assn Census Count Excel Doc, which validated the 137 service connections. During a meeting with Mr. Hill on 10/1/2020, the POU was sketched out on field exam maps. The municipal POU was traced out using Arcmap aerial imagery, and includes the 18 hole golf course, 137 parcels, and 1 clubhouse. Multiple water rights are associated with the POU, and accounts for an added well to the system, irrigation occurring under the municipal beneficial use for the back nine of the golf course, and irrigation up to ½ acre for one home constructed within this right's permit development period. Arcmap parcel tax lot data was used to determine the total number of homes constructed between 3/1/1999 and 3/7/2001 (applicant's statement of completion date), equaling 1 home. The annual and maximum diversion volume was calculated as follows:

- 23.8 acres irrigation x 3.0 afa = 71.4 af
- 1 home constructed between 3/1/1999 and 3/7/2001 (statement of completion date) x 0.6 af = 0.6 af
- Total Municipal Volume = 71.4 + 0.6 af = **72.0 af**, which will be carried forward to license.

Condition 046 was removed from the permit during licensing review. Condition 128 was updated to reflect the PWS# for

water system, and the updated service area. Condition 01C was replaced with 01M. Condition X35 was added to describe overlap requirements between rights 97-7142, 97-7343, and 97-7397.

Right 97-2052 is a surface water source irrigation license that irrigates the front nine of the Priest Lake Golf Course, and not a concern for overlap. Right 97-7342 is a surface water source irrigation permit being licensed in conjunction with this right, which irrigates the front nine of the Priest Lake Golf Course, and does not overlap the irrigation area covered under this right. Right 97-9342 is not a concern for overlap.

Right 97-7142 is a groundwater source license that uses water for domestic purposes that overlaps this right. Upon conclusion of a meeting with Mr. Hill, President of the Priest Lake Golf Club Inc., it was determined that the 5 homes covered for domestic purposes under right 97-7142 has not been used by the applicant's system for decades. The homes are being serviced by the well(s) associated with 97-7343 and 97-7397. As such right 97-7142 will be considered forfeiture and not a concern for overlap, but will be added to condition X35 for licensing purposes.

Right 97-7343 is being licensed in conjunction with this right, and uses groundwater for domestic purposes; the overlapping POU covers the parcels with homes and/or stub-ins identified in the service area for the Priest Lake Golf Course. The annual volume for 97-7343 accounts for domestic volume for 137 parcels not including irrigation, the volume associated with the clubhouse, and up to ½ acre irrigation volume associated with 9 homes constructed prior to 3/1/1999. Condition X35 is incorporated in licensing this right, to mitigate overlap concerns between 97-7142, 97-7343, and 97-7397. There are no additional overlap concerns for this right.

Have conditions of permit approval been met? ☒ Yes ☐ No

H. RECOMMENDATIONS

1. Recommended Amounts

<u>Beneficial Use</u>	<u>Period of Use</u>	<u>Rate of Diversion</u>	<u>Annual Volume</u>
MUNICIPAL	01/01 to 12/31	0.71 CFS	72.0 AF
<u>Totals:</u>		0.71 CFS	72.0 AF

2. Recommended Amendments

☐ Change P.D. as reflected above ☐ Add P.D. as reflected above ☒ None
☐ Change P.U. as reflected above ☐ Add P.U. as reflected above ☒ None

I. AUTHENTICATION

Luke Bates - Water Resource Agent

Field Examiner's Name

[Signature]

Date

11/30/2020

Reviewer


Adam Fink

Date

11/30/2020

State of Idaho
Department of Water Resources
Attachment to Field Exam
97-7397

MUNICIPAL system diagram.



● Point of Diversion

Water Service Area Boundary

Townships


PLS Sections

Quarter Quarters




0 0.225 0.45 0.9 Miles



14B63508 300S300-8 60 Hz



WR 97-7397 IRRIGATION ACREAGE



WR 97-7397 (MUNICIPAL) PRIEST LAKE GOLF COURSE BACK 9 IRRIGATION ACREAGE

WR Edit

X

Save Pls As Layer?

Meridian	Twp	Rng	Rng Partial	Sec	QQ	Q	Govt Lot	County	Acres	Tract ID
1	60N	05W	0	24	SE	SW		BONNER	0.6	
1	60N	05W	0	25	NW	NE		BONNER	0.1	
1	60N	05W	0	25	SW	NE		BONNER	2.5	
1	60N	05W	0	25	NE	NW		BONNER	6.4	
1	60N	05W	0	25	SE	NW		BONNER	3.7	
1	60N	05W	0	25	NE	SW		BONNER	6	
1	60N	05W	0	25	SE	SW		BONNER	1.3	
1	60N	05W	0	25	NW	SE		BONNER	3.2	

Total Acres: 23.8

No


Yes

- REFERENCE WR 97-7397 IRRIGATION ACREAGE MAP PRODUCT

GOLF CLUB ESTATES WATER ASSOCIATION CENSUS COUNT as of Sept. 1, 2020						
NAME / MEMBER	ADDITION	BLOCK #	LOT #	built out lots	stub-in lots	STATUS
Kris Pereira, (Sierra Builders) (Ginno Construction)	First	Block 1	Lot 1		1	Vacant
Morse, Jim & Judy	First	Block 1	Lot 10		1	Vacant
Rein, Geraldine	First	Block 1	Lot 11		1	Vacant
Quinto LLC (John Babcock)	First	Block 1	Lot 12		1	Vacant
David A. Mather	First	Block 1	Lot 13		1	Vacant
Pumnea, Dawn L	First	Block 1	Lot 14		1	Vacant
Pumnea, Dawn L	First	Block 1	Lot 15		1	Vacant
Battaglia Trust	First	Block 1	Lot 16		1	Vacant
Battaglia Trust	First	Block 1	Lot 17		1	Vacant
Rehbock, Cindy	First	Block 1	Lot 18	1		Home
Urquhart, Linda Lee & Rein, Geraldine	First	Block 1	Lot 19		1	Vacant
Kris Pereira (Sierra Builders) (Ginno Construction)	First	Block 1	Lot 2		1	Vacant
Crithfield, Gary	First	Block 1	Lot 20		1	Vacant
Stejer, John W	First	Block 1	Lot 21		1	Vacant
Bockmier, Butch & Michelle. Park Place Ltd.	First	Block 1	Lot 22	1		House
Kris Pereira (Sierra Builders) (Ginno Construction)	First	Block 1	Lot 3		1	Vacant
Kris Pereira (Sierra Builders) (Ginno Construction)	First	Block 1	Lot 4		1	Vacant
Belles, Mike & Katie	First	Block 1	Lot 5	1		Condo Unit 13, V.RENTAL
Burness, Doris	First	Block 1	Lot 5	1		Condo Unit 14
Reilly, Aaron and Christie	First	Block 1	Lot 5	1		Condo Unit 15
Amistad LLC, c/o Craig Hill	First	Block 1	Lot 5	1		Condo Unit 16, V. RENTAL
Salesky, Doug & Krista Whelan	First	Block 1	Lot 6		1	Vacant
Hill's Holding LLC	First	Block 1	Lot 7		1	Vacant
Hargrove, James & Eileen (2822 N Willow, Spo. 99206)	First	Block 1	Lot 8		1	Vacant
Nolan, Max	First	Block 1	Lot 9		1	Vacant
	New Const.	Block 1	Unit 1	1		New Condo for sale
Porter, Ryan and Edwin	Original	Block 1	Lot 1		1	Hydrant only
BordenKircher, Karen & Peterson, Jeannie	Original	Block 1	Lot 10		1	Vacant
Porter, Ryan and Edwin	Original	Block 1	Lot 11		1	Vacant
Porter, Ryan and Edwin	Original	Block 1	Lot 12		1	Vacant
Falk, James P	Original	Block 1	Lot 13		1	Vacant
Tamarack Enterprises, Inc. (Jennifer Bedient)	Original	Block 1	Lot 14		1	Vacant
Estey, Peggy	Original	Block 1	Lot 15		1	Vacant
Estey, Peggy	Original	Block 1	Lot 16	1		House
Estey, Rob & Emily	Original	Block 1	Lot 17	1		House
Estey, Rob & Emily	Original	Block 1	Lot 18		1	Vacant
Porter, Ryan and Edwin	Original	Block 1	Lot 2		1	Vacant
Shoquist, Darrell G & Frances	Original	Block 1	Lot 3		1	Vacant
Ellison, Andy	Original	Block 1	Lot 4		1	Garage only
Vanreenen, Timothy & Patty	Original	Block 1	Lot 5		1	Vacant
Hogan, Mike & Lori	Original	Block 1	Lot 6	1		House
Stutz, Bob & Barb	Original	Block 1	Lot 7		1	Vacant
Stutz, Bob & Barb	Original	Block 1	Lot 8	1		Home
BordenKircher, Karen & Peterson, Jeannie	Original	Block 1	Lot 9	1		House
Rustemeyer, William and Kyunga	Original	Block 3	Lot 1	1		Home
Lewis, Scott	Original	Block 3	Lot 2		1	Vacant
Salter Trust, c/o TW & Shirley Salter	Original	Block 3	Lot 3		1	Vacant
Mielke Properties LLC (Harold & Marcia)	Original	Block 3	Lot 4		1	Vacant
Strode Trust (Mercile M. Goes) (Sharon O'Brien)	Original	Block 3	Lot 5		1	Vacant
Priest Lake Golf Club	Original	Block 3	Lot 6		1	Vacant

Moreau, Larry and Vera	Original	Block 4	Lot 3	1		Home	
Horlacher, Dennis & Leslie	Original	Block 4	Lot 4	1		Home	
Horlacher, Dennis & Leslie	Original	Block 4	Lot 5		1	Vacant	
Hills Holding Co. LLC	Original	Block 2	Lot 1	1		House V. RENTAL	
Peringer, Kathleen & David	Original	Block 2	Lot 2		1	Vacant	
Peringer, Kathleen & David	Original	Block 2	Lot 3	1		House	
Kennedy, Rocky & Autumn	Original	Block 2	Lot 4		1	House. Building now	
O'Brien, Dennis	Original	Block 2	Lot 5	1		Home	
Gyllenhammer, Joseph and Tracy	Original	Block 2	Lot 6		1	Vacant	
Pflaumer Family Trust (Thomas & Terrie)	Original	Block 2	Lot 7		1	Vacant	
Rizzuto, Anthony and Marie	Second	Block 1	Lot 1		1	Vacant	
Rizzuto, Anthony and Marie	Second	Block 1	Lot 2		1	Vacant	
Rizzuto, Anthony and Marie	Second	Block 1	Lot 3		1	Vacant	
Rizzuto, Anthony and Marie	Second	Block 1	Lot 4		1	Vacant	
Garabedian, Carl P	Second	Block 10	Lot 1		1	Vacant	
Vixie, Patricia	Second	Block 10	Lot 2	1		House	
Gibson, Michael	Second	Block 10	Lot 3		1	Vacant	
Craigen, Michael & Vicki	Second	Block 11	Lot 1	1		House	
Kerr, Allyn & Deborah	Second	Block 11	Lot 2	1		House	
Mauzy, Michelle	Second	Block 11	Lot 3	1		House	
Harrington, Judy	Second	Block 12	Lot 1	1		Home	
Stam Family LLC Todd Stam Aspen Homes	Second	Block 12	Lot 2		1	Home. New Construction	
Todd & Janet Eppich	Second	Block 12	Lot 3	1		House V. RENTAL	
Stam Family LLC Todd Stam Aspen Homes	Second	Block 12	Lot 4		1	Vacant	
Buttice, Rick & Kris	Second	Block 12	Lot 5	1		House	
Buttice, Rick & Kris	Second	Block 12	Lot 6		1	Vacant	
Buttice, Rick & Kris	Second	Block 12	Lot 7		1	Vacant	
Burness, Richard & Patricia	Second	Block 12	Lot 8	1		Home	
Whisenhunt, Aaron & Kacey	Second	Block 12	Lot 9	1		House. V. RENTAL	
Priest Lake Golf Club	Second	Block 13	Lot 1		1	Vacant	
Priest Lake Golf Club	Second	Block 13	Lot 2		1	Vacant	
Pimentel, Paul A & Jane T	Second	Block 13	Lot 4		1	Vacant	
Searight, Abby and Maggie	Second	Block 13	Lot 5		1	Vacant	
Searight, Abby and Maggie	Second	Block 13	Lot 6		1	Vacant	
Priest Lake Golf Club	Second	Block 13	Lot 7		1	Vacant	
Morse, Donald W & Yvonne E	Second	Block 13	Lot 8		1	Vacant	
Gibson, Jim and Bridgett	Second	Block 13	Lot 9	1		House	
Dege, Steve & Joann	Second	Block 14	Lot 1	1		Home	
Keighley, John & Michelle	Second	Block 14	Lot 2		1	House. Building now	
Stevens, Mike & Jill	Second	Block 14	Lot 3		1	Vacant	
Searight, Abby and Maggie	Second	Block 14	Lot 4	1		House	
Intermountain Leasing LLC Randy and Janet McNeese	Second	Block 14	Lot 5		1	Vacant	

Intermountain Leasing LLC Randy and Janet McNeese	Second	Block 14	Lot 6		1	Vacant	
Brown, David & D'Arcy L	Second	Block 14	Lot 7		1	Vacant	
Thaler, Lisa	Second	Block 14	Lot 8		1	Vacant	
Hubener, Lance & Kathleen	Second	Block 15	Lot 1	1		Home	
Pool, Matt & Shannon	Second	Block 15	Lot 2		1	Vacant	
Blew, Kolby and Julia	Second	Block 15	Lot 3		1	Vacant	
Valenti, David and Julia	Second	Block 15	Lot 4		1	Vacant	
Wil-Hunt LLC	Second	Block 15	Lot 5		1	Vacant	
Russell, Lindy and Lynn	Second	Block 2	Lot 1	1		Home	
Wane, Dave & Carrie	Second	Block 2	Lot 2	1		House	
Mauzy, Michelle	Second	Block 2	Lot 3	1		House. V. RENTAL	
Hill's Holding Co. LLC	Second	Block 3	Lot 1		1	Vacant	
Priest Lake Mt. Resort HOA (Sue Beard & Marilyn Hann)	Second	Block 3	Lot 2	1		House. V. RENTAL	
Martignetti, Suzan	Second	Block 3	Lot 3	1		House	
Moore, Bernice	Second	Block 4	Lot 1		1	Vacant	
Tatham, John & Patricia	Second	Block 5	Lot 1		1	Vacant	
B. and K. Struzenberg / Hills Resort LLC (a Colorado LLC)	Second	Block 5	Lot 2		1	Vacant	
BFI, Inc (Brad Johnson, BFI, Inc. 185 Industrial Park	Second	Block 5	Lot 3		1	Vacant	
BFI, Inc PO Box 549, Ponderay, Id. 83852)	Second	Block 5	Lot 4		1	Vacant	
Keller, Craig	Second	Block 6	Lot 1	1		House	
Wolcott, Linda	Second	Block 6	Lot 2	1		Home	
Patneade, Mark & Ann (anniepatneade@gmail.com)	Second	Block 7	Lot 1	1		Home	
Urquhart, Linda L	Second	Block 7	Lot 2		1	Vacant	
Dieter, Matt & Lisa	Second	Block 7	Lot 3		1	Vacant	
Rice, Thomas O & Heather M	Second	Block 7	Lot 4		1	Vacant	
Owen, Heather and Sandra	Second	Block 7	Lot 5	1		House	
Hill, Craig & Melissa P.	Second	Block 7	Lot 6	1		House	
Sing, Bruce & Kerrie D	Second	Block 8	Lot 1		1	Vacant	
Schraga-Leon, Suzanne M (John) add "E." to address	Second	Block 8	Lot 2		1	Vacant	
Sheridan-Wolcott Trust	Second	Block 8	Lot 3		1	Vacant	
Landis, Debra J	Second	Block 8	Lot 4		1	Vacant	
Mohr, Charles and Jacalyn	Second	Block 8	Lot 5		1	Vacant	
Mohr, Charles and Jacalyn	Second	Block 8	Lot 6	1		House	
Brulotte, Eric & Lisa	Second	Block 8	Lot 7	1		House	
Hill, Theresa L	Seocnd	Block 9	Lot 1		1	Vacant	
Hill's Holding	Seocnd	Block 9	Lot 2		1	Vacant	
Grimes, Randy and Nancy	Seocnd	Block 9	Lot 3		1	Vacant	
Hutter, Michael A & Sue	Seocnd	Block 9	Lot 4		1	Vacant	
Kine, Scott & Lisa	Seocnd	Block 9	Lot 5	1		House V. RENTAL	
Urquhart, Linda	Seocnd	Block 9	Lot 6		1	Vacant	
Rein, Geraldine G	Seocnd	Block 9	Lot 7		1	Vacant	
Garabedian, Carl P	Seocnd	Block 9	Lot 8		1	Vacant	
Krista Whelan (ex-wife of Salesky)	New Const. ruction	Unit 2	1			New Condo for sale	
Papa Murphy's Belfair Inc	New Const. ruction	Unit 3	1			New Condo for sale	
				46	91		
				developed lots	stub-in/being built		



POD – WELL D0013090 (A0015422)



WELL D0013090




WELL D0013090 – DEQ TAG E009124



WELL D0013090 PUMP CONTROL VAULT AND WATER SYSTEM



DIVERTING WORKS



30 HP PUMP



FLOW METER FOR WELL D0013090



STORAGE RESERVOIR FOR WATER SYSTEM





DISTRIBUTION PUMP HOUSE FROM STORAGE RESERVOIR



DISTRIBUTION PUMP FROM RESERVOIR



7.5 HP PUMP FOR DISTRIBUTION FROM RESERVOIR TO MUNICIPAL POU



MUNICIPAL POU – CLUB HOUSE



MUNICIPAL POU





MUNICIPAL POU





MUNICIPAL POU





MUNICIPAL POU - STUB IN LOCATION EXAMPLES

