WATER DISTRICT NO. 37 & 37 M

P.O. Box T Shoshone, Idaho 83352 (208) 886-2451

March 19,2001

A.W. Molyneux 1174 Gannett Rd Bellevue, Idaho 83313

COPY

Watermaster

Dear Mr. Molyneux, Our Deputy has advised me that your diversion at Dittoe 56-D, needs to be rebuilt, and as a result he cannot make accurate measurement of your water.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repairs to this diversion need to be done as soon as possible for delivery of water during the 2001 season.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson Watermaster

Cc: IDWR

WATER DISTRICT NO. 37 & 37 M

P.O. Box T Shoshone, Idaho 83352 (208) 886-2451

March 19,2001

RECEIVEL

MAR 2 0 2001

Watermaster

COPY Department of Water Resource Southern Region

Rupert House 308 East Fork Rd. Hailey, Idaho 83333

Dear Mr. House,

Cc: IDWR

Our Deputy has advised me that your diversion at Peters 17-A has no measuring device, and as a result he cannot make accurate measurement of your water.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this diversion needs to be done as soon as possible for delivery of water during the 2001 season.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson

Watermaster

WATER DISTRICT NO. 37 & 37 M

P.O. Box T Shoshone, Idaho 83352 (208) 886-2451

March 19,2001

Cc: IDWR

RECEIVEE R. PETERSON Watermaster

MAR 2 0 2001

Department of Water Resource Southern Region

Scott B. Clark P O Box 3028 Salt Lake City, UT 84111

Dear Mr. Clark, Our Deputy has advised me that your diversion at Haugh 42-A does not have a flow meter, and as a result he cannot make accurate measurement of your water.

COPY

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Installation of a flow meter (preferably a Micrometer that registers in CFS) needs to be done as soon as possible for delivery of water during the 2001 season.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson

Watermaster

WATER DISTRICT NO. 37 & 37 M

P.O. Box T Shoshone, Idaho 83352 (208) 886-2451

March 19,2001

Leroy Lewis 3774 S 5th West Idaho Falls, Idaho 83404

COPY





Dear Mr. Lewis,

Our Deputy has advised me that your diversion at Kline 37 needs to be rebuilt and as a result he cannot make accurate measurement of your water.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion. the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this diversion needs to be done as soon as possible for delivery of water during the 2001 season.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson

Watermaster

CC:

I.DWR