


Holly Water Users Weir (Now part of
Mud Lake Water Users) 7N 35E 36 NW 1/4, in
WD 31:

On 7/5/00 and 7/6/00 this weir was running
submerged. The ditch rider's notes in the mailbox
did not mention the submergence. This is a
contracted rectangular weir, $L \approx 15-20'$. On
7/6/00 I measured the following dimensions
w/ my measuring rod: ($\approx 8:45$ AM)



~~I took photos but the process or lost them.~~

Dwight A. Coulter

ROUTING SLIP

TO: Keith Wilson

FROM: Bryce

DATE: 7/7/00 TIME: _____

PER:	
Our Conversation	
Your Request	
The Attached	

FOR YOUR:		REVIEW AND:	
Information		Take Proper Action	
Approval		Comment	
Signature		Draft A Reply	

cc: Tim Luke

ATTACHED TO BE:			
Posted		Returned To Me	
Circulated		Filed	
Distributed		Copied (_____ copies)	

RE: 100 31 Watermaster Records