Last Name	First Name	Diversion	April	May	June	July	Aug	Sept	October	Total AC-FT
*Fairchild	Rose	1 Mill	***	***	***	***	***	***	***	*
*Harper	Jay	1 Mill	***	***	***	***	***	***	***	*
Zollinger	Wade	1 Mill	***	***	16.76	13.68	11.61	6.64	***	*48.76*
Marchant	Gerald	1 Mill	***	***	***	8.72	11.9	9.91	***	*30.53*
Spearing	Scott	1 Mill	***	***	10.9	10.41	12.88	3.96	**	38.15
Hawker	Craig	1 Mill	2.1	7.22	6.59	5.63	0.0	0.0	0.0	21.57
Justesen	Neil	1Mill	10.23	16.65	0.0	0.0	0.0	0.0	0.0	26.88
Hawker	Craig	2 Mill	3.17	16.66	10.95	20.86	6.9	9.2	0.0	67.74
Fairchild	Basil	2 Mill	0.0	8.5	7.16	4.34	3.6	4.8	0.0	28.40
Marchant	Gerald	2 Mill	3.77	62.48	72.55	24.8	18.2	13.65	0.0	195.45
Bedke	Bruce	2 Mill	0.0	23.33	36.34	6.9	9.2	6.9	0.0	82.67
										76.13
Fairchild	Basil	3 Mill	13.30	41.99	20.84	0.0	0.0	0.0	0.0	76.13
Hawker	Craig	3 Mill	14.21	19.77	6.59	0.0	0.0	0.0	0.0	40.57
Bedke	Jared	3 Mill	4.38	31.35	4.13	0.0	0.0	0.0	0.0	39.86
Marchant	Gerald	3 Mill	0.0	2.08	0.0	0.0	0.0	0.0	0.0	2.08
Wells	Bill	4 Mill	***	***	***	***	***	***	***	***
Manninig	Bob	4 Mill	***	***	***	***	***	***	***	***
Smith	Craig	1 Spring	0.0	14.18	5.21	7.33	0.82	***	***	27.56
Smith	Kevin	1 Spring	2.06	6.67	.95	0.0	0.0	0.0	0.0	9.68
Gorringe	Tom	1 Spring	0.0	0.07	1.66	1.66	.83	0.0	0.0	4.15
Matthews	Eugene	1 Spring	33.8	39.26	31.89	18.31	***	***	***	123.26
										02.4
Martin	Rex	2 Spring	12.38	52.35	18.81	6.42	2.14	0.0	0.0	92.1
Zollinger	Wade	2 Spring	6.25	45.92	13.4	1.59	0.0	0.0	0.0	67.16
Bedke	Bruce	2 Spring	8.23	44.73	18.35	8.63	0.0	0.0	0.0	79.84
Wadsworth	Jeff	Summit	0.0	5.37	5.37	5.37	3.45	3.45	0.0	23.01
Hawker	Craig	Summit	4.5	19.8	19.8	19.8	12.74	12.74	12.74	89.38
Bedke	Bruce	Summit	.58	3.42	3.42	3.42	2.21	2.21	0.0	15.26
Wells	George k	Summit		25.61	29.79	29.79	21.43	17.25	5.75	129.62
Total Water 2012			118.96	487.34	341.46	197.66	117.91	90.71	18.49	1,359.81

Sandra Hale 45A

Basin Creek Water District 45A

Checking Account Summary 2012 D. L. Evans Bank

DATE	REFERENCE	PAYEE/PAYER	DESCRIPTION	CREDIT/DEBIT	BALANCE
12/23/11 1/25/12	Deposit Ke	evin Smith	2011 statement balance Water Master Tax-2011	86.40	2,302.50 2,388.90
1/27/12	Credit No.	SVIN SIMITH	Income-Interest	0.11	2,389.01
1/27/12	Debit	1	Federal With-holding	-0.03	2,388.98
1/30/12			Water Master Report	-500.00	1,888.98
2/24/12	Credit	un riiggs	Income-Interest	-500.00	1,889.06
2/24/12	Debit		Federal With-holding	-0.02	1,889.04
3/12/12	· ·	ı ounty Tax Collec			1,862.04
3/23/12	Credit	ounty tax conec	Interest Income	0.07	1,862,11
3/23/12	Debit		Federal With-holding	-0.02	1,862.11
4/10/12		Water Users)	Water Master Tax	6,237.56	8,099.65
4/25/12		ra Hale		•	7,349.65
4/26/12		n Field Welding	Contract Labor (water maste 2 water weirs (#36275)	-976.89	6,372.76
4/27/12	Credit	n riela welaing	Interest Income	0.24	6,373.00
4/27/12	Debit		Federal With-holding	-0.07	6,372.93
5/14/12		nant/J. Zollinger		689.50	7,062.43
5/23/12	#203 Sandra	-	Contract Labor (water maste		6,312.43
5/24/12	#204 Vickie		Contract Labor (secretarial)	•	6,112.43
5/24/12	••••		racting LLC Contract Labor		5,412,43
5/25/12	Credit	ie i recision com	Interest Income	0.29	5,412,72
5/25/12	Debit		Federal With-holding	-0.08	5,412.64
6/22/12	Credit		Interest Income	0.21	5,412.85
6/27/12		a Hale	Contract Labor (water mast		4,662.85
7/25/12		a Hale	Contract Labor (water mast		3,912.85
7/27/12	Credit	a riale	Interest Income	0.22	3,913.07
7/28/12		n Field Welding	1 water weir (#36517)	- 4 77,76	3,435.31
8/22/12		ra Hale	Contract Labor (water mast		2,685.31
8/24/12	Credit	a riaic	Interest Income	0.14	2,685.45
9/10/12	#210 ID State	Insurance Fund	Workers Compensation Policy		2,396.45
9/26/12		a Hale	Contract Labor (water mast		1,646.45
9/28/12	Credit	u / lui0	Interest Income	0.12	1,646.57
10/26/12	Credit		Interest Income	0.06	1,646.63
11/23/12	Credit		Interest Income	0.06	1,646.69
11/23/12	Debit		Federal With-holding	0.02	1,646.67
12/06/12	#212 Sandra	a Hale (sea:	sons' water report to the boar		1,146.67
		•	•	•	*

NOTE: (12/06/12) Eugene said that there is still one outstanding bill that needs to be paid. He has the billing statement.

Sandra Hale 45A Water Master

2012 End of the year Report on what needs fixed in the Basin District.

<u>Spring Creek Feeder:</u> needs small (2ft?) weir to measure how much to send across feeder ditch and weir before water goes into spring creek so % loss can be measured.

<u>Summit Creek Feeder:</u> Thank You Board of directors for the new weir! Weir pool needs cleaned out in from of summit feeder head gate. Needs weir before water goes into summit creek so % loss can be measured. Cat walk needs put up because this is a very hard place to cross.

ZMS: This has been a problem spot! **Weir in creek** is Broken and need replaced a weir needs to be placed in the ditch after the head gate and a weir pool needs put in also. This ditch needs fixed so that when the screen going into the pipe gets clogged it will not flood over and fill the pond behind it and waste the water.

<u>Harper</u>: This has been a problem spot! Needs weir put in Creek channel. Head gate needs replaced with a bigger screw down gate that can be locked and that dose not leak the screw down head gate is being ask for because of past problems. It needs to be placed lower so gate is not at high water mark. Also need weir and weir pool in their ditch.

— Hawker/ Marchant East: Weir in creek chance Leaks on north side and needs fixed. The Hawker Head gate sometimes has a problem shutting off I do not know if this is because the weir pool needs cleaned out or if it is a problem with the gate. Water leaked back around and into the creek cement needs fixed in-between the creek and the ditch. The blue weir needs the north side fixed so water will not leak around weir.

<u>Marchant /Bedke</u>: Needs Weir in creek Channel. Bedke/ Marchant head gate needs fixed or replaced so it will shut off all the way. The north and south sides of the weir in the ditch leak and weir pool needs cleaned out badly.

<u>Jared Bedke</u>: water leeks from creek under head gate and back into creek. Weir in ditch needs to be set in cement and not just laying in the ditch. Weir pool needs cleaned out.

<u>4Mill Gap</u>: North side head gate is broken and will not shut off. South side if their going to take water out the 2 foot opening it must have a weir placed on it and must not take water out of both openings during time water master is on so one side must be blocked off and not leaking if taking through the small opening. The big opening to the far south needs cleaned the weir pool cleaned out in front of it.

1Spring Gorringe/ Matthews: Water leeks from the ditch back into the creek on west side just after weir. East side head gate will not open. Weir pool in creek needs cleaned out.

1Spring Smith/Smith: Thank you for cleaning out by your weir!

1 Spring Smith lower: Weir pool in creek needs cleaned out. Water leeks from creek around head gate on east side and into the ditch needs fixed.

thed.

Spring Creek Matthews: Weir/ Gate needs tilted back up level. And east side needs fixed so it dose not beak.

<u>2 Spring</u>: would be nice to have better boards to shut off the other users while one is on so that they don't leak as much.

<u>Summit</u> Things are good! Thank you! I don't do much on summit Creek I only turn hawkers water so I can take a measurement. So sorry I missed some turns ^②

I know that this is a lot but if everyone would fix the things that are wrong with there head gates and the weir pools in front of their head gates it would not take much work. The Creek channel needs listed out on what needs done first and I think if the board just picks a couple to do a year it would help and only take a couple of years to fix.

Thanks

Sandra Hale

208-432-2604