



State of Idaho
DEPARTMENT OF WATER RESOURCES

206 Van Dreff, Suite B, Salmon, ID 83467-4117
Phone: (208) 756-6644 FAX: (208) 756-6644

PHILIP E. BATT
GOVERNOR

KARL J. DREHER
DIRECTOR

October 16, 1995

Robert B. Amonson
C/O PO Box 51
Lemhi, Idaho 83465

Mr. Amonson:

On September 27, 1995 I accompanied Dick Moll, Watermaster of Water District 74-Q, and John Amonson, to inspect irrigation diversions on Mill Creek.

This visit was made at the request of Dick Moll, watermaster, in response to his letter to Water District 74-Q waterusers concerning the condition and maintenance of diversions and/or headgates/control devices.

My inspection of your headgate (s) and/or controlling device (s) revealed all were in need of repair or replacement to insure accurate delivery of your water right (s) by the watermaster.

An order requiring suitable headgates/controlling devices will be forthcoming from the Department of Water Resources, pursuant to Idaho Code 42-701. I recommend contacting Dick Moll, Watermaster of Water District 74-Q, to determine which headgates/control devices need the most immediate attention. Please be aware that failure to correct these conditions may affect delivery of your water right (s) during the 1996 irrigation season.

If you have any questions or if the department can be of further assistance feel free to contact me at (208) 756-6644 or Gary Spackman in our Boise office at (208) 327-7900.

Cordially,

Robert E. Foster
Sr. Water Resource Agent

cc: Gary Spackman, State Office
Harold W. Jones, Eastern Region
Dick Moll, Watermaster 74-Q

RECEIVED

OCT 18 1995

Department of Resources
Eastern District Office



State of Idaho
DEPARTMENT OF WATER RESOURCES

206 Van Dreff, Suite B, Salmon, ID 83467-4117
Phone: (208) 756-6644 FAX: (208) 756-6644

PHILIP E. BATT
GOVERNOR

KARL J. DREHER
DIRECTOR

October 16, 1995

James F. Stoddard
HC-68 Box 17
Leadore, Idaho 83464

Mr. Stoddard:

On September 27, 1995 I accompanied Dick Moll, Watermaster of Water District 74-Q, and John Amonson, to inspect irrigation diversions on Mill Creek.

This visit was made at the request of Dick Moll, watermaster, in response to his letter to Water District 74-Q waterusers concerning the condition and maintenance of diversions and/or headgates/control devices.

My inspection of your headgate (s) and/or controlling device (s) revealed all were in need of repair or replacement to insure accurate delivery of your water right (s) by the watermaster.

An order requiring suitable headgates/controlling devices will be forthcoming from the Department of Water Resources, pursuant to Idaho Code 42-701. I recommend contacting Dick Moll, Watermaster of Water District 74-Q, to determine which headgates/control devices need the most immediate attention. Please be aware that failure to correct these conditions may affect delivery of your water right (s) during the 1996 irrigation season.

If you have any questions or if the department can be of further assistance feel free to contact me at (208) 756-6644 or Gary Spackman in our Boise office at (208) 327-7900.

Cordially,

A handwritten signature in cursive script that reads "Robert E. Foster".

Robert E. Foster
Sr. Water Resource Agent

cc: Gary Spackman, State Office
Harold W. Jones, Eastern Region
Dick Moll, Watermaster 74-Q

RECEIVED

OCT 18 1995

Department of Water Resources
Eastern District Office



State of Idaho
DEPARTMENT OF WATER RESOURCES

206 Van Dreff, Suite B, Salmon, ID 83467-4117
Phone: (208) 756-6644 FAX: (208) 756-6644

PHILIP E. BATT
GOVERNOR

KARL J. DREHER
DIRECTOR

October 16, 1995

Strupp Enterprises
PO Box 12
Leadore, Idaho 83464

Mr. Strupp:

On September 27, 1995 I accompanied Dick Moll, Watermaster of Water District 74-Q, and John Amonson, to inspect irrigation diversions on Mill Creek.

This visit was made at the request of Dick Moll, watermaster, in response to his letter to Water District 74-Q waterusers concerning the condition and maintenance of diversions and/or headgates/control devices.

My inspection of your headgate (s) and/or controlling device (s) revealed all were in need of repair or replacement to insure accurate delivery of your water right (s) by the watermaster.

An order requiring suitable headgates/controlling devices will be forthcoming from the Department of Water Resources, pursuant to Idaho Code 42-701. I recommend contacting Dick Moll, Watermaster of Water District 74-Q, to determine which headgates/control devices need the most immediate attention. Please be aware that failure to correct these conditions may affect delivery of your water right (s) during the 1996 irrigation season.

If you have any questions or if the department can be of further assistance feel free to contact me at (208) 756-6644 or Gary Spackman in our Boise office at (208) 327-7900.

Cordially,

Robert E. Foster
Sr. Water Resource Agent

cc: Gary Spackman, State Office
Harold W. Jones, Eastern Region
Dick Moll, Watermaster 74-Q

RECEIVED

OCT 18 1995

Department of Water Resources
Eastern District Office



State of Idaho
DEPARTMENT OF WATER RESOURCES

206 Van Dreff, Suite B, Salmon, ID 83467-4117
Phone: (208) 756-6644 FAX: (208) 756-6644

PHILIP E. BATT
GOVERNOR

KARL J. DREHER
DIRECTOR

October 16, 1995

McFarland Livestock Co. Inc.
C/O Tex J Kauer
PO Box 50
Lemhi, Idaho 83465

Mr. Kauer:

On September 27, 1995 I accompanied Dick Moll, Watermaster of Water District 74-Q, and John Amonson, to inspect irrigation diversions on Mill Creek.

This visit was made at the request of Dick Moll, watermaster, in response to his letter to Water District 74-Q waterusers concerning the condition and maintenance of diversions and/or headgates/control devices.

My inspection of your headgate (s) and/or controlling device (s) revealed all were in need of repair or replacement to insure accurate delivery of your water right (s) by the watermaster.

An order requiring suitable headgates/controlling devices will be forthcoming from the Department of Water Resources, pursuant to Idaho Code 42-701. I recommend contacting Dick Moll, Watermaster of Water District 74-Q, to determine which headgates/control devices need the most immediate attention. Please be aware that failure to correct these conditions may affect delivery of your water right (s) during the 1996 irrigation season.

If you have any questions or if the department can be of further assistance feel free to contact me at (208) 756-6644 or Gary Spackman in our Boise office at (208) 327-7900.

Cordially,

A handwritten signature in cursive script that reads "Robert E. Foster".

Robert E. Foster
Sr. Water Resource Agent

cc: Gary Spackman, State Office
Harold W. Jones, Eastern Region
Dick Moll, Watermaster 74-Q

RECEIVED

OCT 18 1995

Department of Water Resources
Eastern District Office

August 1, 1995

Judy Amonson, Secretary
WATER DISTRICT #74-Q
PO Box 51
Lemhi ID 83465

RE: LICENSE #74-07223

Dear Ms. Amonson:

Enclosed please find a copy of a LICENSE issued within your district. If you have any questions, please feel free to contact this office.

Sincerely,

LISA KEISER
Office Secretary

Enclosure

County Treasurer's Report of Water Master Collections

Alberta Wiederrick Auditor
Richard Moll Water Master
Box 153
Leadore, ID 83464 Water District
74-Q Mill, Peterson & Alder
 Lemhi County, Idaho.

RECEIVED

JUN 08 1995

Department of Water Resources
 Eastern District Office

Dear Sirs:

I, Mary Ann Heiser, Treasurer of Lemhi County, Idaho, do hereby report to
 you water assessments collected by me during the month of May 2, 1995 through June 5, 1995.
 Season of 1995, and since my last statement.

Receipt Number	Received From	Water Charges	Other Charges	Total Paid
2177	F. Stoddard (1992)	10 02	2 55	12 57
2386	F. Stoddard (1994)	7 64	72	8 36
2520	W. A. Snyder	553 30		553 30
TOTAL COLLECTED		570 96	3 27	574 23

Dated June 5th, 19 95

Respectfully submitted,

Mary Ann Heiser
 Treasurer

By Helen Skidmore Deputy
 Helen Skidmore

County Treasurer's Report of Water Master Collections

RECEIVED

Alberta Wiederrick Auditor
Richard Moll Water Master
 Box 153
Leadore, ID 83464 Water District
 74-Q Mill Creek
 Lemhi County, Idaho.

APR - 6 1995

Department of Water Resources
 Eastern District Office

Dear Sirs:

I, Mary Ann Heiser, Treasurer of Lemhi County, Idaho, do hereby report to
 you water assessments collected by me during the month of March 8, 1995 through April 4, 1995.
 Season of 1995, and since my last statement.

Receipt Number	Received From	Water Charges		Other Charges		Total Paid	
2519	J. C. Amonson	976	08			976	08
2521	R. E. Carlson	56	59			56	59
2522	R. L. Tyler	130	64			130	64
	TOTAL COMPLETED	1163	31		-0-	1163	31

Dated April 4, 1995

Respectfully submitted,

Mary Ann Heiser
 Treasurer

By Helen Skidmore Deputy
 Helen Skidmore

74-Q

7 AUGUST 1995

DEAR JOHN AMONSON:

A copy of this letter is being sent to each Mill Creek water user. For many years, including this year (1995), Mill Creek has been impossible to control effectively or with any real degree of accuracy.

In some instances effectively controllable and easily adjustable headgates and diversions are non-existent. In other instances they are effectively controllable and easily adjustable in name only. At the present time, there are only three headgates on the entire creek that qualify as effectively controllable and easily adjustable.

The past and present use of rocks, boulders, sod, strawbales and canvas dams to control and adjust the waters of Mill Creek is both ineffective and inaccurate and can be dangerous as well. As your watermaster, it is my desire to do a first class job of controlling and regulating the waters of Mill Creek - but, under current conditions this is an impossibility.

With the current situation as a basis, I am formally requesting that you install fully controllable and easily adjustable headgates and diversions in all instances. These requested changes and improvements to be completed to the watermaster's satisfaction no later than October 31, 1995.

In support of my request, I am enclosing a copy of section 6 of the Watermaster's Handbook entitled "Headgates, Controlling Works and Measuring Devices."

For my part, I will gladly work with and cooperate with each of you to insure that the results of your efforts are something we can both be happy with and proud of. It is my sincere desire that we satisfactorily accomplish the necessary changes and improvements on a local level without the need to involve the Idaho Department of Water Resources.

I look forward to working with you - to make Mill Creek the best instead of the worst creek to work with and regulate.

RECEIVED

OCT 18 1995

Department of Water Resources
Eastern District Office

SINCERELY,
Dick Moll
DICK MOLL
WATERMASTER



State of Idaho
DEPARTMENT OF WATER RESOURCES

206 Van Dreff, Suite B, Salmon, ID 83467-4117
Phone: (208) 756-6644 FAX: (208) 756-6644

PHILIP E. BATT
GOVERNOR

KARL J. DREHER
DIRECTOR

October 16, 1995

John Amonson
PO Box 36
Leadore, Idaho 83464

Mr. Amonson:

On September 27, 1995 I accompanied Dick Moll, Watermaster of Water District 74-Q, and yourself to inspect irrigation diversions on Mill Creek.

This visit was made at the request of Dick Moll, watermaster, in response to his letter to Water District 74-Q waterusers concerning the condition and maintenance of diversions and/or headgates/control devices.

My inspection of your headgate (s) and/or controlling device (s) revealed all were in need of repair or replacement to insure accurate delivery of your water right (s) by the watermaster.

An order requiring suitable headgates/controlling devices will be forthcoming from the Department of Water Resources, pursuant to Idaho Code 42-701. I recommend contacting Dick Moll, Watermaster of Water District 74-Q, to determine which headgates/control devices need the most immediate attention. Please be aware that failure to correct these conditions may affect delivery of your water right (s) during the 1996 irrigation season.

If you have any questions or if the department can be of further assistance feel free to contact me at (208) 756-6644 or Gary Spackman in our Boise office at (208) 327-7900.

Cordially,

Robert E. Foster
Sr. Water Resource Agent

cc: Gary Spackman, State Office
Harold W. Jones, Eastern Region
Dick Moll, Watermaster 74-Q

RECEIVED

OCT 18 1995

Department of Water Resources
Eastern District Office



State of Idaho
DEPARTMENT OF WATER RESOURCES

206 Van Dreff, Suite B, Salmon, ID 83467-4117
Phone: (208) 756-6644 FAX: (208) 756-6644

PHILIP E. BATT
GOVERNOR

KARL J. DREHER
DIRECTOR

October 16, 1995

William A. Snyder
PO Box 49
Lemhi, Idaho 83465

Mr. Snyder:

On September 27, 1995 I accompanied Dick Moll, Watermaster of Water District 74-Q, and John Amonson, to inspect irrigation diversions on Mill Creek.

This visit was made at the request of Dick Moll, watermaster, in response to his letter to Water District 74-Q waterusers concerning the condition and maintenance of diversions and/or headgates/control devices.

My inspection of your headgate (s) and/or controlling device (s) revealed all were in need of repair or replacement to insure accurate delivery of your water right (s) by the watermaster.

An order requiring suitable headgates/controlling devices will be forthcoming from the Department of Water Resources, pursuant to Idaho Code 42-701. I recommend contacting Dick Moll, Watermaster of Water District 74-Q, to determine which headgates/control devices need the most immediate attention. Please be aware that failure to correct these conditions may affect delivery of your water right (s) during the 1996 irrigation season.

If you have any questions or if the department can be of further assistance feel free to contact me at (208) 756-6644 or Gary Spackman in our Boise office at (208) 327-7900.

Cordially,

Robert E. Foster
Sr. Water Resource Agent

cc: Gary Spackman, State Office
Harold W. Jones, Eastern Region
Dick Moll, Watermaster 74-Q

RECEIVED

OCT 19 1995

Dep. _____
Eastern District Office



State of Idaho
DEPARTMENT OF WATER RESOURCES

206 Van Dreff, Suite B, Salmon, ID 83467-4117
Phone: (208) 756-6644 FAX: (208) 756-6644

PHILIP E. BATT
GOVERNOR

KARL J. DREHER
DIRECTOR

October 16, 1995

Robert E. Carlson
HC-68 Box 16
Leadore, Idaho 83464

Mr. Carlson:

On September 27, 1995 I accompanied Dick Moll, Watermaster of Water District 74-Q, and John Amonson, to inspect irrigation diversions on Mill Creek.

This visit was made at the request of Dick Moll, watermaster, in response to his letter to Water District 74-Q waterusers concerning the condition and maintenance of diversions and/or headgates/control devices.

My inspection of your headgate (s) and/or controlling device (s) revealed all were in need of repair or replacement to insure accurate delivery of your water right (s) by the watermaster.

An order requiring suitable headgates/controlling devices will be forthcoming from the Department of Water Resources, pursuant to Idaho Code 42-701. I recommend contacting Dick Moll, Watermaster of Water District 74-Q, to determine which headgates/control devices need the most immediate attention. Please be aware that failure to correct these conditions may affect delivery of your water right (s) during the 1996 irrigation season.

If you have any questions or if the department can be of further assistance feel free to contact me at (208) 756-6644 or Gary Spackman in our Boise office at (208) 327-7900.

Cordially,

Robert E. Foster
Sr. Water Resource Agent

cc: Gary Spackman, State Office
Harold W. Jones, Eastern Region
Dick Moll, Watermaster 74-Q

RECEIVED

OCT 18 1995

Department of Water Resources
Eastern District Office



State of Idaho

DEPARTMENT OF WATER RESOURCES

206 Van Dreff, Suite B, Salmon, ID 83467-4117

Phone: (208) 756-6644 FAX: (208) 756-6644

PHILIP E. BATT
GOVERNOR

KARL J. DREHER
DIRECTOR

October 16, 1995

Richard E. Tyler
HC-68 Box 14
Leadore, Idaho 83464

Mr. Tyler:

On September 27, 1995 I accompanied Dick Moll, Watermaster of Water District 74-Q, and John Amonson, to inspect irrigation diversions on Mill Creek.

This visit was made at the request of Dick Moll, watermaster, in response to his letter to Water District 74-Q waterusers concerning the condition and maintenance of diversions and/or headgates/control devices.

My inspection of your headgate (s) and/or controlling device (s) revealed all were in need of repair or replacement to insure accurate delivery of your water right (s) by the watermaster.

An order requiring suitable headgates/controlling devices will be forthcoming from the Department of Water Resources, pursuant to Idaho Code 42-701. I recommend contacting Dick Moll, Watermaster of Water District 74-Q, to determine which headgates/control devices need the most immediate attention. Please be aware that failure to correct these conditions may affect delivery of your water right (s) during the 1996 irrigation season.

If you have any questions or if the department can be of further assistance feel free to contact me at (208) 756-6644 or Gary Spackman in our Boise office at (208) 327-7900.

Cordially,

Robert E. Foster
Sr. Water Resource Agent

cc: Gary Spackman, State Office
Harold W. Jones, Eastern Region
Dick Moll, Watermaster 74-Q

RECEIVED

OCT 18 1995

Departments
Eastern District Office



State of Idaho
DEPARTMENT OF WATER RESOURCES

206 Van Dreff, Suite B, Salmon, ID 83467-4117
Phone: (208) 756-6644 FAX: (208) 756-6644

PHILIP E. BATT
GOVERNOR

KARL J. DREHER
DIRECTOR

October 16, 1995

Peterson Land & Livestock
Attn: Ed Peterson
Box 85
Leadore, Idaho 83464

Mr. Peterson:

On September 27, 1995 I accompanied Dick Moll, Watermaster of Water District 74-Q, and John Amonson, to inspect irrigation diversions on Mill Creek.

This visit was made at the request of Dick Moll, watermaster, in response to his letter to Water District 74-Q waterusers concerning the condition and maintenance of diversions and/or headgates/control devices.

My inspection of your headgate (s) and/or controlling device (s) revealed all were in need of repair or replacement to insure accurate delivery of your water right (s) by the watermaster.

An order requiring suitable headgates/controlling devices will be forthcoming from the Department of Water Resources, pursuant to Idaho Code 42-701. I recommend contacting Dick Moll, Watermaster of Water District 74-Q, to determine which headgates/control devices need the most immediate attention. Please be aware that failure to correct these conditions may affect delivery of your water right (s) during the 1996 irrigation season.

If you have any questions or if the department can be of further assistance feel free to contact me at (208) 756-6644 or Gary Spackman in our Boise office at (208) 327-7900.

Cordially,

Robert E. Foster
Sr. Water Resource Agent

cc: Gary Spackman, State Office
Harold W. Jones, Eastern Region
Dick Moll, Watermaster 74-Q

OCT 18 1995

Department of Water Resources
Eastern District Office