

*✓DNR**File*

WATER DISTRICT NO. 65

102 N. Main St.
Payette, Idaho 83661
Phone (208) 642-4465
Fax (208) 642-1042

August 21, 1995

Mr. Mark Dawson, Manager
Horseshoe Bend Hydro Project
44 Industries
P.O. Box 2797
Boise, Idaho 83701

Dear Mark:

Yesterday, Sunday, August 20, 1995, I visited with you concerning certain flow disruptions experienced by the Black Canyon Dam operator on duty. You indicated that these flow disruptions were caused by your plant shutting off your generators as well as the canal headgates due to a leak in the liner of the canal. Flows at Black Canyon Dam dropped from 871 cfs to 511 cfs between noon and 2:30 p.m., and the lake elevation dropped from 2,497.50 to 2,497.42 during that time. This drop in river flow and lake elevation caused disruptions in the delivery of irrigation water to users on the Payette River. My letter of August 2, 1995, advised you that major disruptions in flows on the Payette River caused by your operations would not be tolerated during irrigation season. Now that this has happened a second time, my only choice is to call a meeting with you and your personnel, as well as with affected users on the river, to discuss alternative procedures in an attempt to eliminate any flow disruptions in the future.

25

I have taken the liberty of setting this meeting for Friday, August 25, at 1:30 p.m. here in my Payette office at 102 N. Main St. If you have further questions, please give me a call.

Sincerely,

Mark Limbaugh, Watermaster

cc: Mr. Brad Andrew, WD65
Mr. Dave Tuthill, IDWR
Ms. Sheryl Howe, IDWR
Mr. Rick Wells, BOR
Black Canyon Dam Operators
Black Canyon Irrigation District
Emmett Irrigation District
Farmer's Co-op Irrigation Company
Noble Ditch Company
Lower Payette Ditch Company