

State of Idaho

DEPARTMENT OF WATER RESOURCES

1301 North Orchard Street, Boise, ID 83706 - P.O. Box 83720, Boise, ID 83720-0098 Phone: (208) 327-7900 Fax: (208) 327-7866 Web Site: www.idwr.state.id.us

DIRK KEMPTHORNE Governor KARL J. DREHER Director

September 17, 2003

Carl or Terry Jorgensen 1699 Lloyd Rd Bancroft, ID 83217

CERTIFIED MAIL

Re: Water Level Probe Stuck in Well Located in NWNW Sec. 32, T9S, R40E

Dear Gentlemen,

This letter is to confirm and document that a water level probe used by the Water District 13-T watermaster was lost in your well at the above referenced location on July 21, 2003. You will recall that the watermaster and I advised you of this problem on August 4, 2003 when we visited with you at the well site.

The Department and water district has measured this well since 1996 without incident. The watermaster, Craig Shuler, reported that approximately 120 to 130 feet of the probe was lost down the well. The lost section of probe consists of unmarked orange electrical cable or wire. The probe was initially hung up or stuck in the well on about July 17, 2003. The watermaster left the probe in place and returned on July 21st to try to dislodge the wire. The wire broke off near the access port on this latter date in his attempt to remove it from the well. There has been no apparent damage to the well or pump resulting from this incident as evidenced by the continued use of the well since July 21st of this year. However, you are advised to contact the Department should this situation result in any damage to the pumping plant.

Please contact me directly at 208-327-7864 if you have any further concerns or questions regarding this matter.

Respectfully,

Tim Luke

Water Distribution Section

Cc: Craig Shuler, Watermaster IDWR Eastern Region

7/		
SENDER: COMPLETE THIS SECT	TION COMPLETE THIS SECTION ON DELIVERY	
Complete items 1, 2, and 3. Also item 4 if Restricted Delivery is de: Print your name and address on t so that we can return the card to Attach this card to the back of the	the reverse you. Put Torquising 9-23-0	
or on the front if space permits.	e mailpiece, X Dut Junelusu Agent	200
1. Article Addressed to:	D. Is delivery address different from item 1? Yes	300
Carlor Terry Jorg	If YES, enter delivery address below: No	
11-90 11-11 200	January 1	
1699 Lloyd Rd	American and the second	
	atti (Tilliperstatus) un	
Bananct -n	3. Service Type □ Certified Mail □ Express Mail	
Bancroft, ID	☐ Registered ☐ Return Receipt for Merchandi	ica
832	☐ Insured Matf ☐ C.O.D.	3C
2. Article Number (C)	4. Restricted Delivery? (Extra Fee) ☐ Yes	
2. Article Number (Copy from service label	0013 0130 0001	
PS Form 3811, July 1999	Domestic Return Receipt	
	102595-00-M-095	2
,		t.
	U.S. Postal Service	i
	CERTIFIED MAIL RECEIPT (Domestic Mail Only: No Insurance Coverage Provided)	
	(Domestic Mail Unity: No Insurance Coverage Provided)	ı
년 구		
	Postage \$	
 E-	Certified Fee 9 18	
m	Return Receipt Fee Postmark , Here	
	(Endorsement Required)	
	Restricted Delivery Fee (Endorsement Required)	
0.2	Total Postage & Fees \$	
	Sent To	
	TDWK Street, Apt. No.; or PO Box No.;	
	1301N Orchard St.	
<u></u>		
[~	DOISE ID 83706	