

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

Allen Merritt
IDWR
1341 Fillmore, Suite 200
Twin Falls, Idaho 83301

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

October 30, 1997

Dear Allen,

Enclosed are copies of letters to each individual water user who needs to do maintenance or repair to their diversions. We are sending you copies in the event they do not complete the necessary repairs we will be contacting you to do a follow up letter from your office. In the past we have sent letters out most of which have been ignored. This year we intend not to deliver water until the problems are corrected.

We feel we are giving them plenty of notice to be able to complete the necessary work before the beginning of the next delivery season.

Sincerely,

Lee R. Peterson
Watermaster

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

Don Williams
305 Clear Lake Lane
Buhl, Idaho 83316

October 30, 1997

Don:

You need to clean the ditch and repair the headgate at your diversion point (Hitchcock #82).

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this diversion needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If you rent out your farm please forward this to your renter. If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

RECEIVED



OCT 31 1997 LEE R. PETERSON

Watermaster

Department of Water Resources
Southern Region

Clark Biedebach and or Joe Matheney
P O Box 54
Richfield, Idaho 83349

October 29, 1997

Gentlemen:

Your headgate and weir (Appell #60) needs to be rebuilt.

Idaho Code 42-701

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

This repair needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

A handwritten signature in cursive script, reading "Lee R. Peterson".

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

Robert Gardner
Gannett Route
Route 1, Box 470
Bellevue, Idaho 83313

RECEIVED
OCT 31 1997
Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

October 29, 1997

Dear Robert:

Your headgate and weir (Stanfield #13) needs to be rebuilt.

Idaho Code 42-701

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

This repair needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

A handwritten signature in cursive script, reading "Lee R. Peterson".

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

Nature Conservancy
P O Box 624
Picabo, Idaho 83348

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

October 30, 1997

Dear Paul:

You need to install an approved weir at your diversion point (Sun Valley Pump 00-P8)

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

This installation needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

RECEIVED

OCT 31 1997



LEE R. PETERSON
Watermaster

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

Department of Water Resources
Southern Region

Warren Nisson
Box 362
Hailey, Idaho 83333

October 30, 1997

Dear Warren:

You need to install an approved measuring device at your diversion point
(Brett 26 & 27)

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

This installation needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

M & M Farms
1550 S 1819 E
Gooding, Idaho 83330

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

October 30, 1997

Dear Nick:

You need to install a new headgate and measuring device at your diversion point (Walters #0033).

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this diversion needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

Pete Oneida

Shoshone, Idaho 83352

October 30, 1997

Pete:

Your meter is not working at your diversion point (Pete -67).
If you have to purchase a new meter I would recommend Micrometer that
meters in CFS.
Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho
shall maintain to the satisfaction of the director of the department of
water resources suitable headgates and controlling works at the point
where their water is diverted. Each device shall be of such construction
that it can be locked and kept closed by the watermaster or other officer
in charge, and shall also be of such construction as to regulate the flow
of water at the diversion point."

Failure to do so may result in the director of water resources instructing
the watermaster to shut off and refuse to deliver at the point of diversion,
the water owned by such appropriator or user until the user does
construct and maintain such headgates, controlling works or measuring
devices or remedy the defects which exist.

Repair of this meter needs to be done prior to the 1998 irrigation season;
otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

Don Taber
312 E 20 N
Shoshone, Idaho 83352

October 30, 1997

Dear Don:

There is no meter at your diversion point (Taber 66-P).

If you have to purchase a new meter I would recommend Micrometer that meters in CFS.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Installation of the meter needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

Joe Sorenson
45 Old State Hwy
Carey, Idaho 83370

October 30, 1997

Dear Joe:

Your Grainland meter is not working at your diversion point (Ragsdale 44-P). There is no meter hooked up at your diversion point (Cook 41-P).

If you have to purchase new meters I would recommend Micrometer that meters in CFS.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

The necessary repairs need to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

Elise Lufken
P O Box 8154
Ketchum, Idaho 83340

October 30, 1997

Dear Elise:

Your meter is not working at your diversion point (Lufken #21-P2). If you have to purchase a new meter I would recommend Micrometer that meters in CFS.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this meter needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

A handwritten signature in cursive script, reading "Lee R. Peterson".

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

Pat Millington
Box 707
Picabo, Idaho 83348

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

October 30, 1997

Pat:

Your Grainland meter is not working at your diversion point (Chaumell 22-P3). The wire is broke off. If you have to purchase a new meter I would recommend Micrometer that meters in CFS. Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this meter needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

A handwritten signature in cursive script, reading "Lee R. Peterson".

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

RECEIVED

OCT 31 1997



Department of Water Resources
Southern Region

LEE R. PETERSON
Watermaster

Richard Dalton
H C 8C60 Box 1420
Bliss, Idaho 83314

October 30, 1997

Dear Richard:

The water users need to clean the ditch and repair the headgate and install a measuring device at the diversion point (Thorpe #0040).

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this diversion needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

A handwritten signature in cursive script, reading "Lee R. Peterson".

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

Joe Savage
441 East Center
Kimberly, Idaho 83341

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

October 30, 1997

Dear Joe:

You need to install a new headgate and measuring device at your diversion point (Upper Frost #0038).

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this diversion needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

A handwritten signature in cursive script, reading "Lee R. Peterson".

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

RECEIVED

OCT 31 1997



Department of Water Resources
Southern Region
LEE R. PETERSON
Watermaster

Bill Arkoosh
2368 E 1775 S
Gooding, Idaho 83330

October 30, 1997

Dear Bill:

You have a broken orifice on your headgate at your diversion point (Devaney86).

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this diversion needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

A handwritten signature in cursive script, reading "Lee R. Peterson".

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON

Watermaster

Fred Judd
P O Box 476
Sun Valley, Idaho 83353

October 30, 1997

Dear Fred:

Your Grainland meter is not working at your diversion point (Heath #10). If you have to purchase a new meter I would recommend Micrometer that meters in CFS. Idaho Code 42-701 states in part:


"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this meter needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,


Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T

Shoshone, Idaho 83352

(208) 886-2451

John Varin
P O Box 190
Fairfield, Idaho 83327

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

October 30, 1997

Dear John:

Your meter is not working at your diversion point (Winters #80-P). If you have to purchase a new meter I would recommend Micrometer that meters in CFS.

Idaho Code 42-701 states in part:


"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this meter needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,



Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451



OCT 31 1997 LEE R. PETERSON
Department of Water Resources Watermaster
Southern Region

Sliman Land & Livestock
1642 B Hwy 46
Gooding, Idaho 83330

October 30, 1997

Dear David:

Your meter is not working at your diversion point (Silk #31-P). If you have to purchase a new meter I would recommend Micrometer that meters in CFS.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this meter needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

A handwritten signature in cursive script that reads "Lee R. Peterson".

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

Robert Mc Cabe
5201 Wavecrest Way
Oxnard, CA 93035

October 30, 1997

Dear Robert:

Your meter is not working at your diversion point (Lower Frost #0039). If you have to purchase a new meter I would recommend Micrometer that meters in CFS.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this meter needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

David Morrow
% Don Morrow
1661 S Main
Gooding, Idaho 83330

RECEIVED

OCT 31 1997



LEE R. PETERSON
Watermaster

Department of Water Resources
Southern Region

October 30, 1997

Dear David:

Your meter is not working at your diversion point Dietrich #0033-P). If you have to purchase a new meter I would recommend Micrometer that meters in CFS.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this meter needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

William Mirams
P O Box 961
Ketchum, Idaho 83340

October 30, 1997

Dear William:

Your meter is not working at your diversion point (Drager #35). If you have to purchase a new meter I would recommend Micrometer that meters in CFS.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this meter needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

A handwritten signature in cursive script, reading "Lee R. Peterson".

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

Alex Anchustegui
Star Route
Richfield, Idaho 83349



OCT 31 1997
LEE R. PETERSON
Watermaster
Department of Water Resources
Southern Region

October 30, 1997

Dear Alex:

Your headgate and weir (Hughes #64) needs to be rebuilt.

Idaho Code 42-701 states in part:


"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

This repair needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,


Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

James Figge
8015 Vizcaya Way
Naples, FL 33963

October 30, 1997

Dear James:

Your meter is not working at your diversion point (Cove #33). If you have to purchase a new meter I would recommend Micrometer that meters in CFS.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this meter needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

A handwritten signature in cursive script, reading "Lee R. Peterson".

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

John Flood
Box 317
Picabo, Idaho 83348

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

October 30, 1997

John:

Your Grainland meters are not working at your diversion points (Hunter 24-P & Lawson 24-P2). If you have to purchase a new meter I would recommend Micrometer that meters in CFS. Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of these meters needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

Bruce Willis
P O Box 3212
Hailey, Idaho 83333

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region

October 30, 1997



LEE R. PETERSON
Watermaster

Dear Bruce:

You need to repair the frame on the headgate at your diversion point (Aspen #27). It cannot be adjusted.

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this diversion needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

RECEIVED

OCT 31 1997



LEE R. PETERSON
Watermaster

Department of Water Resources
Southern Region

Starweather Subdivision
P O Box 254
Ketchum, Idaho 83340

October 30, 1997

Dear Sirs:

You need to install a new measuring device on the headgate at your diversion point (Mizer# 20).

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this diversion needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T

Shoshone, Idaho 83352

(208) 886-2451

Warm Springs Golf Course
% Bob Dunn
P O Box 5507
Ketchum, Idaho 83340

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

October 30, 1997

Bob:

You need to install a new front orifice on the headgate at your diversion point (Farnlum # 06).

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this diversion needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region



LEE R. PETERSON
Watermaster

Leroy Lewis
3774 S 5th St
Idaho Falls, Idaho 83404

October 30, 1997

Leroy:

You need to rebuild the headgate at your diversion point (Kline #37).

Idaho Code 42-701 states in part:

"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this diversion needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,

Lee R. Peterson
Watermaster

cc: IDWR

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WATER DISTRICT NO. 37 & 37 M

P.O. Box T
Shoshone, Idaho 83352
(208) 886-2451

Harold Drussel
152 Baseline Road
Bellevue,, Idaho 83313

Harold:

The water users need to clean the ditch and repair the headgate at your diversion point (Baseline 55-C).

Idaho Code 42-701 states in part:


"The appropriators or users of any public waters of the state of Idaho shall maintain to the satisfaction of the director of the department of water resources suitable headgates and controlling works at the point where their water is diverted. Each device shall be of such construction that it can be locked and kept closed by the watermaster or other officer in charge, and shall also be of such construction as to regulate the flow of water at the diversion point."

Failure to do so may result in the director of water resources instructing the watermaster to shut off and refuse to deliver at the point of diversion, the water owned by such appropriator or user until the user does construct and maintain such headgates, controlling works or measuring devices or remedy the defects which exist.

Repair of this diversion needs to be done prior to the 1998 irrigation season; otherwise we will not deliver any water until repairs are complete.

If we can be of any assistance please feel free to call.

Sincerely,



Lee R. Peterson
Watermaster

cc: IDWR

RECEIVED

OCT 31 1997

Department of Water Resources
Southern Region

October 30, 1997



LEE R. PETERSON
Watermaster