

RECEIVED

FEB 26 2008

WATER RESOURCES
WESTERN REGION

Water master log - 2007

March 1

Talked to Tim noland about getting
more water out of Ben Ross

Told him I didn't think we
could get water from Ben Ross

he has flood water till
Jun 15

March 10 2007

Ben Ross is at 48'

10.0 miles

April 9, 2007

Res level at 51'6"

meeting at Wayne Burkhardt's

ward - Jeager - and me present

12.8 miles

April 14

meeting

29.8 miles

April 20 - 2007

25.5 miles

Res level 53'

Little wieser wiew 2" over

April 29 - 2007

marilyn abraham call - 740 - 0286

no water in ditch?

(1)

MAY 2. 2007

Helped put Boards in spillway at
Ben Ross

15.0 miles

Tom Grassen called no water in
ditch. (Joe Holmes wasn't fixed
headgate yet?)

26.0 miles

MAY 7 2007

Little Wieser wier $4\frac{1}{2}$ over

Res Level at 55'.8"

MAY 8. 2007

36.1 miles

Donart - 4" over wier.

Res Level 56'

MAY 2007

20.3 miles

MAY 14, 2007

22.1 miles

MAY 15, 2007

25.3 miles

6" over wier on little Wieser

MAY 16. 2007

Res is full

21.4 miles

May 19, 2007

26.0 miles

8" over wick on little wieser

May 23, 2007

lots of water down River, 5" over
wick on little wieser.

46.1 miles

Weather is Cool today.

May 25, 2007

28.0 miles

Little wieser wick is 4" over

Have lost 1" in 2 days looks like
a slow down

May 2007

23.8 miles

$3\frac{1}{4}$ " above wick on little wieser

June 1, 2007

13.6 miles

$2\frac{3}{4}$ " over wick on little wieser.

June 3, 2007

437 miles

2" over wick on little wieser

June 5, 2007

41.4 miles

Joe Holmes called yesterday said he
was taking most of River at Groys C
Went down River to Donard Ditch Div.
Lots of water going down River past divers
TALK TO RAYCE about summer water? (3)

JUNE 10 2007
28.0 miles

Weir on Little Wierer = 1" over weir
has dropped $\frac{3}{4}$ " in 2 days, with a lot
of Rain weir is at 1" above top
of weir.

JUNE 13 2007

Everybody seems
to have all the water they can use
more water at the Donald Ditch
than at the Greys Cr. ditch? (in River)
48.7 miles

JUNE 15 2007

48.4 miles

no water in Donald Ditch? no dam?
seems like there is water for everyone
on the lower end. 12" in Wilkerson ditch
water is at 12" in weir on Little Wierer
dropped 1" in 5 days.

JUNE 23 2007

84.8 miles

opened Res yesterday. (not enough).
Jerry Juegar helped me get things in
order. Everybody was out off water
opened Res more changed splitter m
(worked till dark.

Sunday June 24 2007

23.6 miles

Donard Ditch 9" over weir?
Willerson Ditch 12"
dam Headgate 5" from nut
to headwall?

LITTLE Wier Wieser 8"

June 25 2007

Meeting at Burkarts. CUT WATER
TO $\frac{5}{8}$ of every Bodys allotted
amount.

Board voted on THIS
15 miles

Tues June 26, 2007

in former Swink Dean D. TOM
Grossen we were on $\frac{5}{8}$ water
will get the rest later.

Res is shutdown 1 Turn today
Res level is $8\frac{1}{2}$ " below top of
Boards

40 miles

June 27 2007

wieser-wait - $7\frac{3}{4}$

30.0 miles

Richardson - 8"

Lindsay -

Greys Cr. 10"

Steward -

40.2 miles

40.2 miles

Donard Ditch 6"
Allison 14"
Steward - $9\frac{1}{4}$ "
Mortiz - $8\frac{3}{4}$ "

Sat 2007

Little Wieser wick - $5\frac{3}{4}$
10 miles

Mon July 2, 2007

Res Level - $55\frac{1}{2}$ '

opened Res 1 Turn

opened Splitter 3 Turns

Grays Cr. $9\frac{1}{4}$ "

Steward 9"

Mortiz 11"

July wed 4, 2007

Little Wieser wick 6"
16 miles

July 5 - 2007

27 miles

Swink 11"

Allison 2" Shut off?

Donard - Beaver?

Wilker son - 9"
opened Res $1\frac{1}{2}$ Turn

July 7, 2007

SAT opened Res 1 Turn
10 1/2 miles

Sunday July 8 2007
40. miles

LITTLE Wieser Weir - 6"
opened Res 1/2 Turn
Anderson Ditch is full
Swink Ditch is 11" was 13"

wed July 11, 2007

grays 8 1/2"
Mortiz 7 3/4"
Steward 10"
Res 52.10"
opened Res 1 Turn
Richardson 5 1/4"
48 miles

Talked to Ralph Y
Corniel using too much water.
measured grays cr. 9 1/2" over weir
meeting at ward place
15 miles

July 13th 2007

Talked to Joe Holmes about water
20.8 miles

July 14, 2007

Worked on filing and info on water rights

The following is what the board said
the water level would be on all ditches (5/8)

Richardson	-	3.5"
Grays Cr.	-	9.75"
Steward.		8.16"
MORTZ		7.75"
South ogle	-	2.00"
Wilkinson	-	7.50"
allison	-	13.5/16"
Swink	-	10.80"
Donard	-	7.25"
Lindsay	-	5.1/2"

July 15, 2007

Little wieser wter = 5" may be a little less

Richardson - $4\frac{3}{4}$ " at wter.

wter is washed out on south end.

Grays CR.	-	9.0"
Steward	-	9.0"
MORTZ	-	8.1/4"

opened Res 1/2 Turn Res Level 5' 3"?

40.0 miles

July 17, 2007

July 17 2007

Donard - 10"

Closed splitter down anderson ditch
2 Turns shoul Help upper Canal.
Seems To Be a little too much water
down River?

15 miles

July 21, 2007

Weir on Little weiser 4.25"

Grays Cr. 9"

MORTZ - 8"

Steward - $3\frac{1}{2}$ " Seems a little short BUT I
never measured to day.

No water is over Donard dam. Everything
seems OK. Talked to Ralph Yanis water
is OK on Him.

31 miles

July 24 2007

Res Level about 45'

Grays Cr. $8\frac{3}{4}$ "

Little Wieser weir at 4"

16 miles.

July 31, 2007

Grays Cr. 8.5"

opened Res 1 full Turn

Every Body seems OK

25 miles.

Aug 1, 2007

LITTLE wieser	3.25"
Richardson	5"
Steward	9"
MORTZ	7.75"
Swink	11"

Sun Aug 5 2007

Res Level	36'?
MORTZ	7.4"
Steward	8.6"
Grays	8 1/4"

LITTLE wieser Wier 3"

opened Res. 1 Turn

34 miles

Fri Aug 10 2007

Swink	15"
Wilkinson	12"
Steward	7 3/4"
MORTZ	7"
Grays	8 1/4"
LITTLE wieser	3"

39 miles

Sat Aug 11, 2007

STILL MORE WATER ON LOWER END CAN'T
figure where ITS coming from

23 miles

Sunday Aug 12 2007

Still too much water on lower end
will shut Res down some, I don't
like to do that. Can't find the
Reason why there is too much water
on the lower end Shut Res 2 Turns
Shut splitter 4 Turns
13 miles

wed Aug 15 2007

Donard.	6 $\frac{1}{2}$ "
Swing	11 $\frac{3}{4}$ "
Wilkinson	11 $\frac{1}{2}$ "
Allison	6"
Grays cr.	8"

Shut Res down 1 Turn
Shut splitter down 2 Turns
30 miles

Aug 16 2007

open Res 1 Turn
Open splitter 1 Turn
made a mistake yesterday
Grays cr. 7 $\frac{1}{2}$ "
Little Wieser 2 $\frac{5}{8}$

8/22/2007

Yager called too much water on lower end
Turn Res down 1 Turn. (Rain.)

8/24/2007

Rayce said water is fine at his weir.

8/25/2007

Grays Cr. 7"

Closed splitter 1 Turn

Res at 27'

9/1/2007

Swink (water o.k.)

9/2/2007

Res at 14'

Sept 6 2007

Res is about 4ft

Sept 11 2007

Took pictures of diversions on lower
end of Little Wier

Res. is about 1ft

40 miles

Sept 13 2007

Took pictures of 2 more diversions on
Little Wier

Res is the same as dry. about 6"

15 miles

Sept. 20 2007

Joe Holmes took out the dam for
Grays Cr. don't know how they are going
to get stock water.

Talked to Dave Uersera about stock water.

10 miles

SEPT 21 2007

Shut Steward ditch down to about 4" over weir. That is a little more than the 45 inches of water they are supposed to get. Will recheck tomorrow. Helped on office in Indian Valley.

23 miles

OCT 2 2007

Shut Headgate on Res down only stock water going down Anderson Cr.

Little weir weir is at 5"

15 Miles

Joe Holmes & I looked at Grays Cr. Head gate they have been working on looks real good.

Put sprayer away opened gate below dam. Ready for winter.

Water Masters
Signed Merrill J. Steppik