Clayton Fullmer, Water Master
North side Badger Creek diversion near Felt, ID.
4/15/2004 3:57:28 PM

Water Right No(s). _____



GPS DATA:

Tag # NA Location: _____

Diversion Data:

Source: Badger Creek Trib to: Teton River

MOTOR

Make: _____ Model: _____ Hp: _____

SN: _____

PUMP

Make: _____ Model: _____ Disch: _____

SN: _____

NOTES:

_____

_____

_____

_____

_____

Field Exam Date: 04/15/2024 Agent: _____

Water Right No(s). _____



GPS DATA:

Tag # NO TAG Location: _____

Diversion Data:

Source: _____ Trib to: _____

MOTOR

Make: _____ Model: _____ Hp: _____

SN: _____

PUMP

Make: _____ Model: _____ Disch: _____

SN: _____

NOTES:

THIS IS WHERE THE CHANNEL OF BADGER CR IS BLOCKED OF TO FORCE WATER INTO BACK CHANNELS FOR FLOOD IRR'S DURING HIGH WATER

Field Exam Date: _____ Agent: _____

Water Right No(s). _____

County Property
Bull Elk Ck Rd.

GPS DATA:

Tag # No Tag Location: _____

Diversion Data:

Source: Badger Creek Trib to: Teton River

MOTOR

Make: _____ Model: _____ Hp: _____
SN: _____

PUMP

Make: _____ Model: _____ Disch: _____
SN: _____

NOTES:

This photo is of A Back Channel ditch to convey water back into lands between Badger Ck and Bull Elk Ck Road. Blockage of it forces water under the Road to irrig lands on North side ~ 25 ac.

Field Exam Date: 4/15/04 Agent: AJR CF