

# **WATERMASTER'S REPORT**

## **2010 Delivery Records**

See attached pages/log books

WATERMASTER'S REPORT  
ANNUAL WATER RIGHT DELIVERY  
SUMMARY FOR 2010  
DELIVERY TO DIVERSIONS  
(ALL VALUES GIVEN IN 24-HR SECOND FEET)

Diversion Name	TOTAL DIVERTED
ALCOA	0
ALCOB	0
ALC1	0
BCO	0
BCOA	0
BC1	0
BC2	30
BOC1	126.86
Camp Perkins Well #3	26.6
CBC2	0
CCC1	0
CCC2	0
CHC3	125
CHC4/7	744.63
CHC5	131.29
CHC6	752.34
CHC7	0
CLC0	30.37
CLC1	0
Cron Well	0.96
EC1	335.62
EC2	0
FC0	2
FC1	0
FC2	0
FC3	500
FC4	0
FHC0	0
FHC1	0
FJC1	671.9
FJC2	81.02
FJC3	300
GC1	130
GC10	0
GC2	90
GC2A	0
GC3	90
GC3A	0
GC4	185
GC5	44.77
GC5A	7
GC5B	15
GC6	0
GC7	0
GC7A	0
GC7B	83.43
GC7C	0
GC8	300
GC9	500
GOCO	14.79
GOCOA	0

Diversion Name	TOTAL DIVERTED
GOC1	116.86
GOC2	133.11
GOCUT1	0
GW Inflow	0
GW02	0
GW05	115.05
GW06	98.75
GW09	3.35
GW11	0
GW12	0
GW13	0
GW14	0
GW15	3.32
GW16	5.4
GW17	2.02
GW18	0
GW19	0
GW20	*311.8
GW21	*584.3
GW22	*342.5
GW23	1.92
Harrahs Well No. 12	10.17
Harrahs Well No. 13	6.95
Harrahs Well No. 15	0
Harrahs Well No. 17	0
Harrahs Well No. 19	0
Harrahs Well No. 6	0
Harrahs Well No. 7	0
HC1	0
IC0	0
ICOA	0
ICOB	0
IC1	0
IC1A	0
IC2	145.33
IC3	0
IC4	334.49
IC6	25.38
JC1	0
Jerry's Cabins Well	1.41
Jerry's Well	0.1
LJC1	10
LTC0	2.12
LTC1	0
LTC2	0
LTC3	0
LTC4	10.2
Mahoney	15
MCOB	0
MC1	0
MC2A	210.32

Diversion Name	TOTAL DIVERTED
MC2B	100
MC3	200
MGC0	54.4
MGCO	1.41
MGC1	0
NC0	159.25
NC1	0
NewSFH WELL1	0
NewSFH WELL2	0
NewSFH WELL3	0
NewSFH WELL4	0
NTC1	0
Obsidian Spg	2
Obsidian Well	2.07
Other IRMR div.	5.5
Pappa Brunee's Well	5.44
PC0	0
PC1	0
PC1A	0
PC2	0
PC2A	0
PC3	0
PC4	0
PC5	0
PC6	0
PC7	2450
PKC1	136.68
Redfish Resort Well	1.71
RFC2	0
RFL1	0
RothBaur Well	1.46
S38A	1.5
S38B	1.5
S38D	4
S39	1033
S39A	864
S39B	*8166.19
S39E	0
S39E1	0
S40	2213.22
S41	2040.29
S42	1750.67
S43	918.54
S44	0
S45	0
S46	0
S46A	169.04
S46B	0
S46B1	6.65
S46C	0
S47	163.09

Diversion Name	TOTAL DIVERTED
SFH Well #5	0
SLC1	197.55
SMCr01	320.45
SMCr02	0.32
Smiley Creek Lodge Well	2.27
SPG02	8
SPG03	2
SPG04	2
SPG05	2
SPG06	2
SPG07	2
SPG08	0
SPG09	0
SPG1/SRUT7	54.99
SPG10	0
SPG11	0
Stanley Park Well	3.07
Stanley School Well	3.22
Stanley Sewer Well	0
TEC1	16.06
TEC2	18.92
TEC3	0
TPC1	0
UD1	0
UD2	13
UD3	3
UD4	3
UD5	0
UD6	0
UD7	0
VCO	2
VCOA	15
VCOB1	17
VCOB2	3
VC1	393.4
VC3	520.99
VC4	101.27
VCS/6	558.56
VCUT4	18
WCO	29.54
WC1	0
WC2	327.03
WC3	38.26
WCUT3	47
WCUT4	0
West Well	2.4
WMC1	49.8
WMC2	0
WMC3	0
WOHELO GW Well	1.81
WW1	200

\* Volume not included in billing total

\* Volume not included in billing total

WATERMASTER'S REPORT  
ANNUAL WATER RIGHT DELIVERY  
SUMMARY FOR 2010  
DELIVERY TO WATER RIGHTS  
(ALL VALUES GIVEN IN 24-HR SECOND FEET)

WR_num	DiversionName	Total Amount Diverted (CFS)	TOTAL DIVERTED FOR THIS RIGHT
71-10032	Smiley Creek Lodge Well	2.27	2.27
71-10057	Cron Well	0.96	0.96
71-10059	VCUT4	18.00	18.00
71-10080	CHC5	34.92	371.22
71-10080	CHC6	336.30	
71-10081	CHC5	26.39	279.18
71-10081	CHC6	252.79	
71-10103	LTC2	0.00	10.20
71-10103	LTC3	0.00	
71-10103	LTC4	10.20	
71-10104	S39	261.35	261.35
71-10107	SPG08	0.00	200.00
71-10107	SPG09	0.00	
71-10107	SPG10	0.00	
71-10107	SPG11	0.00	
71-10107	WW1	200.00	
71-10110B	GC7C	0.00	0.00
71-10117	S39	0.00	264.38
71-10117	S39A	264.38	
71-10136A	TPC1	0.00	0.00
71-10136B	TPC1	0.00	0.00
71-10144	GC5B	15.00	15.00
71-10144	GC6	0.00	
71-10149	WC0	7.86	124.73
71-10149	WC1	0.00	
71-10149	WC2	86.99	
71-10149	WC3	29.88	
71-10190	GC1	75.27	602.03
71-10190	GC2	52.11	
71-10190	GC2A	0.00	
71-10190	GC3	52.11	
71-10190	GC3A	0.00	
71-10190	GC4	107.12	
71-10190	GC5	25.92	
71-10190	GC7B	0.00	
71-10190	GC8	0.00	
71-10190	GC9	289.50	
71-10197	WCUT4	0.00	0.00
71-10277	CHC5	0.00	0.00
71-10278	CHC5	0.00	0.00
71-10631	S39	0.00	599.62
71-10631	S39A	599.62	
71-10663	S43	648.49	648.49
71-10664	CCC1	0.00	5.50
71-10664	CCC2	0.00	
71-10664	GOC2	0.00	
71-10664	GOCUT1	0.00	
71-10664	Other IRMR div.	5.50	

WR_num	DiversionName	Total Amount Diverted (CFS)	TOTAL DIVERTED FOR THIS RIGHT
71-10665A	BC0A	0.00	0.00
71-10665A	BC1	0.00	
71-10665A	BC2	0.00	
71-10665B	BC0	0.00	0.00
71-10665B	BC1	0.00	
71-10665B	BC2	0.00	
71-10723	CLC1	0.00	0.00
71-10723	NC0	0.00	
71-10723	NC1	0.00	
71-10724	S43	0.00	0.00
71-10726	IC4	0.00	0.00
71-10728	S40	0.00	0.00
71-10729	Redfish Resort Well	1.71	1.71
71-10762	FJC2	40.27	40.27
71-10763	FC3	167.00	285.20
71-10763	FJC3	118.20	
71-10764	S42	264.35	264.35
71-10765	S40	907.42	1070.37
71-10765	WC0	13.50	
71-10765	WC1	0.00	
71-10765	WC2	149.45	
71-10766	S41	0.00	0.00
71-10767	S42	299.36	299.36
71-10768	FJC1	286.90	286.90
71-10772	FJC2	0.00	0.00
71-10773	CBC2	0.00	0.00
71-10774	CCC1	0.00	249.97
71-10774	CCC2	0.00	
71-10774	GOC0A	0.00	
71-10774	GOC1	116.86	
71-10774	GOC2	133.11	
71-10774	GOCUT1	0.00	
71-10852	LJC1	10.00	10.00
71-10853	GC7B	17.85	17.85
71-10854	GC5	0.00	5.50
71-10854	GC5A	5.50	
71-10854	GC6	0.00	
71-10871	S44	0.00	0.00
71-10872	VC4	61.98	61.98
71-10880	SLC1	143.82	143.82
71-10881	VC0B1	17.00	17.00

WATERMASTER'S REPORT  
ANNUAL WATER RIGHT DELIVERY  
SUMMARY FOR 2010  
DELIVERY TO WATER RIGHTS  
(ALL VALUES GIVEN IN 24-HR SECOND FEET)

WR_num	DiversionName	Total Amount Diverted (CFS)	TOTAL DIVERTED FOR THIS RIGHT	WR_num	DiversionName	Total Amount Diverted (CFS)	TOTAL DIVERTED FOR THIS RIGHT							
71-10882	PC0	0.00	2383.85	71-10937	GW20	0.00	0.00							
71-10882	PC1	0.00												
71-10882	PC1A	0.00												
71-10882	PC2	0.00												
71-10882	PC2A	0.00												
71-10882	PC3	0.00												
71-10882	PC4	0.00												
71-10882	PC5	0.00												
71-10882	PC6	0.00												
71-10882	PC7	2383.85												
71-10883	PC0	0.00	66.15	71-11	IC0	0.00	25.29							
71-10883	PC1	0.00												
71-10883	PC1A	0.00												
71-10883	PC2	0.00												
71-10883	PC2A	0.00												
71-10883	PC3	0.00												
71-10883	PC4	0.00												
71-10883	PC5	0.00												
71-10883	PC6	0.00												
71-10883	PC7	66.15												
71-10909	FJC1	0.00	0.00	71-11	IC0A	0.00	63.36							
71-10910	FJC3	0.00	0.00	71-11	IC0B	0.00								
71-10911	FJC2	0.00	0.00	71-11	IC2	25.29								
71-10912	IC0B	0.00	0.00	71-12	IC0	0.00								
71-10913	IC2	0.00	0.00	71-12	IC0A	0.00								
71-10914	CHC3	0.00	0.00	71-12	IC0B	0.00								
71-10915	CHC4/7	0.00	0.00	71-12	IC2	63.36								
71-10916	CHC6	0.00	0.00	71-13	IC0	0.00		50.28						
71-10917	IC6	0.00	0.00	71-13	IC0A	0.00								
71-10918	S47	163.09	163.09	71-13	IC0B	0.00								
71-10919	S46A	163.00	163.00	71-13	IC2	50.28								
71-10920	IC3	0.00	0.00	71-14	MC2B	21.90	65.70							
71-10921	S46A	6.04	6.04	71-14	MC3	43.80								
71-10926	Mahoney	15.00	15.00	71-15	MC2B	43.80			131.40					
71-10929	LTC1	0.00	0.00	71-15	MC3	87.60								
71-10930	BOC1	113.29	113.29	71-16	GC7B	0.00				39.60				
71-10931	BOC1	13.57	13.57	71-16	GC8	39.60								
71-10934	GW20	0.00	0.00	71-16	GC9	0.00								
71-10934	GW21	0.00												
71-10934	GW22	0.00												
71-10934	NewSFH WELL1	0.00												
71-10934	NewSFH WELL2	0.00												
71-10934	NewSFH WELL3	0.00												
71-10934	NewSFH WELL4	0.00												
71-10934	SFH Well #5	0.00												
71-10936	GW23	1.92		1.92	71-17	MC2B	6.80	20.40						
					71-17	MC3	13.60							
				71-18	MC2B	27.50	82.50							
				71-18	MC3	55.00								
				71-19A	GC7B	0.00			43.50					
				71-19A	GC8	43.50								
				71-19A	GC9	0.00								
				71-19B	GC7B	1.17				2.07				
				71-19B	GC8	0.90								
				71-2004A	S42	8.75					8.75			
				71-2004B	S42	3.50		3.50						
				71-2004C	FJC1	151.85						151.85		
				71-2004D	FJC2	0.49	0.49							
				71-2004E	FJC1	11.42							11.42	
				71-2014	FJC2	40.27			40.27					
				71-2015	CLC1	0.00								102.40
				71-2015	NC0	102.40								
				71-2015	NC1	0.00								
				71-2016	S40	177.06				208.79				
				71-2016	WC0	2.63								
				71-2016	WC1	0.00								
				71-2016	WC2	29.11								

WATERMASTER'S REPORT  
ANNUAL WATER RIGHT DELIVERY  
SUMMARY FOR 2010  
DELIVERY TO WATER RIGHTS  
(ALL VALUES GIVEN IN 24-HR SECOND FEET)

WR_num	DiversionName	Total Amount Diverted (CFS)	TOTAL DIVERTED FOR THIS RIGHT
71-2026	CHC5	9.85	9.85
71-2047B	CHC4/7	244.98	244.98
71-2047B	CHC7	0.00	
71-2052	WC0	2.22	
71-2052	WC1	0.00	
71-2052	WC2	24.53	35.12
71-2052	WC3	8.38	
71-2053A	UD1	0.00	0.00
71-2053B	S40	223.54	
71-2053B	WC0	3.34	
71-2053B	WC1	0.00	263.83
71-2053B	WC2	36.95	
71-2054	CHC4/7	288.92	288.92
71-2054	CHC7	0.00	
71-2063	S41	118.34	
71-2063	S42	147.06	265.39
71-2077A	CHC3	125.00	125.00
71-2077B	WMC1	49.80	49.80
71-2078	WMC2	0.00	0.00
71-2078	WMC3	0.00	
71-2079	S43	270.05	270.05
71-2081	NTC1	0.00	0.00
71-2082	S41	181.59	181.59
71-2084A	SLC1	17.58	17.58
71-2084B	SLC1	6.52	6.52
71-2085B	S42	190.82	190.82
71-2088	S39B	0.00	0.00
71-2091C	BC0A	0.00	0.00
71-2091D	BC0	0.00	0.00
71-2091E	SMCr02	0.32	0.32
71-20A	GC7B	0.00	
71-20A	GC8	72.00	72.00
71-20A	GC9	0.00	
71-20B	GC7B	2.42	
71-20B	GC8	2.10	4.52
71-2102A	JC1	0.00	
71-2102A	LJC1	0.00	0.00
71-2111	S39	231.39	231.39
71-21A	GC7B	0.00	
71-21A	GC8	115.20	115.20
71-21A	GC9	0.00	
71-21B	GC7B	4.76	
71-21B	GC8	3.90	8.66
71-22A	GC7	0.00	0.00
71-22B	GC7B	11.93	11.93
71-25B	IC6	25.38	25.38
71-26A	IC1	0.00	0.00

WR_num	DiversionName	Total Amount Diverted (CFS)	TOTAL DIVERTED FOR THIS RIGHT
71-26B	IC0	0.00	
71-26B	IC0B	0.00	
71-26B	IC1	0.00	
71-26B	IC1A	0.00	
71-26B	IC3	0.00	133.13
71-26B	IC4	133.13	
71-26C	IC1	0.00	
71-26C	IC1A	0.00	0.00
71-27A	IC1	0.00	0.00
71-27B	IC0	0.00	
71-27B	IC0B	0.00	
71-27B	IC1	0.00	
71-27B	IC1A	0.00	201.36
71-27B	IC3	0.00	
71-27B	IC4	201.36	
71-28	FC3	140.00	140.00
71-29	FC3	75.00	75.00
71-30B	FC1	0.00	0.00
71-30B	FC2	0.00	
71-30C	FC3	43.50	43.50
71-30D	FC0	2.00	2.00
71-31B	FC3	23.50	23.50
71-31C	FC1	0.00	
71-31C	FC2	0.00	0.00
71-33A	FJC3	5.40	5.40
71-33B	FJC3	1.20	1.20
71-33C	FJC3	12.00	12.00
71-33E	FJC3	2.70	2.70
71-34A	FJC3	9.90	9.90
71-34B	FJC3	6.00	6.00
71-34C	FJC3	2.70	2.70
71-34D	FJC3	5.10	5.10
71-34E	FJC3	7.20	7.20
71-34F	FJC3	1.50	1.50
71-34G	FJC3	2.70	2.70
71-35A	FJC3	70.50	70.50
71-36A	FJC1	108.85	108.85
71-36C	FJC3	19.20	19.20
71-37B		0.00	
71-37B	FC3	51.00	
71-37B	FC4	0.00	
71-37B	FJC3	35.70	86.70
71-37C		0.00	
71-37C	FC1	0.00	
71-37C	FC2	0.00	
71-37C	FC4	0.00	0.00
71-37C	FJC3	0.00	
71-39A	MGC0	40.31	40.31
71-39D	MGC1	0.00	0.00

WATERMASTER'S REPORT  
ANNUAL WATER RIGHT DELIVERY  
SUMMARY FOR 2010  
DELIVERY TO WATER RIGHTS  
(ALL VALUES GIVEN IN 24-HR SECOND FEET)

WR_num	DiversionName	Total Amount Diverted (CFS)	TOTAL DIVERTED FOR THIS RIGHT
71-39E	MGC0	1.41	1.41
71-39G	MGC0	14.09	14.09
71-39H	MGC1	0.00	0.00
71-4000	SPG03	2.00	10.00
71-4000	SPG04	2.00	
71-4000	SPG05	2.00	
71-4000	SPG06	2.00	
71-4000	SPG07	2.00	
71-4006	CHC5	17.07	
71-4006	CHC6	163.26	
71-4012	S38A	1.50	3.00
71-4012	S38B	1.50	
71-4013	GW17	2.02	2.02
71-4014	GOC0	14.79	14.79
71-4015	SPG1/SRUT7	38.93	38.93
71-4016	S41	1083.39	1083.39
71-4018	CHC4/7	210.73	210.73
71-4018	CHC7	0.00	
71-4021	CHC5	43.06	43.06
71-4022	GC7B	11.93	11.93
71-4023	BC2	30.00	30.00
71-4025	S39E	0.00	0.00
71-4025	S39E1	0.00	
71-4026	SPG1/SRUT7	16.06	16.06
71-4028	SPG02	8.00	8.00
71-4030	RFL1	0.00	0.00
71-4033	S39	458.65	458.65
71-4034	WCUT3	47.00	47.00
71-4035	UD2	13.00	13.00
71-4036A	UD5	0.00	0.00
71-4036A	UD6	0.00	
71-4036A	UD7	0.00	
71-4037	S41	656.97	1467.53
71-4037	S42	810.56	
71-4038	S40	832.17	832.17
71-4039	CLC0	30.37	30.37
71-4044	GW15	1.26	3.31
71-4044	GW16	2.05	
71-4045	RothBaur Well	1.46	1.46
71-4047	Jerry's Cabins Well	1.41	1.41
71-4048	Obsidian Well	2.07	2.07
71-4049	Obsidian Spg	2.00	2.00
71-4050	UD3	3.00	6.00
71-4050	UD4	3.00	
71-4051	CLC1	0.00	56.85
71-4051	NC0	56.85	
71-4051	NC1	0.00	
71-4052	FJC1	57.78	57.78

WR_num	DiversionName	Total Amount Diverted (CFS)	TOTAL DIVERTED FOR THIS RIGHT
71-4053	GC7B	27.45	50.25
71-4053	GC8	22.80	
71-4055B	GC5	0.00	1.50
71-4055B	GC5A	1.50	
71-4055B	GC6	0.00	
71-40A	VC5/6	49.15	49.15
71-40D	VC5/6	19.55	19.55
71-40E	VC5/6	44.68	44.68
71-40G	VC5/6	17.32	17.32
71-40H	VC5/6	0.00	0.00
71-41	HC1	0.00	0.00
71-41	VC5/6	0.00	
71-42A	VC5/6	131.82	131.82
71-42B	VC5/6	0.00	0.00
71-43A	VC5/6	24.58	24.58
71-43B	VC5/6	0.00	0.00
71-44	EC1	228.56	228.56
71-44B	EC1	23.16	23.16
71-45	VC5/6	123.44	123.44
71-46	EC1	83.91	83.91
71-47	VC5/6	148.02	148.02
71-48	EC2	0.00	0.00
71-49B	VC5/6	0.00	0.00
71-4B	MC0B	0.00	49.85
71-4B	MC1	0.00	
71-4B	MC2A	49.85	
71-5	MC0B	0.00	160.47
71-5	MC1	0.00	
71-5	MC2A	160.47	
71-50	VC5/6	0.00	0.00
71-51	TEC1	16.06	34.98
71-51	TEC2	18.92	
71-51	TEC3	0.00	
71-52	VC3	130.25	130.25
71-52	VC5/6	0.00	
71-53	PKC1	136.68	136.68
71-54	VC3	130.25	130.25
71-55	VC1	179.00	179.00
71-57	VC3	260.50	260.50
71-58	VC1	214.40	214.40
71-59	S45	0.00	0.00
71-59	S46	0.00	

WATERMASTER'S REPORT  
ANNUAL WATER RIGHT DELIVERY  
SUMMARY FOR 2010  
DELIVERY TO WATER RIGHTS  
(ALL VALUES GIVEN IN 24-HR SECOND FEET)

WR_num	DiversionName	Total Amount Diverted (CFS)	TOTAL DIVERTED FOR THIS RIGHT
71-6	GC1	27.37	218.87
71-6	GC2	18.95	
71-6	GC2A	0.00	
71-6	GC3	18.95	
71-6	GC3A	0.00	
71-6	GC4	38.94	
71-6	GC5	9.42	
71-6	GC7B	0.00	
71-6	GC8	0.00	
71-6	GC9	105.25	
71-60B	SMC01	320.45	320.45
71-60C	S46B1	1.75	1.75
71-60C	S46C	0.00	0.00
71-61	S45	0.00	
71-61	S46	0.00	
71-62C	S46B1	4.90	4.90
71-62C	S46C	0.00	0.00
71-64A	ALC0A	0.00	
71-64A	ALC0B	0.00	
71-64A	GW11	0.00	
71-64A	GW12	0.00	
71-64A	GW13	0.00	
71-64A	GW14	0.00	
71-64B	ALC1	0.00	0.00
71-66	ALC1	0.00	0.00
71-68	ALC1	0.00	0.00
71-69	ALC0A	0.00	0.00
71-69	ALC0B	0.00	
71-69	GW11	0.00	
71-69	GW12	0.00	
71-69	GW13	0.00	
71-69	GW14	0.00	
71-7	GC1	27.37	218.87
71-7	GC2	18.95	
71-7	GC2A	0.00	
71-7	GC3	18.95	
71-7	GC3A	0.00	
71-7	GC4	38.94	
71-7	GC5	9.42	
71-7	GC7B	0.00	
71-7	GC8	0.00	
71-7	GC9	105.25	
71-7002	UD1	0.00	0.00
71-7008	BC0A	0.00	0.00
71-7009	S46B	0.00	0.00
71-7010	GW15	0.80	2.09
71-7010	GW16	1.30	
71-7011	WOHELO GW Well	0.91	0.91

WR_num	DiversionName	Total Amount Diverted (CFS)	TOTAL DIVERTED FOR THIS RIGHT
71-7016	VC0A	15.00	15.00
71-7020	SLC1	11.26	11.26
71-7023	SLC1	1.58	1.58
71-7027	S38D	4.00	4.00
71-7028	Stanley School Well	3.22	3.22
71-7037	Pappa Brunees Well	5.44	5.44
71-7038	Stanley Park Well	3.07	3.07
71-7052	FHC1	0.00	0.00
71-7057	RFC2	0.00	0.00
71-7063	GC10	0.00	0.00
71-7063	GC7A	0.00	
71-7063	GC7C	0.00	
71-7075	WOHELO GW Well	0.91	0.91
71-7079	S39B	0.00	0.00
71-7083	GW18	0.00	0.00
71-7084	GC7B	5.92	5.92
71-7092	GW19	0.00	0.00
71-7102A	SLC1	5.53	5.53
71-7104	GW05	115.05	115.05
71-7105	SLC1	4.74	4.74
71-7108	Harrahs Well No. 13	6.95	6.95
71-7108	Harrahs Well No. 15	0.00	
71-7108	Harrahs Well No. 6	0.00	
71-7108	Harrahs Well No. 7	0.00	7.16
71-7109	Harrahs Well No. 12	7.16	
71-7109	Harrahs Well No. 17	0.00	
71-7113	West Well	2.40	2.40
71-7117	SLC1	6.52	6.52
71-7124	VC0B2	3.00	3.00
71-7128B	FHC0	0.00	0.00
71-7129	GW02	0.00	0.00
71-7132	Jerry's Well	0.10	0.10
71-7139	VC0	2.00	2.00
71-7143	Harrahs Well No. 12	3.01	3.01
71-7143	Harrahs Well No. 17	0.00	
71-7143	Harrahs Well No. 19	0.00	
71-7144	GW15	1.26	3.31
71-7144	GW16	2.05	
71-7147	EC1	0.00	0.00
71-7148	VC5/6	0.00	0.00
71-7149	S41	0.00	0.00
71-7150	S40	0.00	0.00
71-7151	S46	0.00	0.00
71-7153	S43	0.00	0.00
71-7154	S42	0.00	0.00
71-7156	VC4	0.00	0.00
71-7157	VC3	0.00	0.00
71-7159	VC1	0.00	0.00

WATERMASTER'S REPORT  
 ANNUAL WATER RIGHT DELIVERY  
 SUMMARY FOR 2010  
 DELIVERY TO WATER RIGHTS  
 (ALL VALUES GIVEN IN 24-HR SECOND FEET)

WR_num	DiversionName	Total Amount Diverted (CFS)	TOTAL DIVERTED FOR THIS RIGHT
71-7160	PC7	0.00	0.00
71-7161	S47	0.00	0.00
71-7162	S39	0.00	0.00
71-7163	S39A	0.00	0.00
71-7169	GW06	98.75	98.75
71-7170	S42	26.26	26.26
71-7173	Camp Perkins Well #3	26.60	26.60
71-7178	LTC0	2.12	2.12
71-7179	GW Inflow	0.00	3.35
71-7179	GW09	3.35	
71-7179	LTC0	0.00	
71-7181	Stanley Sewer Permit location	0.00	0.00