

Water District

45A

Water Master's

Report

2010

RECEIVED

MAR 15 2011

DEPT. OF WATER RESOURCES
SOUTHERN REGION

3rd mill 10.00
March 3rd Am

Ball Fairchild

Hawkins

60 in

March 3rd

140 inches

Cranny 5

Bill W. & Robinson

May 4th

went to Basin

Garth loaded Rock

To put in washout

mill cr

Excavator Broke Down

May 5th

Canth working
on weirs & cleaning
out so we can measure
water

May 6th

Canth finished day

Sat May 8th

Cranney's Station
off water so cold
not enough to run
1 wheel line

Monday 10th

went to alms Brandied
calves Wade 2 Hinger
ordered water
Started to rain

Tues 11th

Rained all night
wade canceled water
order for now

Wed 13th

water running down
cr about 50 in

Thurs 13 May

Ryan Hawker

Summit cr

Turned on

Engine Matthews

Running one Pilot

Cranneys

80-100 inches

BW Place

May 17th

Summit cr. 120 in

18th

Can't over measure in
Cranney or Bill well

54 in Warm Springs

19th

Turned water to meet

Turkosen 8:00

Turned water to Ryan

Hawker 8:00

21st 1st mill nail in for
Warm Springs

Turned 255

21st

Turned on Wade
Zollinger

23rd Turned on
Ryan Hawker Summister

24th

Pulled weir out of
Craig Smith water
selling under house

turned water to Rambo's

Turned off worn
Neil Justesen Springs
30th

Turned some water to
Neil Justesen
out of Mill creek
ditch & cleaned at
weeds above Bruce
Mitchell's House

Warm 29th
Springs May
54 inches

Turned on
Neil Just 507

549 going mill

219 Springs ^{under}
T60

Water Broke out
into crannys corr.
Could get that shut
off crannys
Mexican Boys washed
out Div. Pond not
letting it go by

checked Ditch
with washaking

Sat Night over
the well to Bruce's
House

& Craig & I went
& turned some to

TV Smith & He had

water under his
House Pulled a wire
out of ditch so it
would take more
Down main Ditch

today lots of
water Had to
wade creek
to get to Headgate
Miller Ice cold
water way over top
of Weir & Headgate

Slowed Down ^{7th} June
Spring or Feeder

^{8th}
Put more water
into Summit or
its Dropped off a
Little But will

Come Back some
^{9th}

Some body had put
tin in ditch and shut
off Hawkers Pond
Water ^{10th}

got some water
going to Hawkers
cows

water still lower
weirs & Running over
Ditches

11th - Still water running
High sanding steady
to Neil Justinson
Wade Pivot is stuck

12 crannys off Except
for Pivots on Robinson

13th crannys off
Except for Pivots on Robinson

14th crannys
off Except for Pivots
on Robinsons

15th

Water still high
But is going down
More people using
water now

crannys shut
off for three days
& now on & water
corn Ryan Screen
Plugged & sanded shot
need culvert down
Ray Wells House

24th June
Turned water
To Craig Smith

July 3rd

11:55

turned Eugene off

1st Spring 12:10

Turned on Craig Smith

July 4th

Bruce Bealke on

Wade Zollinger

off

Tom Gorringer on

TR ^{Rev} Smith off

Springer

July

3rd mill

6th

turned on

James Bedke

300 PM

6:00 PM

Turned off Bruce

2nd spring Bedke

turned on Harold

6:00 PM

Tom Goringe

off

Ernest Matthews

1st Spring 6th

turned off Summit

Gr. Frecker

7th July

1st mill

Turned on C Hawke

8:00 AM

Turned off

8:1 AM

St. S. Pearson

off Craig Hunter

on Basil Farchild

Samuel Wells

Turned off James Bedke

Wells Ray on Summit

& Bruce OFF

2nd mill 9th

Turned on C Hawke

turned off Bruce Bedke

2nd mill

July 10th

Turned Wade on
a little bit early
today

11th

Monday 12th

Turned off Basil
Craig Smith on
turned Eugene off
Bruce Redbe on
Turned off Wade 1st

Spring

Craig Smith off
14th

on sd until 2:00 PM

Gerald Marchant

Kevin Smith on 6:00 PM

Gates are locked

turned off bus & turned

on Rex Martin 6:00 PM

15th

turned on Tom Corrigan

& off for Kevin Smith

& got Darned Bedke

turned on Late Headgate

washed out

16th

Gene Matthews on

tom off Springer

17th

6 PM

wade Zollinger no water

Crannys now

Haying

Rex Left water in

Martin Ditch

1st mill Hawkler

on 8:00 AM

Shift off Spearin

18th

42° Warm Spring

Turned water

to Neil Justesen

18th

Turned water
To Neil J. Josteson

8:00 AM

Turned off

Bruce 2nd mill

Changed Hawk
From First to Second
mill

19th Jason Hale

called said He never
got water so I will

Ditch Soaking
into Ditch

2nd Spring AM

Bruce 2nd mill

turned off Rex Man

Had whole's water

Because New was

Haying

2nd mill Basil

Sainschuld

turned off Neil J. Josteson

Turned on Wade

Rolling in 36 in

1st mill

I Also turned off
water at Harper Place

They Have Run
Water Steady
Since April

15 or 20 in

8 AM 2nd mill
Turned off Basil F
Turned on
Gerald Marchant
2nd mill
July 21st

22nd

Turned off
Engen Matthews
Spring & turned

on Craig Smith
upper Ditch
5:00 AM

Turned off Bruce
Becker 2nd Spring
& turned on Hog
2nd Spring Martin
6:00 PM

23rd 12:00

Turned Craig Smith
off & Kevin Smith on

24th turned
off Kevin Smith
& turned on 12:00 PM
Tom Goring

Wade was just ahead
of me & He had turned
on Gerald Marchant's
water onto His own
Pivot at noon

Derald called at 5 to 6:00
Wade had taken His water

Summit

turned Hawker
on 7:00 PM
Jeff off

25th

Tom Goring
off 12 noon
Eugene on 12:00 noon

26th no Tarnes

27th

Craig Hawker on
soon - in off

Craig 7:00 AM on
Ginger off 7:00 AM

25th

Turn off Wade

7

Turn on Brace

Bealke

~~2nd~~

Spring 6:00 AM

29th

Bealke off

CHawker off

on 8:00 AM

30th

Gerald mauler

Bealchill off

1st mill

Wade

I went to Turn

Wade on

at 5:30 it was

already turned

on 5:45 is on

Time

This turn

Ret martin on

6:00 PM & Brace off

2nd Spring

Aug 1st

Turned Kevin
Water Smith

Shut off Craig
Water Smith

Aug 2nd

Turned on Wade 2
6:00pm into Tom's house

Turned off RX Martin

1st Spring Tom Corring

Turned off Kevin
7:00 PM Smith

1st Spring

Aug 3rd

Eugene Matthews
7 PM

Turned off Tom Corring
7 PM

Turned off Harper
again

Ryan made changes
The 5th

Aug 5th

2nd Spring

Bruce Bedke 6:00 AM

Turn off Zollinger

Craig Hawker 2nd mill
7:00 AM

6th
Augth 2nd mill
Craig on
Scott Spearin off

7th Aug Neil Jastesen
8:00 am
Craig off
Basil on 2nd mill 7:00 AM
Hawthorn off
2nd Spring
Rex Martin 6:00 pm
B. Berke off - 6:00 pm

8th Aug

Gerald Marchant
8:00 AM
Basil turned off

9th

1st m TI Wade
Hawthorn off 5:45
7:00 pm Craig on
Eugene off

10th Turned water on 6:00 pm

RX Martin off
Kevin on 5:00 AM
Craig off 5:00 AM

12th

Tom Goring 5 AM

Kevin Smith 5:00 AM

13th

Turned wade

off Goring off

Eugene 1st Spring

Aug 14th

2nd mill Craig on

Summitter Craig on
11:00 PM

turned off Jeff

15th

2nd Spring R Martin

6:00 PM

Turn Bruce off

2nd mill off

16th Basil 7:00 AM

2nd mill off & Hawker

1st mill on Hawker

Screen off 1st mill

17th aug

Turned on Neil J

Turned Craig off

19th

Turned on Craig Smith
& turned off Eugene

Spring 1st Mill 545
Wade was on when I got

Turned off Neil J

Wade was on when I got

20th Have

Turned Craig Smith
at noon,

Turned Kern Smith on

21st

4:00 pm
Tom Gorringer on 12:00

Turned off Herin Smith
2nd Spring

Bruce Beal on 6:00 am

Wade Zollinger off

22nd

Eugene Matthews 12 PM

23rd RX Martin on

Bruce off

Craig Hawker on 7:00 am

Bruce off

24th Summiter

Craig Hawker on

Jeff off

25th

Basil on

Hawker off

26th 1st mill

Craig on 8:00 AM

Sorearin off

Marchant on

Basil off

2nd Spring Zollinger on

Martin off

27th 8:00 AM
on Neil Justesen
off Craig Hawker

28th 12
on Craig Smith noon
Eugene Matthews
B

29th 2nd Spring
Bruce Bedke on
Wade 2 off 8 AM
Neil Justesen off
Wade on 1st mill
Turned on early
5:25

Craig off
8 Kevin on 7:00 PM

~~30th Kevin off~~

Tom Gorringer
Turned water
Down creek

31st Eugene Matthews
7 PM on
Tom Gorringer off
Ray Martin
6:00 PM on
Bruce Bedke off

1st on 7:Am

Craig Hawker

Bruce off

2nd not on

3rd Wade 2^{am} 6:00 PM

Bruce off

Basil on

Hawker off

4th Sept

Closed Hawker

Head Gate on

mill or Dry

A Trickle at Harper place

Wade worth Trough
over Flow Plugged

solid

Terry merchant

Trough tipped over
no water getting

to over Flow

Screen in main pipe

Gelling Plugged

no water at

Terry's Headgate

on Hawkers

about all water

going down pipe

5th

Craig Hawker

Ryan turned on for me

Craig Smith Turned

off Spearin To move

~~to not touch~~

Neil Water

2nd

Went Aroch till

End of town Ditch

Soaks it up

Left town

~~to not touch~~

8th

Ray martin on

Bruce off

Wade on 5.45

9th

Checked down
Wade Water Finn

Ann Wade Tom Goring
on Roving Water

10th

Spearin
Craig Hawker on

Bruce off

Engine on Tom's off

11th

Spring creek

Hado Wade make the
Train His on Rex off

Warm Springs
Cleaned water
cross out of
Ditch & weir

30th Warm Spring
Headgate at Craig
Smith House
Cranked wide open
again same last
week

Hub Wade turned his
water 1st spring
this evening as
I was fencing

12th

Basil on
Craig off
same Headgate
Solpel

5:00 AM
13th Turned Basil off
Marchant on

14th

Told Gerald

Marchant

A Lot of water

Goes By Weir

Leak's

Also Told Bruce

Bedke

Leaking Weir

By His House

18th Sunday

2nd Mill
Bruce Bedke
turnoff 7Am

Neil Japison
on 8Am

Craig Hawken

19th Mon

Latin Fence
 20 Posts 7.00 Ea 140.00
 48 Rds 384.00
 25 Per Post Brace 5.00
 Cross Sticks 24.00 1024.00
 24
 Barb wire 100.00 1048.00
 100.00
 1148.00

Neil Justesen
 off 8 AM
 Turn on Bruce B
 6 AM 2nd spring
 2nd Basil Ranch
 Turn off Harper 1145 AM