

Spring Creek Feeder - Good Condition!

DEC 2 4 2015

DEPT OF WATER RESOURCES
SOUTHERN REGION

Summit Creek Feeder - Weir is in good condition. Willows and ditch garbage need cleaned out bad!

Harper – Weir is in good condition. Head gate leaks turning water down ditch.

Hawker – Weir is in good condition. Willows, weeds, and ditch garbage need cleaned out bad!

Marchant/Bedke – Marchant/Bedke head gate NEEDS fixed/replaced so water will shut off all the way. The north and west side of the weir needs cleaned out badly. Ditch garbage is clogging back the water.

Jared Bedke - Needs weir.

4 Mill Gap - Creek needs cleaned out due to dirt build up.

Spring Creek Matthews – Weir leaks on sides.

2 Spring – Things are good. Need better boards/tarp to help shut off water for other user's turns.

Summit – Channel for water to go to K & Jeff needs to be cleaned out of dirt and mud build up. I don't do a lot on this creek, everyone turns their own water. Got a couple of measurements, but will try harder next season.

Weirs are in good shape. I will propose to the Board of Directors this year to have chain and padlocks for all head gates, this will cut down on water thieves immensely. Also proposing to Board, to burn ditches, head gates and clean out ditch garbage such as grass and overgrown willows. Also propose – the water users that irrigate out of those creeks need to be responsible to help burn ditches and man the fire. We also need to ask the Oakley Volunteer Fire Dept. to help on these days to keep fire from raging out of control.

Thanks

Danielle Bedke-Helms

208-312-8048

WD 45A - Basin Water District Year End Report 2015

	Α	В	С	D	E	F	G	Н	_	J	K	L
1			Ī			1						
2	LAST NAME	FIRST NAME	DIVERSION	APRIL	MAY/Flood	JUNE/Flood	JUNE/Turns 6/18	JULY	AUG	SEPT	ОСТ	TOTAL AC-FT
3	Harper	Jay	1 Mill	***	Flood	Flood	***	***	***	***	***	***
4	Fairchild	Rose	1 Mill	***	Flood	Flood	***	***	***	***	***	***
5	Bowers	Bart	1 Mill	7.14	Flood	Flood	2.44	6.96	1.26	0.9	0.0	18.7
6	Marchant	Gerald	1 Mill	8.6	Flood	Flood	7.9	5.96	1.26	0.9	0.0	24.62
7	Larson	Seth	1 Mill	6.2	Flood	Flood	0.0	7.1	1.26	0.9	0.0	15.46
8	Hawker	Craig	1 Mill	2.36	Flood	Flood	0.0	7.34	0.0	0.0	0.0	9.7
9	Justessen	Neil	1 Mill	11.18	Flood	Flood	0.0	0.0	0.0	0.0	0.0	11.18
10												
11	Hawker	Craig	2 Mill	6.72	Flood	Flood	0.88	9.08	0.0	0.0	0.0	16.68
12	Fairchild	Basil	2 Mill	7.88	Flood	Flood	0.0	5.24	0.0	0.0	0.0	13.12
13	Marchant	Gerald	2 Mill	6.58	Flood	Flood	12	11.98	0.0	0.0	0.0	30.56
14	Bedke	Bruce	2 Mill	4.06	Flood	Flood	9	8	0.0	0.0	0.0	21.06
15												
16	Fairchild	Basil	3 Mill	14.96	Flood	Flood	4.78	0.0	0.0	0.0	0.0	19.74
17	Hawker	Craig	3 Mill	7.5	Flood	Flood	0.0	0.0	0.0	0.0	0.0	7.5
18	Bedke	Jared	3 Mill	1.4	Flood	Flood	4.74	11.4	0.0	0.0	0.0	17.54
19	Marchant	Gerald	3 Mill	0.0	Flood	Flood	0.0	0.0	0.0	0.0	0.0	0.0
20	Wells		4 Mill	***	***	***	***	***	***	***	***	***
21	Duncan		4 Mill	***	***	***	***	***	***	***	***	***
22												
23	Smith	Craig	1 Spring	8.04	Flood	Flood	4.2	7.44	1.68	0.0	0.0	21.36
24	Justessen	Neil	1 Spring	14.38	Flood	Flood	4.2	3.4	1.76	0.0	0.0	23.74
25	Gorringe	Tom	1 Spring	0.0	Flood	Flood	0.0	0.0	1.52	0.0	0.0	1.5
26	Matthews	Eugene	1 Spring	12.04	Flood	Flood	10.72	17.94	5.04	0.0	0.0	45.74
27												1277
28	Martin	Rex	2 Spring	21.58	Flood	Flood	11.52	13.98	3.84	0.0	0.0	50.92
29	Zollinger	Wade	2 Spring	14.04	Flood	Flood	2.4	10	3.4	0.0	0.0	29.84
30	Bedke	Bruce	2 Spring	10.78	Flood	Flood	15	10.44	2.16	0.0	0.0	38.38
31							_					
32	Wadsworth	Jeff	Summit	0.0	Flood	Flood	Flood	5.37	3.45	3.45	0.0	12.3
33	Hawker	Craig	Summit	4.5	Flood	Flood	Flood	19.8	12.74	12.74	12.7	62.52
34	Bedke	Bruce	Summit	0.58	Flood	Flood	Flood	3.42	2.21	2.21	0.0	8.42
35	Wells	George K	Summit	***	Flood	Flood	Flood	29.79	21.43	17.25	5.75	74.22
36	36 Total Water 2015			170.52			89.78	194.64	63.01			574.79

DEC 2 4 2015

DEC 2 4 2015

DEPT OF WATER RESOURCES
SOUTHERN REGION