WATERMASTER'S ANNUAL REPORT

From: June 27th	, 20_24	To: January 29th	, 20_25
			RECEIVED
Water District No. 13T	- 4		JAN 3 0 2025
Water District Name: Bancroft Lui	nd Area	er I	DEPT. OF WATER RESOURCES EASTERN REGION
Name of Watermaster: Kaid Panek			
Mailing Address: PO Box 99 Soda	a Springs, Idaho	83276	(9)
		II .	
- 1	AFFIDAVIT OF	WATERMASTER	
1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -			
As the appointed watermaster of water di	istrict no. 13T	, I hereby certify that the	information contained in this
		± V	
report is true and correct to the best of m	y knowledge.		
			T is
1000	01	1/29/2025	
Watermaster signature	Da	nte de la compa	
			19
Pursuant to Section 42-606 Idaho Code,	thic Watermaster's	Annual Report shall be filed n	rior to the end of the
watermaster's appointment for the curren			
(IDWR). The Watermaster's Daily Dive	-		
electronically to IDWR.	- SION TROUBLE SHOW	To be seemed to mile report in	
TITLINGIAN OF THE TITLING			1,



Water Master Annual Report 2025

DEPT. OF WATER RESOURCES EASTERN REGION

To Whom It May Concern:

The 2024 water year was a year of learning and inventory.

Initial inventory has happened on 71 Points of Diversion across the water district.

It was surveyed that most are absent of water meters, and if they do possess a measuring device it has evidence of malfunction or improper installation. Water users are encouraged to update the measurement device on their system as the IDWR is expected to make this a requirement in the near future.

All approved devices can be found at:

https://idwr.idaho.gov/wp-content/uploads/sites/2/water-measurement/Approved-flow-meter-list-v4.1 7 1 2024.pdf

Out of the 71 surveyed sites, there were 2 unable to be located, sites 261295 and 336580

Most points of diversions meet the requirement of our jurisdiction, but we are seeking clarification on minor sites that could fall under the domestic/ culinary well criteria.

Budget wise, the WD13T has sufficient funds going into 2025, which I suggest we adopt the same budget outline used in Fiscal Year 2024. This will ensure that we can operate within the requirements and expectations of the IDWR. Until the measurement device requirements are set, we will look to distribute assessments according to water rights rather than water usage.

In 2025 we look forward to a year of learning and progressing as a water district with the help and guidance of the IDWR.

Respectfully,

Kaid Panek

Water Master WD13T

Spatial DataiD	Water Right Number	OwnerList	WaterUseList	Priority Date	Diversion Rate (cfs)	Total	Acre Limit	Diversion Volume (acre-feet)	WM Site Visit Comments
255000	29-2537	RIGBY, BONNIE K; RIGBY, MAX D	IRRIGATION	10/9/1966	1.9	107	95	285	No meter present. Gas powered
256009	29-2557	•		CONTRACTOR SALE	0.24	107		42	pump, not near power lines
256009	29-10247	RIGBY, BONNIE K, RIGBY, MAX D	IRRIGATION	4/1/1987 11/20/1969	0.24 4.68	800	477	1432.4	No meter or metal tag present
256146	29-7041	WISTISEN LIVESTOCK CORP	IRRIGATION, STOCKWATER	245,000 (155,000)	4.68	800	324	972	No meter of metal tag present
256146	29-7305	WISTISEN LIVESTOCK CORP	IRRIGATION	2/2/1976	4.08	800	324	372	No tag, no meter, located at base of
256631	29-2347	ELIASON & SONS INC	IRRIGATION	6/12/1954	1.2	122	95	285	pivot with a junction that feeds to the north
256631	29-14317	YOST & YOST FARMS LLC	IRRIGATION	11/8/1976	0.22	122	18	56	
256631	29-14318	YOST & YOST FARMS LLC	IRRIGATION	8/22/1977	0.13	122	9	27	
256631	29-7308	YOST, MONTE; YOST, SHAUNA	IRRIGATION	2/20/1976	2.64	132		396	
256638	29-2313	MODERSITZKI, DAVID; MODERSITZKI, KAREN J	IRRIGATION	4/14/1952	2.34	173.9		522	feeds pivot at diversion point
256638	29-580	MODERSITZKI, DAVID; MODERSITZKI, KAREN J	IRRIGATION	4/14/1953	2.34	160		480	
256666	29-7253	RINDLISBAKER, MARJEAN; RINDLISBAKER, TERRY G	IRRIGATION	3/11/1975	2,55	314		942	POD serves two mainlines, one to the west the other to the north
256666	29-7446	YOST, LISA J, YOST, PHIL J	IRRIGATION	4/3/1978	1.89	159		477	
256866	29-574	1031, 2373, 1031, 1122	DOMESTIC to look at						Stock water use only, no irrigation use
256948	29-587		DOMESTIC to look at						
257073	29-7352A	JENKINS, JAY DELL	IRRIGATION	11/28/1976	0.1	8		24	Tucked in sink hole, cannot see it from the road.
257073	29-7352C	YOST & YOST FARMS LLC	IRRIGATION	11/8/1976	1.05	87		268	
257073	29-7419A	YOST & YOST FARMS LLC	IRRIGATION	8/22/1977	6,49	451		1353	
257211	29-2548	R LLOYD BROS	IRRIGATION	2/13/1967	3.12	156		468	No meter, big portion of mainline exposed
257211	29-7061	R LLOYD BROS	IRRIGATION	11/12/1970	3.16	158		474	
257226	29-528		DOMESTIC to look at						Culinary well only
257332	29-2540	YOST, LISA J; YOST, PHIL J	IRRIGATION	10/19/1966	3.14	157		471	Located in middle of field, fenced o for livestock. POD splits 3 ways. North, east, west
257542	29-13823	NEIBAUR, CHAD B; NEIBAUR, JACQUELYN	(IRRIGATION	3/20/1972	1.48	340	202	604.9	Very intricate piping and manifold system. POD is in north end of field
257542	29-13821	NEIBAUR, CHAD B; NEIBAUR, JACQUELYN	IRRIGATION	5/23/1973	1.31	340	81	284	
257542	29-13821		IRRIGATION	11/8/1976		340	2	5.9	
257542		NEIBAUR, CHAD B; NEIBAUR, JACQUELYN	IRRIGATION	1/5/1977	0.25	340	33.6	100.8	
257542	29-13817	N/15 8/2/09/2009/0004 (New 25/20 L.)	IRRIGATION	8/22/1977	0.22	340	21.7	65.2	
257542	29-13815	10	DOMESTIC, STOCKWATER	6/1/1900	0,11			5.8	Culinary and stock water well, located in front yard of old house
257644	29-573	WILSON, BRENDA; WILSON, ROGER B							under old windmill
257644	29-573	WELCH, JOHN COLTER	IRRIGATION	5/23/1973	1.09	78		273	
			IRRIGATION IRRIGATION	5/23/1973	1010	78 330	307	273 921	Easy to find, right off of Welch road

Spatial DataID	Water Right Number	OwnerList	WaterUseList	Priority Date	Diversion Rate (cfs)	Total Acres	THE RESERVE OF THE PARTY OF THE	Diversion Volume (acre-feet)	WM Site Visit Comments
258606	29-7000В	GEM VALLEY FARMS	IRRIGATION	7/28/1967	4.41	305	299	897	Pod directly between 2 pivots, no meter. Mainline splits and presumably runs both pivots, one to the east, one to the west.
258606	29-7000A	MORGAN, JOLIN	IRRIGATION	7/28/1967	0.09	305	6	18	
258617	13-2312	LLOYD, ELLA; LLOYD, KEITH E	IRRIGATION	8/8/1962	3	230		690	
259074	29-2352	GEM VALLEY FARMS	IRRIGATION	7/31/1954	2.5	360.5		687	Visited this site earlier in the year. Seems to not have saved. Caution driving in, due to hand line pipe in road
259074	13-2203A	GEM VALLEY FARMS	IRRIGATION	9/9/1959	0.22	11		33	
259074	13-2203B	GEM VALLEY FARMS; NEIBAUR FARM ENTERPRISES	IRRIGATION	9/9/1959	2.88	360.5		409.5	
259110	13-7807	YOST, LISA J; YOST, PHIL J	IRRIGATION	4/4/1977	3.39	240.2		720.6	
259110	13-7775	YOST, LISA J; YOST, PHIL J	IRRIGATION	12/13/1977	2.21	110.4		331.2	
259159	29-539	GEM VALLEY FARMS	DOMESTIC, INDUSTRIAL	5/1/1901	0.09			3.8	Behind grey shop with white door. No major irrigation use
259252	29-2352	GEM VALLEY FARMS	IRRIGATION	7/31/1954	2.5	360.5		687	Pod runs pivots in this section, no visible tags, manifold does run multiple directions
259252	13-2203B	GEM VALLEY FARMS; NEIBAUR FARM ENTERPRISES	IRRIGATION	9/9/1959	2.88	360.5		409.5	
259621	29-7324	YOST, MONTE; YOST, SHAUNA	IRRIGATION	6/3/1976	8.08	404		1212	Enter from south of field by crossing the railroad tracks.

Spatial DataID	Water Right Number	OwnerList	WaterUseList	Priority Date	Diversion Rate (cfs)	Total Acres	Acre Limit	Diversion Volume (acre-feet)	WM Site Visit Comments
259625	13-7807	YOST, LISA J; YOST, PHIL J	IRRIGATION	4/4/1977	3.39	240.2		720.6	Location is north of pin, along hegstrom road. POD appears straight forward, heads west toward center
259625	13-7775	YOST, LISA J; YOST, PHIL J	IRRIGATION	12/13/1977	2.21	110.4		331.2	pivot
259655	29-7070	GEM VALLEY FARMS	IRRIGATION	9/20/1971	4.68	306		918	Simplistic, easy to find. 12 inch mainline travels south after POD
259770	13-2259	GEM VALLEY FARMS	IRRIGATION	8/5/1963	2.1	799	158	553	Easily accessible, manifold services E, NW and W.
259770	13-7165	GEM VALLEY FARMS	IRRIGATION	4/6/1977	3.12	799	158	546	
259770	13-7198B	GEM VALLEY FARMS	IRRIGATION	6/20/1977	0.64	799	158	147	
259770	13-7198C	GEM VALLEY FARMS	IRRIGATION	6/20/1977	1.66	799	158	385	
259770	13-7261	GEM VALLEY FARMS	IRRIGATION	9/10/1979	2	799	158	535.5	
259815	13-7068	BROWN BRAVO II LLC	IRRIGATION	12/14/1973	3 1.14	153		345.9	POD feeds pipe that tees both and south. Can be found on west side of hegstrom road, right off the roadmeter not installed to spec pipe up sized right after meter
259920	13-2259	GEM VALLEY FARMS	IRRIGATION	8/5/1963	2.1	799	158	553	No meter, 2 POD side by side both look to be active
259920	13-7165	GEM VALLEY FARMS	IRRIGATION	4/6/1977	3.12	799	158	546	
259920	13-7198B	GEM VALLEY FARMS	IRRIGATION	6/20/1977	0.64	799	158	147	
259920	13-7198C	GEM VALLEY FARMS	IRRIGATION	6/20/1977	1.66	799	158	385	
259920	13-7261	GEM VALLEY FARMS	IRRIGATION	9/10/1979	2	799	158	535.5	Side by side with pod 259920 no
259922	13-2259	GEM VALLEY FARMS	IRRIGATION	8/5/1963	2.1	799	158	553	meter, appears to tie in with other POD
259922	13-7165	GEM VALLEY FARMS	IRRIGATION	4/6/1977	3.12	799	158	546	
259922	13-7198B	GEM VALLEY FARMS	IRRIGATION	6/20/1977	0.64	799	158	147	
259922	13-7198C	GEM VALLEY FARMS	IRRIGATION	6/20/1977		799	158	385	
259922	13-7261	GEM VALLEY FARMS	IRRIGATION	9/10/1979	2	799	158	535.5	
259944	13-7161	JORGENSEN, CARL B; JORGENSEN, PATRICIA	IRRIGATION	4/15/1977	4.54	230		690	2 lines headed south, one line headed north. A tag is on old concrete structure, should be moved
259944	13-7815	JORGENSEN, KEITH AND TERRY; JORGENSEN, TERRY C	IRRIGATION	8/14/1957	3.44	314.8	3	944.4	
259977	13-7815	JORGENSEN, KEITH AND TERRY; JORGENSEN, TERRY C	IRRIGATION	8/14/1957	3.44	314.8	3	944.4	Between pivot and turner road, POD tees going north and south
259982	29-530		DOMESTIC to look at						Could not find, no name on owner list, no well in location
260073	13-7198A	GEM VALLEY FARMS	IRRIGATION	6/20/1977	7 2.93	193			Very complicated manifold, hard to indicate what area is serviced, need to schedule meeting with user

Spatial DataID	Water Right Number	OwnerList	WaterUseList	Priority Date	Diversion Rate (cfs)	Total Acres	Limit	Diversion Volume (acre-feet)	WM Site Visit Comments
260126	13-7010	JORGENSEN, KEITH AND TERRY; TERRY C JORGENSEN ET UX	DOMESTIC, IRRIGATION	3/5/1970	0.68	35		108.6	Enter through feed lot. No meter, but appears pod tees and services mainline running north and south
260180	29-7001	R LLOYD BROS	IRRIGATION	9/5/1967	5.97	1652	440	1320	On shoulder of unmaintained cinder road, appear to run pivot to the south
260180	29-7636	R LLOYD BROS	IRRIGATION	4/19/1982	0.59	1652	80	242	
260180	29-7637	R LLOYD BROS	IRRIGATION	4/19/1982	6.02	1652	852	2555.3	
260180	29-10171	R LLOYD BROS	IRRIGATION	4/1/1987	3.79	1652	280	2534	
260345	29-13577	RINDLISBAKER, MARJEAN; RINDLISBAKER, TERRY G	IRRIGATION	2/2/1977	2.74	137		411	Located on east side of brown building, mainline tees north and south, meter is improperly installed
260643	13-7099	CHRISTENSEN, BART O	IRRIGATION	1/14/1975	4.79	306		918	Directly east of potato cellars right off of road pipe tees, one heading north, one heading south
260761	29-7001	R LLOYD BROS	IRRIGATION	9/5/1967	5.97	1652	440	1320	Electrical box and well has suffered damage from livestock
260761	29-7637	R LLOYD BROS	IRRIGATION	4/19/1982	6.02	1652	852	2555.3	
260761	29-10171	R LLOYD BROS	IRRIGATION	4/1/1987	3.79	1652	280	2534	

Spatial DataID	Water Right Number	OwnerList	WaterUseList	Priority Date	Diversion Rate (cfs)	Total Acres	Acre Limit	Diversion Volume (acre-feet)	WM Site Visit Comments
260974	13-7810	YOST, LISA J; YOST, PHIL J	IRRIGATION	1/3/1975	0.3	122.4	21	63	2 pumps, POD splits and services lines running north and south
260974	13-7778	YOST, LISA J; YOST, PHIL J	IRRIGATION	4/4/1977	0.61	122.4	39.8	119.4	
260974	13-7808	YOST, LISA J; YOST, PHIL J	IRRIGATION	4/4/1977	0.03	122.4	3	9	
260974	13-7776	YOST, LISA J; YOST, PHIL J	IRRIGATION	12/13/1977	0.95	122.4	58.6	175.8	
260974	13-7809	YOST, LISA J; YOST, PHILIP J	IRRIGATION	1/3/1975	4.16	289		867	
261005	29-7001	R LLOYD BROS	IRRIGATION	9/5/1967	5.97	1652		1320	Directly west of neighboring POD, no meter, no A tag
261005	29-7636	R LLOYD BROS	IRRIGATION	4/19/1982	0.59	1652	80	242	
261005	29-7637	R LLOYD BROS	IRRIGATION	4/19/1982	6.02	1652	852	2555.3	
261005	29-10171	R LLOYD BROS	IRRIGATION	4/1/1987	3.79	1652	280	2534	
261014	29-7001	R LLOYD BROS	IRRIGATION	9/5/1967	5.97	1652	440	1320	No meter, A tag is on on check valve right after POD FEED 2 mainlines, one to south, one to north west
261014	29-7636	R LLOYD BROS	IRRIGATION	4/19/1982	0.59	1652	80	242	
261014	29-7637	R LLOYD BROS	IRRIGATION	4/19/1982	6.02	1652	852	2555.3	
261014	29-10171	R LLOYD BROS	IRRIGATION	4/1/1987	3.79	1652	280	2534	
261096	29-7098	RINDLISBAKER, TERRY G	IRRIGATION	8/30/1972	4.79	292		876	Under cover, east side of Lloyd road Feeds to booster pump and tees north and south.
261295	13-485	MYERS, DARLYNE; MYERS, JAMES W	DOMESTIC, IRRIGATION, STOCKWATER	6/1/1903	0.08	2		8.3	Old well that needs more homework Name on rights do not match any current land holdings. Going to need more homework. No well in designated location but multiple farm yards owned by multiple partie near by
261463	29-7264	HANSEN, D C	IRRIGATION	4/21/1975	3.06	153		459	Pod is under cover, appears to run two pivots. No tags, no meter
261463	29-7102A	RINDLISBAKER, MARJEAN; RINDLISBAKER, TERRY G	IRRIGATION	10/17/1972	5.35	308		924	
261789	29-572	JORGENSON, BILL; JORGENSON, CARL; JORGENSON, EARL J	DOMESTIC, STOCKWATER	7/1/1915	0.04			4.5	House well with stock water rights Well location is updated, in a vaul on east side of canal
261841	13-8054	CHRISTENSEN, BART O	IRRIGATION	1/19/1977	0.1	320	6	18	In middle of field, directly north o White House.
261841	13-8070	CHRISTENSEN, BART O	IRRIGATION	1/19/1977	0.32	320	20	60	
261841	13-2269	CHRISTENSEN, BART O; CHRISTENSEN, CHERIE	IRRIGATION	12/9/1965	4.42	320	237	711	
262097	29-8240	JORGENSEN FARMS LTD PARTNERSHIP	IRRIGATION	12/22/1958	3 2.88	355	246		Pod is directly south of Grace tow sign. Very intricate manifold syste no tag no meter.
262097	29-8241	JORGENSEN FARMS LTD PARTNERSHIP	IRRIGATION	5/15/1969	3.74	355	352		

Spatial DataID	Water Right Number	OwnerList	WaterUseList	Priority Date	Diversion Rate (cfs)	Total Acres	Acre Limit	Diversion Volume (acre-feet)	WM Site Visit Comments
									Appears to be out of use for
281945	29-7636	R LLOYD BROS	IRRIGATION	4/19/1982	0.59	1652	80	242	irrigation, now solar powered
									livestock source
282027	29-584	CENTRAL CEMETERY DISTRICT	IRRIGATION	4/10/1938	0.05	3		9	Well on south side of building,
282027	23-304	CENTRAL CEMETERY DISTRICT	IIIIIIIIII	-, 10, 1550					waters cemetery
									Well is in vault in back yard. No major
294179	13-481	COMISH, BENNY C; COMISH, FRANCES M; COMISH, RICHARD	DOMESTIC, IRRIGATION, STOCKWATER	4/1/1920	0.06	1		5.5	irrigation, runs domestic and farm
									yard
				E /4 2 /4 2 ==	0.00=		_	24	POD is directly behind white shed
335248	5248 29-7394B	WISTISEN, DALE R	IRRIGATION	5/13/1977	0.095	23	7	21	between house and shop no meter
225240	30 73046	WISTISSAL DALE D	IRRIGATION	5/13/1977	0.095	23	7	21	
335248	29-7394C 29-13987	WISTISEN, DALE R WISTISEN, DALE R; WISTISEN, NUELENE	IRRIGATION IRRIGATION, STOCKWATER	5/13/1977	0.095	50	7	155.7	
335248	29-13988	WISTISEN, DALE R; WISTISEN, NUELENE WISTISEN, DALE R; WISTISEN, NUELENE	IRRIGATION, STOCKWATER	5/13/1977	0.12	23	9	28	
335248	29-13988	WISTISEN, DALE K, WISTISEN, NOELENE	INNIGATION, STOCKWATER			23	9	20	Appears to be municipal POD not
336580	29-561	CITY OF BANCROFT	MUNICIPAL	3/1/1935	0.36				sure about jurisdiction
336580	29-560	CITY OF BANCROFT	MUNICIPAL	11/18/1955	2				oute about junious train
					1.0				Metal tag present, no flow meter,
340928	29-7392A	JENKINS, NEWELL R	IRRIGATION	5/21/1977	0.39	38		114	electric powered
340928	29-7392B	WISTISEN, KATHLEEN; WISTISEN, STANLEY	IRRIGATION	5/21/1977	1.26	124		372	
341141	29-561	CITY OF BANCROFT	MUNICIPAL	3/1/1935	0.36				Appears to be a municipal POD
341141	29-560	CITY OF BANCROFT	MUNICIPAL	11/18/1955	2				
350788	13-2313	LLOYD, THOMAS PARKE	IRRIGATION	9/29/1966	0.68	57		171	Test, moved location on Survey 123,
330766	15-2515	ELOTO, MONIAS PARKE			0.00				no meter present
350788	13-8090	STODDARD FARMS PROPERTIES LLC	IRRIGATION	9/29/1966	3	180		540	
350796	29-531		DOMESTIC to look at						No name on owner list, but this runs domestic property to the west

Spatial DataID	Water Right Number	OwnerList	WaterUseList	Priority Date	Diversion Rate (cfs)	Total Acres	Acre Limit	Diversion Volume (acre-feet)	WM Site Visit Comments
350860	29-13912	YOST & YOST FARMS LLC	IRRIGATION	3/20/1972	0.02	4	2.4	7.2	Just to the north of center pivot. Pip tees out of point of diverson, 2 line to the east, 1 line to the west.
350860	29-13913	YOST & YOST FARMS LLC	IRRIGATION	3/20/1972	0.64	110	65.2	195.5	
350860	29-14227	YOST & YOST FARMS LLC	IRRIGATION	3/20/1972	0.39	62	36.8	110.4	
350860	29-13910	YOST & YOST FARMS LLC	IRRIGATION	5/23/1973	0.02	· 4	1	3.5	
350860	29-13911	YOST & YOST FARMS LLC	IRRIGATION	5/23/1973	0.57	110	26.2	91.7	
350860	29-14226	YOST & YOST FARMS LLC	IRRIGATION	5/23/1973	0.34	62	14.8	51.8	
350860	29-13818	YOST & YOST FARMS LLC	IRRIGATION	11/8/1976	0.01	4	0.1	0.3	
350860	29-14223	YOST & YOST FARMS LLC	IRRIGATION	11/8/1976	0.01	62	0.9	2.8	
350860	29-13908	YOST & YOST FARMS LLC	IRRIGATION	1/5/1977	0.01	4	0.3	0.9	
350860	29-13909	YOST & YOST FARMS LLC	IRRIGATION	1/5/1977	0.11	110	11.9	35.7	
350860	29-14225	YOST & YOST FARMS LLC	IRRIGATION	1/5/1977	0.07	62	5.2	15.6	
350860	29-13906	YOST & YOST FARMS LLC	IRRIGATION	8/22/1977	0.01	4	0.3	0.9	
350860	29-13907	YOST & YOST FARMS LLC	IRRIGATION	8/22/1977	0.09	110	7_1	21.2	
350860	29-14224	YOST & YOST FARMS LLC	IRRIGATION	8/22/1977	0.06	62	3.9	11.7	
350887	29-538	PRIESTLEY, LINDA J; PRIESTLEY, MARK L	COMMERCIAL, DOMESTIC	10/15/1900	0.04			3.2	Culinary well with stock water, r irrigation
350890	29-534	RINDLISBAKER, J RUSSELL; RINDLISBAKER, LEON G	DOMESTIC, STOCKWATER	5/1/1900	0,23			13.8	Culinary well and used for barn w also. Located right outside back o under ground
350963	29-10242	RINDLISBAKER, MARJEAN; RINDLISBAKER, TERRY G	IRRIGATION	4/1/1978	0.16	20			2 rights to the same well, POD AL SERVICES 350964
350964	29-7253	RINDLISBAKER, MARJEAN; RINDLISBAKER, TERRY G	IRRIGATION	3/11/1975	2,55	314		942	Same POD services 350963
351007	29-2536	RIGBY, BONNIE K; RIGBY, MAX D	IRRIGATION	10/9/1966	3.14	200		600	Not in use due to broken connec between main line and POD
351078	29-2467	WIGHT, SHERI; WIGHT, STEVEN	IRRIGATION	11/9/1962	1.9	440	212	714	Fenced for livestock use, a tag loose, no meter present
351078	29-7172	WIGHT, SHERI; WIGHT, STEVEN	IRRIGATION	2/13/1974	3.41	440	264	924	
351078	29-7371	WIGHT, SHERI; WIGHT, STEVEN	IRRIGATION	2/14/1977	1.26	440	63	220.5	
371454	29- 7 419A	YOST & YOST FARMS LLC	IRRIGATION	8/22/1977	6.49	451		1353	No meter, located 100 yards wes house at end of red house cany road. Main line tees right after P
371464	29-13578	RINDLISBAKER, MARJEAN; RINDLISBAKER, TERRY G	IRRIGATION	2/2/1977	1.54	77		231	Pod under cover, according to po panel, pod services two pivots. meter, no tags
371464	29-7387	RINDLISBAKER, MARJEAN; RINDLISBAKER, TERRY G	IRRIGATION	4/18/1977	3.2	160		480	
371465	29-2315	WELCH, KIM	IRRIGATION	7/17/1952	2.14	269		781	Located 15 yards south of wip
371465	29-7443	WELCH, KIM	IRRIGATION	3/23/1978	0.67	269		244	pivot under pump shed
390164	13-2313	LLOYD, THOMAS PARKE	IRRIGATION	9/29/1966	0.68	57		171	Test, no meter, in range of pivo could be difficult to access dur active irrigation

Spatial DataID	Water Right Number	OwnerList	WaterUseList	Priority Date	Diversion Rate (cfs)	Total Acres	100000000000000000000000000000000000000	Diversion Volume (acre-feet)	WM Site Visit Comments
390164	13-8090	STODDARD FARMS PROPERTIES LLC	IRRIGATION	9/29/1966	3	180		540	
434573	29-561	CITY OF BANCROFT	MUNICIPAL	3/1/1935	0.36				Municipal well for Bancroft memorial park
434573	29-560	CITY OF BANCROFT	MUNICIPAL	11/18/1955	2				
452123	13-472	TURNER CEMETERY DISTRICT	IRRIGATION	3/21/1955	0.04	2		6	Under ground in vault,
455774	13-520	WILLIAMS, GRANT E	DOMESTIC, IRRIGATION, STOCKWATER	8/1/1941	0.04	1		7.8	Clearly falls under domestic and stock water right. No irrigation. Pod is located at back door of old White House
458483	29-7041	WISTISEN LIVESTOCK CORP	IRRIGATION, STOCKWATER	11/20/1969	4.68	800	477	1432.4	Appears to be stock water only, fenced off for livestock use only
486578	13-2278	MC NEILL, BOYD NEWTON	IRRIGATION	8/6/1965	5.45	308		924	Pod supply line runs north, services east and west pivots nearby pivots, no meter
486580	13-7084	SIMONSON, VON N	IRRIGATION	10/7/1974	4.36	274		822	Directly under the pivot behind house, manifold goes multiple different ways.
486580	13-7259	SIMONSON, VON N	IRRIGATION	9/20/1979	1.92	96		288	
486582	13-7099	CHRISTENSEN, BART O	IRRIGATION	1/14/1975	4.79	306		918	Right on top of hill of Anderson road, 400 yards north or north extension canal, feeds manifold south of POD
486582	13-7147	CHRISTENSEN, BART O	IRRIGATION	1/19/1977	4.59	287		861	