

Merrill J. STIPPICH
2195 Hawthorn RD
Indian Valley Td 83632
355-2208

Merrill is sending
WM report 4/18/07.
Per telecon 4/18/07.

ly
4/18/07

Muir Allison
Assessments:
\$.38/ac
Irrig Dist assess-
ments: \$1/ac

March 3-06

RECEIVED LETTER FROM WATER
RE SOURCE.

March 4-06

RECEIVED LETTER FROM WATER
RE SOURCE. (MALCUM HUY W.R.)

March 5-06

24 mi. WENT TO WAYNE B. 2 TIMES
(WATER THINGS)

April 6th 06

15 mi. MEETING WITH WARD, YEAGER, WAYNE B.

April 13, 06

7 mi. BOARD MEMBERS SHOWED ME
ALL THE DEVIATIONS. TOOK ALL DAY.

April 17, 06

7 mi. TALKED TO R. YANTIS + WAYNE B.
ABOUT WATER DATES CLEANED 2
BEAVER DAMS OUT OF LINSEY DITCH

May 3, 06

8 mi. GOT PAPER NOTICIZED FOR WATER

MAY 06

19mi. Helped WAYNE B. put Boards in
Spill way of Res.

MAY 20 06

32mi. Water level at Little Wieser
Weir - 14" from TOP of CONCRETE.



MAY 11 06

11mi. Water level at Little Wieser
weir is 9 1/2" Below concrete



MAY

Talked to Kari Wallace
about water on Her place

MAY 25

Received letter from Water
Resource Board to attend
meeting in Jerome IDA on
JUNE 8, 2006

JUNE 5th 2006

9 mi. Measured L. Wieser weir, Got paper

JUNE 6 2006

Called about ATU sprayer parts
said part would be here soon

482mi JUNE 8 2006

Went to Jerome IDA, water
master work shop

20mi JUNE 17, 2006

Measured Willer son Ditch $8\frac{1}{4}$ "
over weir, got parts for sprayer.

9m JUNE 18, 2006

Sprayed weeds from dam down
Anderson ditch

19 JUNE 30 - 2006

30" at weir on little weir

JUNE 30 - 2006

Res is 2" over 56' mark at
Boat dock

JULY 4, 2006

ditch to Jerry Yeager is 24" ?
Cal ... 13 ... 11 ... 11

93.6 mi July 10 - 2006

Grays Cr. 12.9" (AM)

Anderson - LOOKS Good

Lower Canal LOOKS OK

Res is at 56' 10" (AM)

LOOKS LIKE weeds I sprayed Sat.
has BEEN HIT Hard?

Stewart Ditch dam Has washed
out NO water.

Mortiz Ditch wa 14" (Plenty)

90.6 mi July 11 2006

Wilkinson Ditch 13 1/4"

TOMASON Lane 16"

SWIR Ditch 16 1/2"

Lowest Ditch 2"

92.6 mi July 12. 2006

Grays CR. 12 1/2"

Mortiz - 13"

Stew dam out?

Open west Gate at Res 1/2 Turn

have lost about an inch on all
ditches.

33.2^m July 13 2006

Little Weiser River 8"
Grays Cr. 12 ¹/₄"
Stew 13"
MORTS was 15" now 10"
Talled to RAYC everything
seems to be OK, c down at that end.

July 14, 2006

Res is at 56.2"
Opened Res 1 Turn AM.
Opened Anderson 4 Turns
Grays Cr. 11"
Stew 12"
MORTZ 10"
Opened Res 1 Turn PM

July 15 2006

Sun. Opened Res ¹/₂ Turn P.M.
Things are getting dry.

(looking good)

July 16, 2006

(Wed) Things look pretty good

no water down River.

Swick Ditch is at $11\frac{1}{2}''$

Will Ditch is at $12''$

opened Res 1 Turn AM

Grass $11\frac{1}{4}''$

Mortz $10''$

Stew $12''$

Res Level - $54' 9''$

Wier at Little Wier is $6\frac{1}{4}''$

36 mi July 18 2006

Monday

Res Level is at $54'$

26 mi July 20 2006

wed

Res Level is $53' 4''$

47 mi July 21 2006

Swick - $14''$

alison - $0''$

will - $8\frac{1}{2}''$

724 July 22 2006

Opened Res 1 Turn
River water - 6"

Opened splitter 2 turns

July 26 2006

didn't work

Wed July 27 2006

Every thing looks good

28 July 2006

didn't work

Aug 2 2006

Every Body looks ok

Res level is at 50'

Aug 5 2006
Open Res $\frac{1}{2}$ Turn
Splitter 2 Turns
McNee was Short of water

Aug 6 2006
McNee is Looking Better
Swirl $14\frac{1}{2}$ "
Rock at Wilkerson Headgate
is just visible

Aug 9 2006
Res Level at $48''?$
Res open at $6\frac{1}{4}$ "
Little wicket with 5"

43.0 mi Aug 11, 2006
Res at $47''$
Everybody seems to be
getting water

31.7 mi Aug 12 2006
Things are going Great
(no measurement)

Aug 13, 2006
Every Body's getting water
(Some going down River)

43.3^{mi} Aug 14, 2006
Shut Res $\frac{1}{4}$ Turn
Res level is 46' 8"
Little w/s water 4 $\frac{3}{4}$ "

45.2^{mi} Aug 16, 2006

Aug 19, 2006
Res 43' 0"
Willkerson - 10"
Grays 11"

41.2^{mi} Aug 23, 2006
Every Body seems to be getting
water, no one complaining

43.0^{mi} Aug 28, 2006
Res 41.0'
Every thing is good (all over)

53 mi Wed Aug 30, 2006

Water Looks Low all over

43 mi Aug 31, 2006

Water a little Low everywhere

Res 37'

Turned more water in

32.6 mi Sept 2, 2006

Water is good everywhere

Res seems to be dropping fast

33.2 mi Sept 4, 2006

Joe Holmes called (Low water)

opened Res $\frac{1}{2}$ turn

15.2 mi Sept 11, 2006

Water OK?

Res is at 31'

Little water in (3 $\frac{1}{4}$ ")

107 mi Sept 13, 2006

opened Res $\frac{1}{2}$ turn Everybody

River at Willkerson down about
opened Res 1 full turn
Gray Cr. is down about 2"
Little Winser were at 3 1/4"

37.6 mi Sept 16 2006

Res is about 28'. opened Res 2 turns
SHUT SPLITER down 2 turns
Grays Cr. a little short.

28.2 mi SEPT 17 2006

Willkerson, SWIX, water is fine
Grays Cr. is up some

34.6 mi Sept 21, 2006

Res is open 17 1/4" at (Res loc)
That is 18 turns on west head gate
Little Winser were 5"

34.2 mi Sept 23 2006

Res level is dropping fast
Concretes is showing at Head gate

down & opened splitter. everything is
going down anderson cr. Talked to
Ralph Yantis about STOCK WATER? IT
IS OK

26m. Sept 28. 2006

Called WAYNE B, HE IS GONE
Talked to JOE HOLMES about GRAYS CR.
Head gate

11.6m Sept 29, 06

Talked to WAYNE B. about GRAYS CR.
HE IS GOING TO TAKE CARE OF IT,
SO HOLMES CAN GET CONCRETE WORK
DONE WITH OUT TOO MUCH WATER
IN THE RIVER.

10.0m OCT 2006

TOOK SPRAYER TO STORAGE SHED
DONT KNOW WHAT ELSE TO DO FOR
THE YEAR SO AM CLOSING BOOK
AS FAR AS I GO.

Budget for 2007 =

about the same as 2006

Wages - Phone & mileage. Can't
see any change in the future
unless I haven't been doing
job to every body's expectations

(phone = 400⁰⁰)

(misc supplies 50⁰⁰)

Water meters |

Merrill & ~~Stephen~~

Jan 2007