

Rich Wootan  
2286 S. Pruett Road  
King Hill, Idaho 83633

December 14, 2015

Little Canyon Creek  
11204 N Bar 21 Drive  
Glenns Ferry, Idaho 83623

PLEASE FIND THE FOLLOWING CALL OUTS FOR THE 2015 IRRIGATION SEASON

- 3/2/15           Went and looked at Bob Hall's water meter
- 3/16/15           Went and checked Paul's reservoir. Dirt in the spill-way and he is almost full. Went up to Paul's diversion - no measuring device there. Check Trail's diversion very little water. Checked Marked Anderson's weir at Dick's old pump station.
- 3/17/15           Talked to Steve Lester, who said to turn Paul off. Paul didn't have measuring device. Turned Paul down to only receive cow water right. Paul called said he was not full. He wanted to leave 100 inches. Asked if he moved dirt out of spill way, he said it was there for 4-wheelers to cross. Paul didn't remove dirt.
- 3/18/15           Adjusted Paul's head gate down, too much for cows. (Rocky)
- 3/20/15           Adjusted head gate down at Paul's. (Juan)
- 4/14/15           Jerry Gorrell called and was out of water. Turned Trail diversion on.
- 4/16/2015        Rocky called and wants whoever does not have measuring device on their system to be shut off. I called Angie Grimm and asked what to do, she said she would talk to her manager and get back to me.
- 4/20/15           Took IDWR around to look at all the points of diversion on Little Canyon Creek.
- 4/25/15           Went with Rob Whitney to look at Paul's new weir on pipe. Weir is not right and doesn't show how much water is coming across the weir.

2015 LITTLE CANYON CREEK – 9 days

Rich Wootan, Little Canton Creek water master