



PHOTOGRAPHER: KAY WALKER & Linda Werner
DATE OF PHOTOS 10-7-93
FILE NO(S). A51-00006/00007/00008/04096



Ditch at
measurement
site -

Stilling
well & 2.0'
gage beside
Canal.

Water level
at 1.0' -

