


A25-00056D Summary 9/18/03

- 1) Ownership - correct
- 2) POD - Claim lists POD of anderson canal.
I photed pump from canal - GPS 674, 355 E
280, 539 N Waypoint 56D. See exchange
agreement, notes re: POD in A25-00056F.
- 3) POU POU is large lawn area, 2 large
gardens, irrigated pasture, associated w/
2 homes. It is hard to tell from aerial
photo where the line is between this POU
and neighbor to the south east. GPS
Waypoint 56D-2, 674, 236 E 280, 434 N
is SE corner of this POU



A25-00056A summary 9/18/03 p2

4) Overlap. None for Irrigation. Domestic well serves homes.

5) Conflict. See conflict notes in A25-00056F.

Bryce A. Contor

Water Resources
Field Services
208 663 4667

A25-00056D Field Inspection 9/15/03

Photo 1) POD GPS waypoint 56D
674355 E 280539 N

- 2) N end of POD - calf pasture
- 3) S end of POD - lawn & garden

GPS 2 674236 E 280434 N SE
corner of POD waypoint 56D-2

A25-00056D Contract log

9/11/03 523-2890 1635

Mrs. Bolinder - Monday 1 pm
White long circles drive -