



10/23/2003

P/D from Eagle Creek.

E
↑



5/7/2004 When dam was in place, overflow
would run down this channel.

S
↑



10/23/2003

NW
↑

View of Pou from P/D.



5/1/2004

W
↑

Downstream view P/D and resulting
washed out area near Eagle Cr.



5/7/2004

N
↙

East end of POU lying between
fence and road. This ground irrigated
from upper P/D.



5/7/2004
E
↑

Mike Silbrett says this is the place where
- canvas dam is placed to back up Eagle Cr.
for sub-irrigation.



5/7/2004

WNW



West end of P04 lies between fence and road. This ground irrigated from upper P/D.