A25-11809 #1 Holding tank @ east POD



25-7478

A25-11809 #2 East POD, lower spring

25-7478



A25-11809 #3 East POD, upper spring



A25-~~11809~~ 11809 #4 Historical ditch west of Cabin



A25-11809 #5 Holding Tank at West POD



A25-11809 #6 Original Pod. Ditch went to right, behind tree.



This doesn't show in photo but same is old beaver pond/ wetland @ Sellars creek

A25-11509 #7 POU



A25-11809 Contact Log

10/28/03 Post Card mailed

10/29/03 Mr. Kelly Called- he will be there Saturday AM. 1/2 mile past Bone store turn right on Blackfoot Reservoir Road. Go 4 miles, cross Sellars creek. Turn right, go 1 1/4 mile. On the left is a double gate with an over head crossbar with a sign "010 Ranch." House is back against a hill.

5/30/03 Claimant said there are 3 points of diversion and ~~that~~ actual POU is about an acre of pasture and lawn and garden.

Post Card
10/28/03
Bac