

29-00274D

POD

Field Exam: 8/13/02



Looking at POD. Mink creek to the right of the picture. POU to the left of the picture (csaxton).



Looking SW. Irrigated pasture land. POD behind me in picture (csaxton).

29-00274D

POU

Field Exam: 8/13/02



Looking South at claimed POU (csaxton).



Looking West at claimed POU. Note irrigation line at the base of the wire fence (csaxton).