

29-00276H

POD

Field Exam: 8/14/02



Looking East at POD pump. Pump Info: Make = Sta-Rite; HP = 5; Model =TVB184TCDR7011DNL (csaxton).



Looking South at claimed POU. Pic shows claimants front yard (csaxton).

29-00276H

POU

Field Exam: 8/14/02



Looking North. Claimant stated that this land is not irrigated with the creek water. This pic shows the claimants property that is next to Mink Creek. Mink Creek to the right of the picture (csaxton).

No, later statement
Confirmed that it
is. CS 6-10-03