

29-00276B

POU

Field Exam: 8/14/02



Looking North at what looks like a garden on claimed POU (csaxton).



Looking West at claimed POU (csaxton).

29-00276B

System

Field Exam: 8/14/02



Looking South at pile of old pipe that looks like it could have been part of an irrigation system (csaxton).



Looking SE at what appears to be an irrigation hose that might supply water to the claimed POU (csaxton).

29-00276B

POU

Field Exam: 9/17/02



Looking North at claimed POU (csaxton).

29-00276B

POD

Field Exam: 9/17/02



Looking at point where pump is placed when in place. Mink Creek to left of picture. POU behind me in picture. Ditch seen in the middle of picture (csaxton).



Looking East at POD. Claimed POU behind me in picture (csaxton).