

29-00497C

POD

Field Exam 11/01/01



Looking west. Current POD put in place in 1984 when claimant acquired property. Pump in place is General Electric: $\frac{3}{4}$ HP: Model 5KC39QN101. Current pump is just used to irrigate around his home. During the irrigation season claimant uses two 5 HP pacer pumps, or a PTO Berkly T2. The generally runs 18 heads at a time (csaxton 11/02/01).

29-00497C

POD

Field Exam 11/01/01



Looking west. Current POD put in place in 1984 when claimant acquired property. Pump in place is General Electric: $\frac{3}{4}$ HP: Model 5KC39QN101. Current pump is just used to irrigate around his home. During the irrigation season claimant uses two 5 HP pacer pumps, or a PTO Berkly T2. The generally runs 18 heads at a time (csaxton 11/02/01).

29-00497C

POU

Field Exam 11/01/01



Looking East. Claimant's white home in the background. This picture shows the south irrigated field. Rapid Creek behind me in picture (csaxton 11/02/01).

29-00497C

POU

Field Exam 11/01/01



Looking SW. Picture shows the irrigated field west of Rapid creek. Rapid creek to the right of the picture (csaxton 11/02/01).

29-00497C Historical Ditch Field Exam 11/01/01



Looking West. Two pictures show historical ditch that used to carry Shaw Hollow water to the West side of the claimants property (csaxton 11/2/01)