29-00285G POD Field Exam: 8/13/02

Looking West at red hose that is assumed to be used to convey water from Rapid Creek to the claimed POU (csaxton).

Looking North at claimed POU. No signs of irrigation system that serves this field (csaxton).

29-00285G POD Field Exam: 8/13/02

Looking East at POD. Claimed POU behind me in picture. Rapid creek in background (csaxton).



Looking East at claimed POU. Can see red hose in center of picture that seems to be used to convey water to the claimed POU (csaxton).