

PIPE LAYING OUT OF WAY FOR WINTER - LOOKS INTO MAIN LINE
PIPE



PIPE LAYING BY FENCE SO LIVESTOCK CANNOT DAMAGE IT



PROFILED

SCANNED
JUL 21 2005

WHERE PIPE NORMALLY LAYS IN THE SUMMER



PIPE CANNOT BE REMOVED BECAUSE PART OF IT IS BURIED UNDER ROAD



SCANNED

JUL 21 2005

ANIMAL DAMAGE



PIPE LAYING BY FENCE SO ANIMALS CANNOT DAMAGE IT



PROFILED

SCANNED
JUL 21 2005

LOOKING NORTH FROM GEORGE'S HOUSE ROCKS AND DEBRIS WERE
MOVED FROM SOUTH TO NORTH TO STOP FURTHER DAMAGE



AFTER A FLASH FLOOD THIS GULLEY WAS FILLED WITH ROCKS
AND DEBRIS THAT THE COUNTY HAD TO CLEAN UP



PROFILED

SCANNED
JUL 21 2005

VIEW OF THE DIKE LOOKING TOWARD GEORGE'S
HOUSE SOUTH



END OF PERMANENT MAIN LINE



PROFILED

SCANNED
JUL 21 2005



PROFILED

SCANNED
JUL 21 2005