

File No. Hart/Witt

STATE OF IDAHO
Department of Water Resources

FIELD INSPECTION REPORT

1. Date: 8/31/2004 Time: 12:30p-2:30p Photos: X Yes No
2. Inspection involves: X Water Rights Dam Safety Well Construction or Driller
Waste Well Stream Channel Alteration Water Distribution
X Other Water Rt Adj.
3. Reason for inspection: Field exam of Adj. lake claims
4. Stream name: Unnamed Steam trib to Lake Fork Creek
5. Stream characteristics:
6. Stream width: Depth: Gradient: Q: est. meas.
7. Location: 1/4 1/4, Sec. 34, Twp. 18N Rge. 3E, County Valley
Landmark: E of Lake Fork (town)
8. Person(s) contacted: Daryl & Michelle Hart, Vera Witt
9. Dam name: Turner Dam * Spilling: ? No Yes Q
Outlet open: No Yes Q Spillway open: Yes Fibrd Gate open
Freeboard: Spillway Crest Res. stage: Rising Falling Rate
10. Area characteristics: Pond - see photos
11. Weather conditions: Sunny & Warm
12. Describe activity/conditions inspected: Pond & property owned by Harts & Witt
13. Are all requirements being met? X Yes
If not, check type violated: Statutory Rules & Regs Permit
14. Describe impact on others:
15. Describe alternatives:
- X Did not visit spillway - had met previously
coordinated w/ Mr. Ramon, owner of property at spillway

16. Remarks

17. Followup Necessary: ☒ Yes ☐ No

Describe:

Repair recommendations
for adj claims

18. Sketch: Include direction, important dimensions, photo locations, landmark or reference point

19. Action taken at time of inspection: Took photos, discussed

w/ claimants some of their options for recording
storage water right, discussed adj claims

20. Signed: David R. Tuttle (with Chris Bromley)

21. Follow up action: Date: _____ Additional Memo Prepared: ☐ Yes ☐ No

Describe: _____

22. Signed: _____