

29-00299&309

POD

Field Exam 10/10/01



POD in Sawmill Creek. Pump information: Make – Wayne: HP 1: SN 0017 (csaxton 10/11/01).

29-00299&309

POU

Field Exam 10/10/01



Looking south at POU. Irrigate POU is around home (csaxton 10/11/01).
East

29-00299&309

POU

Field Exam 10/10/01



Looking ~~SE~~
NE Home and lawn is to the right of picture. Shows POU (csaxton 10/11/01).

29-00299&309
Field Exam 10/10/01

Historical Conveyance



Top picture looking South. Bottom picture looking West. Both of these pictures show what looks like evidence of historical ditches that would convey creek water to the home-site (csaxton 10/11/01)