

29-00443G POD

Field Exam 10/02/01



Looking South. Pond within the natural channel of the stream just on the other side of the fence. Black ABS pipe is the intake line. Pond and creek dry at time of field exam. POU Behind me in picture (csaxton 12/04/01).

29-00443G

POD

Field Exam 10/02/01



Looking SW. Pond within the natural stream channel. Andersons cleaning out the pond while creek is dry. Andersons indicate that pond has historically been in place.



Looking SE. Pond within the natural stream channel. Andersons cleaning out the pond while creek is dry. Andersons indicate that pond has historically been in place.

Split History According to Needs for 29-00443

