

**29-00443M**

**POD**

**Field Exam 9/24/01**




Looking NW. Pocatello creek on the other side of the RR tracks. Pump outflows to a 2 in underground PVC to sprinkler system. Pump is a Magnetek – Centurion. 1.5 hp; # 7-164300-24; AMPS SF 9.2/18.4. (CSAXTON 9-25-01)

**29-00443M**

**POU**

**Field Exam 9/25/01**



Looking S. Pocatello Creek behind me in picture. Home is to the left in picture.



Looking South. Irrigated Place of use around the home and the RR tracks consists mostly of lawn. Diesel

**29-00443M**

**POU**

**Field Exam 9/25/01**



Looking NE. POD home and lawn behind me in picture. POU shown here is on the West side of driveway. This property bought by the Griggs on July 29, 1994. In phone conversation with Ethel Griggs she said that the previous owner didn't irrigate. Not irrigated this year. NAPP photography indicates it could have been irrigated in 1987, but not recommending it as irrigated POU based on conversation with Mrs. Griggs.

**Historical Ditch**

**Taken 10/3/01**



Historical Point of diversion that diverted water to the ditch that carried water to the north side of the North Fork of Pocatello Creek.

## Historical Ditch

Taken 10/3/01



Looking East. Signs of the old historical Ditch that carried water to the north side of Pocatello creek to flood irrigate down to as far as Angelo Trayis' place.

## Historical Ditch

Taken 10/3/01



Looking West



Looking East