

Photos from 7/26/2001 Fieldwork, Russell Hayden, Ben Hayden, Mid-Crystal Farms AJ Claims.

Photos taken by B. Contor. See attached notes and layouts for locations and directions.

Photo #3. Well at upper Clifton Creek location.



p3 Bac

Photos from 7/26/2001 Fieldwork, Russell Hayden, Ben Hayden, Mid-Crystal Farms AJ Claims.

Photos taken by B. Contor. See attached notes and layouts for locations and directions.

Photo #4, Pond. Taken from hill NW of pond. *looking SE*




Photo #5, POU for spring/Clifton Creek. Taken from near location of spring looking west.



p4 Bac

Photos from 7/26/2001 Fieldwork, Russell Hayden, Ben Hayden, Mid-Crystal Farms AJ Claims.

Photos taken by B. Contor. See attached notes and layouts for locations and directions.

Photo #6, grove of trees in which spring POD is located. Too dark in trees for photo.



Photos from 7/26/2001 Fieldwork, Russell Hayden, Ben Hayden, Mid-Crystal Farms AJ Claims.

Photos taken by B. Contor. See attached notes and layouts for locations and directions.

Photo #10 (see item #14 in notes), last remnants of ditch on upper end of claimed POU.



p 7 BAC

MEMORANDUM


To: Harold Jones
Fr: Bryce Contor
Date: 7/27/2001

Re: Pond, possibly no WR?

This pond was pointed out to me by a concerned downstream user who believes there is no associated WR. It is located at approximately 8S 35E 35, NWSW.

I told the user that if he wanted to take action the appropriate thing to do is write to you. He was unsure whether he wanted to do that.

The photo was taken looking south off the Mink Creek/Arbon highway about one mile SW of the summit.



p10 Bac

Photos from 7/26/2001 Fieldwork, Russell Hayden, Ben Hayden, Mid-Crystal Farms AJ Claims.

Photos taken by B. Contor. See attached notes and layouts for locations and directions.

Photo #8, pump site for Clifton Creek, below house. Photo looking south. Clifton Creek/Rattlesnake Creek confluence south of this location.



Photo #9, showing Cipolletti weir cutout in pump basin. See notes from licensing exam 29-7948.



p11 Bue

Photos from 7/26/2001 Fieldwork, Russell Hayden, Ben Hayden, Mid-Crystal Farms AJ Claims.

Photos taken by B. Contor. See attached notes and layouts for locations and directions.

Photo #1, Lower POD on creek. Known as "Meddows Pump." Uses portable pump, not installed today.



Photo #2, typical installation of portable pump. This site not GPSd as not typically operated here, location not claimed, will not be recommended.



p1 Bac